





序号	报告编号	发布日期	结论	影像资料
13	GX-B1418/23-2-25005	2025. 8. 4	综合判定：合格。	
14	GX-B1418/23-2-25006	2025. 8. 4	综合判定：合格。	
15	GX-B1418/23-2-25007	2025. 8. 4	综合判定：合格。	

16	GX-B1418/23-2-25008	2025. 8. 4	综合判定：合格。	
17	GX-B1418/23-2-25009	2025. 8. 4	综合判定：合格。	
18	GX-B1418/23-2-25010	2025. 8. 4	综合判定：合格。	

19	GX-B1418/23-2-25011	2025. 8. 4	综合判定：合格		 2025/07/19	
20	GX-B1418/23-2-25012	2025. 8. 4	综合判定：合格		 2025/07/19	
21	GX-B1418/23-2-25013	2025. 8. 4	综合判定：合格		 2025/07/19	

22	GX-B1418/23-2-25014	2025. 8. 4	综合判定：合格			
23	GX-B1418/23-2-25015	2025. 8. 4	综合判定：合格			
24	GX-B1418/23-2-25016	2025. 8. 4	综合判定：合格			

25	GX-B1418/23-2-25017	2025. 8. 4	综合判定：合格		
26	GX-B1310/21-2-25185	2025. 8. 4	综合判定：合格		
27	GX-B1539/22-2-25026	2025/8/3	除未配备司机室, 无辅助制动系统外, 所检项目合格。		

28	GX-B1539/22-2-25027	2025/8/3	除未配备司机室, 无辅助制动系统外, 所检项目合格。		
29	GX-B1310/21-2-25158	2025/8/11	符合标准要求。		
30	GX-B1310/21-2-25159	2025/8/11	符合标准要求。		


31	GX-B1310/21-2-25160	2025/8/11	符合标准要求。			
32	GX-B1427/21-2-25160	2025/8/11	符合标准要求。			
33	GX-B1310/21-2-25161	2025/8/11	符合标准要求。			

34	GX-B1310/21-2-25162	2025/8/11	符合标准要求。	 2025/07/05
35	GX-B1310/21-2-25163	2025/8/11	符合标准要求。	 2025/07/05
36	GX-B1427/21-2-25163	2025/8/11	符合标准要求。	 2025/07/05

37	GX-B1310/21-2-25164	2025/8/11	符合标准要求。	
38	GX-B1310/21-2-25165	2025/8/11	符合标准要求。	
39	GX-B1310/21-2-25166	2025/8/11	符合标准要求。	

40	GX-B1427/21-2-25166	2025/8/11	符合标准要求。		
41	GX-B1310/21-2-25167	2025/8/11	符合标准要求。		
42	GX-B1310/21-2-25168	2025/8/11	符合标准要求。		

43	GX-B1310/21-2-25169	2025/8/11	符合标准要求。	
44	GX-B1427/21-2-25169	2025/8/11	符合标准要求。	
45	GX-B1310/21-2-25170	2025/8/11	符合标准要求。	


46	GX-B1310/21-2-25171	2025/8/11	符合标准要求。	
47	GX-B1310/21-2-25172	2025/8/11	符合标准要求。	
48	GX-B1427/21-2-25172	2025/8/11	符合标准要求。	

49	GX-B1310/21-2-25173	2025/8/11	符合标准要求。	
50	GX-B1310/21-2-25174	2025/8/11	符合标准要求。	
51	GX-B1310/21-2-25175	2025/8/11	符合标准要求。	

52	GX-B1427/21-2-25175	2025/8/11	符合标准要求。	
53	GX-B1428/21-2-25176	2025/8/11	无缺陷迹痕显示。	
54	GX-B1428/21-2-25177	2025/8/11	无缺陷迹痕显示。	



55	GX-B1428/21-2-25178	2025/8/11	无缺陷迹痕显示。			
56	GX-B1428/21-2-25179	2025/8/11	无缺陷迹痕显示。			
57	GX-B1428/21-2-25180	2025/8/11	无缺陷迹痕显示。			

58	GX-B1428/21-2-25181	2025/8/11	无缺陷迹痕显示。	
59	GX-B1428/21-2-25182	2025/8/11	无缺陷迹痕显示。	
60	GX-B1428/21-2-25183	2025/8/11	无缺陷迹痕显示。	


61	GX-B1428/21-2-25184	2025/8/11	无缺陷迹痕显示。		
62	GX-B1539/22-2-25028	2025/8/11	除无辅助制动系统，其余所检项目合格。		
63	GX-B1539/22-2-25029	2025/8/11	除无辅助制动系统，其余所检项目合格。		


64	GX-B1539/22-2-25030	2025/8/11	除无辅助制动系统，其余所检项目合格。	
65	GX-B1539/22-2-25031	2025/8/11	除无辅助制动系统，其余所检项目合格。	
66	GX-B1539/22-2-25032	2025/8/11	除无辅助制动系统、坐姿司机室基本出入口高度小于1300mm，其余所检项目合格。	

67	GX-B1539/22-2-25033	2025/8/11	除无辅助制动系统、坐姿司机室基本出入口高度小于1300mm，其余所检项目合格。		 2025/04/21
68	GX-B1302/25-2-25002	2025. 8. 12	综合判定：合格。		 2025/7/10
69	GX-B1359/21-2-25023~25024	2025. 8. 12	本次共检矿用隔爆型照明信号综合保护装置2台,2台所检项目合格。		 2025/7/14

70	GX-B1352/21-2-25148~25150	2025. 8. 12	本次共检矿用防爆低压交流真空馈电开关3台, 3台所检项目合格。	
71	GX-B1310/21-2-25269	2025. 8. 6	符合标准要求。	
72	GX-B1427/21-2-25269	2025. 8. 6	符合标准要求。	


73	GX-B1310/21-2-25270	2025. 8. 6	符合标准要求。	
74	GX-B1427/21-2-25270	2025. 8. 6	符合标准要求。	
75	GX-B1310/21-2-25271	2025. 8. 6	符合标准要求。	

76	GX-B1427/21-2-25271	2025. 8. 6	符合标准要求。	
77	GX-B1310/21-2-25272	2025. 8. 6	符合标准要求。	
78	GX-B1427/21-2-25272	2025. 8. 6	符合标准要求。	



79	GX-B1310/21-2-25273	2025. 8. 6	符合标准要求。	 A worker wearing a red helmet and safety harness is standing on a blue metal platform or walkway. The background shows industrial structures. A timestamp '2025/08/01' is visible in the bottom right corner of the photo.
80	GX-B1427/21-2-25273	2025. 8. 6	符合标准要求。	 A worker wearing a red helmet and a grey uniform is standing on a blue metal platform. The background shows industrial structures. A timestamp '2025/08/01' is visible in the bottom right corner of the photo.
81	GX-B1310/21-2-25274	2025. 8. 6	符合标准要求。	 A worker wearing a red helmet and a grey uniform is crouching on a blue metal platform. The background shows industrial structures. A timestamp '2025/08/01' is visible in the bottom right corner of the photo.


82	GX-B1427/21-2-25274	2025. 8. 6	符合标准要求。	 A photograph showing two workers in safety gear (hard hats and work clothes) standing in front of industrial equipment. A date stamp '2025/08/01' is visible in the bottom right corner of the image.
83	GX-B1310/21-2-25275	2025. 8. 6	符合标准要求。	 A photograph showing a worker in safety gear operating a large industrial machine. A date stamp '2025/08/01' is visible in the bottom right corner of the image.
84	GX-B1427/21-2-25275	2025. 8. 6	符合标准要求。	 A photograph showing two workers in safety gear (hard hats and work clothes) standing in front of industrial equipment. A date stamp '2025/08/01' is visible in the bottom right corner of the image.

85	GX-B1310/21-2-25276	2025. 8. 6	符合标准要求。	
86	GX-B1427/21-2-25276	2025. 8. 6	符合标准要求。	
87	GX-B1310/21-2-25277	2025. 8. 6	符合标准要求。	

88	GX-B1427/21-2-25277	2025. 8. 6	符合标准要求。	 2025/08/01
89	GX-B1310/21-2-25278	2025. 8. 6	符合标准要求。	 2025/08/01
90	GX-B1427/21-2-25278	2025. 8. 6	符合标准要求。	 2025/08/01

91	GX-B1310/21-2-25279	2025. 8. 6	符合标准要求。	
92	GX-B1427/21-2-25279	2025. 8. 6	符合标准要求。	
93	GX-B1310/21-2-25280	2025. 8. 6	符合标准要求。	

94	GX-B1427/21-2-25280	2025. 8. 6	符合标准要求。		
95	GX-B1352/21-2-25151~25153	2025. 8. 12	本次共检矿用防爆低压交流真空馈电开关3台, 3台所检项目合格。		
96	GX-B1359/21-2-25025	2025. 8. 12	所检项目合格。		

97	GX-B1612/23-2-25127	2025. 8. 12	所检项目合格。	
98	GX-B1310/21-2-25194	2025. 8. 11	符合标准要求。	
99	GX-B1310/21-2-25195	2025. 8. 11	符合标准要求。	