


序号	报告编号	发布日期	结论	影像资料
1	GX-B1328/25-3-25260	2025. 11. 3	所检项目合格。	
2	GX-B1328/25-3-25261	2025. 11. 3	所检项目合格。	

3	GX-B1310/21-3-25237	2025. 11. 7	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 检验项目：海则滩煤矿探伤 经度：108.906883 纬度：37.611156 地址：榆林市靖边县高杨路在中煤特能海则滩项目部 时间：2025-10-23
4	GX-B1428/21-3-25068	2025. 11. 7	无缺陷迹痕显示。	 检验项目：海则滩煤矿探伤 经度：108.907007 纬度：37.611161 地址：榆林市靖边县高杨路在中煤特能海则滩项目部附近 时间：2025-10-23

5	GX-B1310/21-3-25238	2025. 11. 7	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 检验项目: 海阳港煤矿探伤 经度: 108.906882 纬度: 37.811098 地址: 榆林市靖边县杨路在中煤特能海阳项目部附近 时间: 2025-10-23
6	GX-B1428/21-3-25069	2025. 11. 7	无缺陷迹痕显示。	 检验项目: 海阳港煤矿探伤 经度: 108.906882 纬度: 37.811098 地址: 榆林市靖边县杨路在中煤特能海阳项目部附近 时间: 2025-10-23

7	GX-B1310/21-3- 25239	2025年11月7日	符合标准要求。	
8	GX-B1310/21-3- 25240	2025年11月7日	符合标准要求。	

9	GX-B1310/21-3- 25241	2025年11月7日	符合标准要求。	
10	GX-B1310/21-3- 25242	2025年11月7日	符合标准要求。	

11	GX-B1310/21-3- 25243	2025年11月7日	符合标准要求。	 A worker wearing a green raincoat, red helmet, and white gloves is inspecting a large, horizontal metal pipe. The pipe has a circular opening with a flange. The worker is holding a device, possibly a detector or a camera. The ground is muddy and there is some debris. A yellow timestamp "2025.10.31" is visible in the bottom right corner of the image.
12	GX-B1310/21-3- 25244	2025年11月7日	符合标准要求。	 Three workers wearing green raincoats, red helmets, and white gloves are inspecting a large, vertical metal pipe. The worker in the foreground is holding a device, possibly a detector or a camera. The other two workers are standing behind him, also looking at the pipe. The ground is muddy and there is some debris. A yellow timestamp "2025.10.31" is visible in the bottom right corner of the image.

13	GX-B1310/21-3- 25245	2025年11月7日	符合标准要求。	
14	GX-B1312/20-3-25971~25972	2025. 11. 6	所检项目合格。	