


序号	报告编号	发布日期	结论	影像资料
6	GX-B1328/20-2-25136	2025.11.10	本次共检绝缘手套4只，4只绝缘手套合格。	
7	GX-B1328/20-2-25137	2025.11.10	本次共检绝缘靴4只，4只绝缘靴合格。	

8	GX-B1328/20-2-25138	2025.11.10	本次共检验电器2支， 2支验电器合格。		 2025/11/07	
9	GX-B1310/21-2-25410	2025/11/7	符合标准要求。		 2025.10.22	

10	GX-B1310/21-2-25411	2025/11/7	符合标准要求。		 2025.10.22	
11	GX-B1310/21-2-25412	2025/11/7	符合标准要求。		 2025.10.23	

12	GX-B1310/21-2-25413	2025/11/7	符合标准要求。	 2025.10.23
13	GX-B1310/21-2-25414	2025/11/7	符合标准要求。	 2025.10.24

14	GX-B1310/21-2-25407	2025.11.12	符合标准要求。	 2025/10/23
15	GX-B1428/21-2-25407	2025.11.12	无缺陷迹痕显示。	 2025/10/23

16	GX-B1310/21-2-25408	2025.11.12	符合标准要求。	 2023/10/23
17	GX-B1428/21-2-25408	2025.11.12	无缺陷迹痕显示。	 2023/10/23

18	GX-B1310/21-2-25409	2025.11.12	符合标准要求。	 2025/10/23
19	GX-B1310/21-2-25415	2025.11.12	符合标准要求。	 2025/10/29

20	GX-B1310/21-2-25416	2025.11.12	符合标准要求。	 2025/10/29
21	GX-B1310/21-2-25417	2025.11.12	符合标准要求。	 2025/10/30

22	GX-B1428/21-2-25417	2025.11.12	无缺陷迹痕显示。	
23	GX-B1310/21-2-25418	2025.11.12	符合标准要求。	

24	GX-B1310/21-2-25419	2025.11.12	符合标准要求。	
25	GX-B1598/24-2-25238	2025.11.12	实测钢丝绳有效截面积损失百分比最大为0.38%，小于5%为正常。 。	

26	GX-B1598/24-2-25239	2025.11.12	实测钢丝绳有效截面积损失百分比最大为 0.46%，小于5%为正常。 。	 2025/10/30
27	GX-B1598/24-2-25240	2025.11.12	实测钢丝绳有效截面积损失百分比最大为 0.51%，小于5%为正常。 。	 2025/10/30

28	GX-B1598/24-2-25241	2025.11.12	实测钢丝绳有效截面积损失百分比最大为 0.48%，小于5%为正常。 。	 2025/10/30
29	GX-B1598/24-2-25242	2025.11.12	实测钢丝绳有效截面积损失百分比最大为 0.39%，小于5%为正常。 。	 2025/10/30

30	GX-B1598/24-2-25243	2025.11.12	实测钢丝绳有效截面积损失百分比最大为2.89%，小于5%为正常。 。	
31	GX-B1301/25-2-25025	2025.11.17	综合判定：合格。	

32	GX-B1301/25-2-25024	2025/11/17	综合判定：合格。	 2025/10/14
33	GX-B1304/21-2-25018	2025/11/17	综合判定：合格。	 2025/09/29

34	GX-B1304/21-2-25020	2025/11/17	综合判定：合格。	 2025/10/29
----	---------------------	------------	----------	---