




序号	报告编号	发布日期	结论	影像资料	
35	GX-B1328/25-2-25139	2025. 11. 20	本次共检验电器1只， 1支验电器合格。		
36	GX-B1323/21-2-25078~25094	2025. 11. 20	所检项目合格。		

37	GX-B1323/21-2-25095~25107	2025. 11. 20	所检项目合格。		
38	GX-B1536/20-2-25005	2025. 11. 20	综合判定：合格。		

39	GX-B1536/20-2-25006	2025. 11. 20	综合判定：合格。		
40	GX-B1323/21-2-25060~25074	2025. 11. 21	所检项目合格		

41	GX-B1301/25-2-25026	2025/11/21	综合判定:合格。	
42	GX-B1301/25-2-25027	2025/11/21	综合判定:合格。	

43	GX-B1310/21-2-25441	2025/11/21	符合标准要求。	
44	GX-B1310/21-2-25442	2025/11/21	符合标准要求。	

45	GX-B1598/24-2-25273	2025/11/21	实测钢丝绳有效截面积损失百分比最大为4.56%，小于5%为正常。 。		
46	GX-B1598/24-2-25274	2025/11/21	实测钢丝绳有效截面积损失百分比最大为2.45%，小于5%为正常。 。		

47	GX-B1598/24-2-25275	2025/11/21	实测钢丝绳有效截面积损失百分比最大为4.25%，小于5%为正常。 。	 2025/11/5	
48	GX-B1598/24-2-25276	2025/11/21	实测钢丝绳有效截面积损失百分比最大为2.94%，小于5%为正常。 。	 2025/11/5	





49	GX-B1598/24-2-25277	2025/11/21	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常。 。		
50	GX-B1310/21-2-25435	2025/11/21	符合标准要求。		



51	GX-B1310/21-2-25436	2025/11/21	符合标准要求。		
52	GX-B1310/21-2-25437	2025/11/21	符合标准要求。		

53	GX-B1310/21-2-25438	2025/11/21	符合标准要求。	
54	GX-B1310/21-2-25439	2025/11/21	符合标准要求。	

55	GX-B1310/21-2-25440	2025/11/21	符合标准要求。		
56	GX-B1310/21-2-25434	2025/11/23	符合标准要求。		

57	GX-B1310/21-2-25433	2025/11/23	符合标准要求。	
58	GX-B1310/21-2-25432	2025/11/23	符合标准要求。	


59	GX-B1310/21-2-25431	2025/11/23	符合标准要求。	
60	GX-B1305/21-2-25003	2025. 11. 24	钢丝绳与提升容器的连接，未采用桃形环连接装置或楔形连接装置。 综合判定：合格。	



61	GX-B1302/25-2-25003	2025. 11. 24	综合判定：合格。	
62	GX-B1302/25-2-25004	2025. 11. 24	综合判定：合格。	

63	GX-B1321/20-2-25431~25432	2025. 11. 24	本次共检验电力电缆2条, 2条所检项目合格。 。		
64	GX-B1321/20-2-25433~25439	2025. 11. 24	本次共检验电力电缆7条, 7条所检项目合格。 。		




65	GX-B1321/20-2-25440~25444	2025. 11. 24	本次共检验电力电缆5条, 5条所检项目合格。 。	
66	GX-B1598/24-2-25264	2025/11/20	实测钢丝绳有效截面积损失百分比最大为2.49%, 小于5%为正常。	

67	GX-B1598/24-2-25265	2025/11/20	实测钢丝绳有效截面积损失百分比最大为2.61%，小于5%为正常。		
68	GX-B1598/24-2-25266	2025/11/20	实测钢丝绳有效截面积损失百分比最大为1.68%，小于5%为正常。		

69	GX-B1598/24-2-25267	2025/11/20	实测钢丝绳有效截面积损失百分比最大为1.55%，小于5%为正常。		
70	GX-B1598/24-2-25268	2025/11/20	实测钢丝绳有效截面积损失百分比最大为1.45%，小于5%为正常。		

71	GX-B1598/24-2-25269	2025/11/20	实测钢丝绳有效截面积损失百分比最大为1.44%，小于5%为正常。	
72	GX-B1598/24-2-25270	2025/11/20	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常。	

73	GX-B1598/24-2-25271	2025/11/20	实测钢丝绳有效截面积损失百分比最大为1.54%，小于5%为正常。 。		
74	GX-B1598/24-2-25272	2025/11/20	实测钢丝绳有效截面积损失百分比最大为1.68%，小于5%为正常。 。		

75	GX-B1312/20-2-25276~25282	2025/11/25	本次共检煤矿用防爆干式变压器7台，7台所检项目合格。	
76	GX-B1312/20-2-25283~25286	2025/11/25	本次共检煤矿用防爆干式变压器4台，4台所检项目合格。	

77	GX-B1310/21-2-25420	2025/11/23	符合标准要求。	
78	GX-B1310/21-2-25421	2025/11/23	符合标准要求。	



79	GX-B1310/21-2-25422	2025/11/23	符合标准要求。	
80	GX-B1310/21-2-25423	2025/11/23	符合标准要求。	

81	GX-B1310/21-2-25424	2025/11/23	符合标准要求。	
82	GX-B1310/21-2-25425	2025/11/23	符合标准要求。	

83	GX-B1310/21-2-25426	2025/11/23	符合标准要求。	
84	GX-B1310/21-2-25427	2025/11/23	符合标准要求。	

85	GX-B1323/21-2-25075~25077	2025/11/25	所检项目合格。	
86	GX-B1574/20-2-25058	2025/11/25	所检项目合格。	

87	GX-B1574/20-2-25059	2025/11/25	所检项目合格。	
88	GX-B1574/20-2-25060	2025/11/25	所检项目合格。	

89	GX-B1574/20-2-25061	2025/11/25	所检项目合格。	
90	GX-B1574/20-2-25062	2025/11/25	除未取得矿用产品安全标志外，其余所检项目合格。	

91	GX-B1574/20-2-25063	2025/11/25	除未取得矿用产品安全标志外，其余所检项目合格。	
92	GX-B1312/20-2-25288~25290	2025. 11. 26	本次共检煤矿用防爆干式变压器3台，3台所检项目合格。	





93	GX-B1312/20-2-25291~25292	2025. 11. 26	本次共检煤矿用防爆干式变压器2台，2台所检项目合格。	
94	GX-B1312/20-2-25293	2025. 11. 26	所检项目合格。	



95	GX-B1312/20-2-25294~25296	2025. 11. 26	本次共检煤矿用防爆干式变压器3台，3台所检项目合格。	 2025/11/12	
96	GX-B1314/21-2-25008~25010	2025. 11. 26	本次共检干式电抗器3台，3台所检项目合格。	 2025/11/11	

97	GX-B1495/25-2-25934~25941	2025. 11. 27	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
98	GX-B1495/25-2-25942~25946	2025. 11. 27	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	



99	GX-B1495/25-2-25947	2025. 11. 27	所检项目合格。	
100	GX-B1495/25-2-25948~25954	2025. 11. 27	本次共检防爆型高压 配电装置7台，7台所 检项目合格。	



101	GX-B1495/25-2-25955~25956	2025. 11. 27	本次共检防爆型高压 配电装置2台，2台所 检项目合格。	
102	GX-B1495/25-2-25957	2025. 11. 27	所检项目合格。	



103	GX-B1495/25-2-25958~25968	2025. 11. 21	本次共检防爆型高压 配电装置11台，11台所 检项目合格。	 <p>2025/11/21</p>
104	GX-B1304/21-2-25021	2025/11/26	综合判定：合格。	 <p>2025/11/26</p>



105	GX-B1598/24-2-25250	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.56%，小于5%为正常。	
106	GX-B1598/24-2-25251	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.72%，小于5%为正常。	






107	GX-B1598/24-2-25252	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.80%，小于5%为正常。	
108	GX-B1598/24-2-25253	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.77%，小于5%为正常。	

109	GX-B1598/24-2-25254	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.92%，小于5%为正常。		
110	GX-B1598/24-2-25255	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.85%，小于5%为正常。		

111	GX-B1598/24-2-25256	2025/11/23	实测钢丝绳有效截面积损失百分比最大为0.49%，小于5%为正常。			
112	GX-B1598/24-2-25257	2025/11/23	实测钢丝绳有效截面积损失百分比最大为0.40%，小于5%为正常。			

113	GX-B1598/24-2-25258	2025/11/23	实测钢丝绳有效截面积损失百分比最大为2.18%，小于5%为正常。	 A photograph showing two workers in safety gear (hard hats, high-visibility vests) inspecting a large industrial machine. One worker is standing and holding a green component, while the other is kneeling and working on the machine. The machine has a large red and green section. The date 2025/11/14 is visible in the bottom right corner of the image.
114	GX-B1598/24-2-25259	2025/11/23	实测钢丝绳有效截面积损失百分比最大为2.25%，小于5%为正常。	 A photograph showing a worker in safety gear (hard hat, high-visibility vest) inspecting a large industrial machine. The worker is kneeling and working on the machine. The machine has a large red and green section. The date 2025/11/14 is visible in the bottom right corner of the image.

115	GX-B1598/24-2-25260	2025/11/23	实测钢丝绳有效截面积损失百分比最大为2.07%，小于5%为正常。	
116	GX-B1598/24-2-25261	2025/11/23	实测钢丝绳有效截面积损失百分比最大为2.47%，小于5%为正常。	

117	GX-B1598/24-2-25262	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.84%，小于5%为正常。		
118	GX-B1598/24-2-25263	2025/11/23	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常。		

119	GX-B1304/21-2-25022	2025/11/28	合格。	 A photograph showing three workers in a factory or industrial setting. Two workers are wearing blue uniforms and one is wearing a red uniform. They are standing near some equipment, and a toolbox is open on the floor. The date 2025/11/28 is visible in the bottom right corner of the image.
120	GX-B1304/21-2-25023	2025/11/28	合格。	 A photograph showing two workers in a factory or industrial setting. One worker is wearing a red uniform and the other is wearing a dark uniform. They are standing near some equipment, and a toolbox is open on the floor. The date 2025/11/18 is visible in the bottom right corner of the image.



121	GX-B1304/21-2-25024	2025/11/28	合格。	 A photograph showing two workers in a factory environment. They are wearing red hard hats and camouflage jackets. They are standing next to a large, blue industrial machine. A toolbox is on the floor in front of them. The date 2025/11/20 is visible in the bottom right corner of the image.
122	GX-B1310/21-2-25443	2025/11/28	符合标准要求。	 A photograph showing two workers in a factory environment. They are wearing red hard hats and camouflage jackets. They are standing next to a large, blue industrial machine. The date 2025/11/18 is visible in the bottom right corner of the image.

123	GX-B1310/21-2-25444	2025/11/28	符合标准要求。			
124	GX-B1310/21-2-25445	2025/11/28	符合标准要求。			

125	GX-B1310/21-2-25446	2025/11/28	符合标准要求。	 A worker wearing a red hard hat and a camouflage jacket is shown in profile, working on a dark, possibly metallic, structure. The image is taken at night or in a dark environment. A timestamp '2025/11/19' is visible in the bottom right corner of the photo.
126	GX-B1310/21-2-25447	2025/11/28	符合标准要求。	 A worker wearing a blue and yellow safety suit and a helmet is standing on a platform, working on a large, rusted metal structure. The structure appears to be part of a large industrial machine or vessel. A timestamp '2025/11/19' is visible in the bottom right corner of the photo.

127	GX-B1310/21-2-25448	2025/11/28	符合标准要求。	 A photograph showing two workers in safety gear (hard hats, high-visibility vests) standing next to a large red industrial machine, possibly a pump or motor. The date 2025/11/20 is visible in the bottom right corner of the image.
128	GX-B1310/21-2-25449	2025/11/28	符合标准要求。	 A photograph showing two workers in safety gear (hard hats, high-visibility vests) working on a large industrial machine. One worker is in the foreground, and another is in the background. The date 2025/11/20 is visible in the bottom right corner of the image.

129	GX-B1310/21-2-25450	2025/11/28	符合标准要求。		
130	GX-B1310/21-2-25451	2025/11/28	符合标准要求。		

131	GX-B1310/21-2-25452	2025/11/28	符合标准要求。	 <p>2025/11/20</p>
132	GX-B1310/21-2-25453	2025/11/28	符合标准要求。	 <p>2025/11/20</p>

133	GX-B1310/21-2-25454	2025/11/28	符合标准要求。		
134	GX-B1310/21-2-25455	2025/11/28	符合标准要求。		



135	GX-B1310/21-2-25456	2025/11/28	符合标准要求。	
136	GX-B1310/21-2-25457	2025/11/28	符合标准要求。	

137	GX-B1310/21-2-25458	2025/11/28	符合标准要求。		
138	GX-B1310/21-2-25459	2025/11/28	符合标准要求。		

139	GX-B1310/21-2-25460	2025/11/28	符合标准要求。		
140	GX-B1428/21-2-25460	2025/11/28	无缺陷迹痕显示。		

141	GX-B1310/21-2-25461	2025/11/28	符合标准要求。	
142	GX-B1428/21-2-25461	2025/11/28	无缺陷迹痕显示。	

143	GX-B1428/21-2-25462	2025/11/28	无缺陷迹痕显示。		 <p>2025/11/21</p>	
144	GX-B1428/21-2-25463	2025/11/28	无缺陷迹痕显示。		 <p>2025/11/21</p>	