

序号	报告编号	发布日期	结论	影像资料
118	GX-B1329/21-4-25206~25212	2025. 12. 25	本次共检氧化锌避雷器7组，7组氧化锌避雷器所检项目合格。	
119	GX-B1451/20-4-25497~25502	2025. 12. 25	本次共检高压开关柜6面，6面高压开关柜所检项目合格。	

120	GX-B1451/20-4-25492~25496	2025. 12. 25	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	
121	GX-B1310/21-4-25261	2025. 12. 24	符合标准要求	

122	GX-B1310/21-4-25262	2025. 12. 24	符合标准要求	 <p>地址：烟台南羊平区西直格庄 时间：2025-12-9</p>
123	GX-B1310/21-4-25263	2025. 12. 24	符合标准要求	 <p>地址：烟台南羊平区西直格庄 时间：2025-12-9</p>

124	GX-B1310/21-4-25264	2025. 12. 24	符合标准要求	 <p>地址：烟台牟平区西孟格庄 时间：2025-12-9</p>
125	GX-B1428/21-4-25265	2025. 12. 24	无缺陷迹痕显示	 <p>时间：2025-12-10</p>

126	GX-B1427/21-4-25272	2025. 12. 22	符合标准要求	 <p>地址: 鹤壁市淇县高村镇在鹤壁万丰矿山 机械制造有限公司附近 工程名称: 鹤壁 时间: 2025-12-17</p>
127	GX-B1427/21-4-25273	2025. 12. 22	符合标准要求	 <p>地址: 鹤壁市淇县高村镇在鹤壁万丰矿山 机械制造有限公司附近 工程名称: 鹤壁 时间: 2025-12-17</p>

128	GX-B1310/21-4-25274	2025. 12. 29	符合标准要求	 <p>地址: 鹤壁市淇县高村镇在鹤壁万丰矿山 机械制造有限公司附近 工程名称: 鹤壁 时间: 2025-12-17</p>
129	GX-B1310/21-4-25275	2025. 12. 29	符合标准要求	 <p>地址: 鹤壁市淇县高村镇在鹤壁万丰矿山 机械制造有限公司附近 工程名称: 鹤壁 时间: 2025-12-17</p>

130	GX-B1309/21-4-25011	2025. 12. 29	所检项目合格。	
131	GX-B1304/21-4-25004	2025. 12. 29	综合判定：合格。	

132	GX-B1304/21-4-25003	2025. 12. 29	综合判定：合格。	
133	GX-B1500/21-4-25038	2025. 12. 31	综合判定：合格。	

134	GX-B1500/21-4-25039	2025. 12. 31	综合判定：合格。	
135	GX-B1500/21-4-25040	2025. 12. 31	综合判定：合格。	

136	GX-B1309/21-4-25012	2025. 12. 31	所检项目合格。			
137	GX-B1328/25-4-25238	2025. 12. 31	本次共检绝缘胶垫 1个，1个绝缘胶垫合格。			

138	GX-B1598/24-4-25044	2025. 12. 31	实测钢丝绳有效截面积损失百分比最大为1.66%，小于5%为正常。 。	
139	GX-B1598/24-4-25045	2025. 12. 31	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常。 。	

140	GX-B1598/24-4-25046	2025. 12. 31	实测钢丝绳有效截面积损失百分比最大为1.50%，小于5%为正常。 。	
141	GX-B1598/24-4-25047	2025. 12. 31	实测钢丝绳有效截面积损失百分比最大为1.54%，小于5%为正常。 。	