


序号	报告编号	发布日期	结论	影像资料
33	GX-B1382/26-1-26008	2026. 3. 6	所检项目合格	 <p>2026/2/23</p>
34	GX-B1382/26-1-26009	2026. 3. 6	所检项目合格	

35	GX-B1382/26-1-26010	2026. 3. 6	所检项目合格	
36	GX-B1382/26-1-26011	2026. 3. 6	所检项目合格	

37	GX-B1382/26-1-26012	2026. 3. 6	所检项目合格	
38	GX-B1382/26-1-26013	2026. 3. 6	所检项目合格	

39	GX-B1598/24-1-26037	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.32%，小于5%为正常	 <p>2026/02/24</p>
40	GX-B1598/24-1-26038	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.17%，小于5%为正常	 <p>2026/02/24</p>

41	GX-B1598/24-1-26039	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.31%，小于5%为正常	
42	GX-B1598/24-1-26040	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.18%，小于5%为正常	

43	GX-B1598/24-1-26041	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.97%，小于5%为正常			
44	GX-B1598/24-1-26042	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.05%，小于5%为正常			

45	GX-B1598/24-1-26043	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.70%，小于5%为正常	 <p>2026/02/24</p>
46	GX-B1598/24-1-26044	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.99%，小于5%为正常	 <p>2026/02/24</p>

47	GX-B1598/24-1-26045	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.91%，小于5%为正常	 A photograph showing a worker in an orange safety vest and helmet inspecting a steel cable on a construction site. The worker is positioned on a wooden platform or scaffolding. The background shows a dark structure, possibly a building or tunnel, with some yellow railings. The date '2026/02/24' is visible in the bottom right corner of the image.
48	GX-B1598/24-1-26046	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.10%，小于5%为正常	 A photograph showing a worker in an orange safety vest and helmet inspecting a steel cable on a construction site. The worker is positioned on a wooden platform or scaffolding. The background shows a dark structure, possibly a building or tunnel, with some yellow railings. The date '2026/02/24' is visible in the bottom right corner of the image.

49	GX-B1598/24-1-26047	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.92%，小于5%为正常	
50	GX-B1598/24-1-26048	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.92%，小于5%为正常	

51	GX-B1598/24-1-26049	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.05%，小于5%为正常	
52	GX-B1598/24-1-26050	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.09%，小于5%为正常	

53	GX-B1598/24-1-26051	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.10%，小于5%为正常	 <p>2026/02/23</p>
54	GX-B1598/24-1-26052	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.11%，小于5%为正常	 <p>2026/02/23</p>

55	GX-B1598/24-1-26053	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常	 <p>2026/02/23</p>
56	GX-B1598/24-1-26054	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.97%，小于5%为正常	 <p>2026/02/25</p>

57	GX-B1598/24-1-26055	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.99%，小于5%为正常		 <p>2026/02/25</p>
58	GX-B1598/24-1-26056	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.97%，小于5%为正常		 <p>2026/02/25</p>

59	GX-B1598/24-1-26031	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.72%，小于5%为正常		
60	GX-B1598/24-1-26032	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.69%，小于5%为正常		

61	GX-B1598/24-1-26033	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.77%，小于5%为正常		 <p>2026.2.28</p>
62	GX-B1598/24-1-26034	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.71%，小于5%为正常		 <p>2026.2.28</p>

63	GX-B1598/24-1-26035	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.50%，小于5%为正常		 A worker in a red safety suit and helmet is working on a steel structure, possibly a crane or hoist. The worker is positioned on a platform or walkway, and the background shows industrial equipment and structural elements. The date 2026.2.28 is visible in the bottom right corner of the image.	
64	GX-B1598/24-1-26036	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.44%，小于5%为正常		 A worker in a red safety suit and helmet is holding a device, possibly a measuring instrument or a mobile phone, in an industrial setting. The worker is standing on a platform or walkway, and the background shows industrial equipment and structural elements. The date 2026.2.28 is visible in the bottom right corner of the image.	

65	GX-B1305/21-1-26004	2026. 3. 6	综合判定：合格。	
66	GX-B1598/24-1-26050	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.09%，小于5%为正常。 。	

67	GX-B1598/24-1-26051	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.10%，小于5%为正常。 。	
68	GX-B1598/24-1-26052	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.11%，小于5%为正常。 。	

69	GX-B1598/24-1-26053	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常。 。	 <p>2026/02/23</p>
70	GX-B1598/24-1-26054	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.93%，小于5%为正常。 。	 <p>2026/02/25</p>

71	GX-B1598/24-1-26055	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.99%，小于5%为正常。 。		 <p>2026/02/25</p>
72	GX-B1598/24-1-26056	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.96%，小于5%为正常。 。		 <p>2026/02/25</p>

73	GX-B1303/21-1-26009	2026/3/9	综合判定：合格。	
74	GX-B1451/20-1-26082~26089	2026. 3. 5	本次共检高压开关柜8台, 8台高压开关柜所检项目合格	

75	GX-B1451/20-1-26090~26107	2026. 3. 5	本次共检高压开关柜 18台, 18台高压开关柜 所检项目合格	
76	GX-B1451/20-1-26108~26109	2026. 3. 5	本次共检继电保护装置 2台, 2台继电保护装 置所检项目合格	

77	GX-B1313/26-1-26026~26029	2026/3/10	所检项目合格	
78	GX-B1380/26-1-26012	2026/3/11	所检项目合格	

79	GX-B1380/26-1-26013	2026/3/10	所检项目合格	
80	GX-B1380/26-1-26015	2026/3/11	所检项目合格	

81	GX-B1598/24-1-26063	2026/3/10	实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常。 。	
82	GX-B1598/24-1-26064	2026/3/10	实测钢丝绳有效截面积损失百分比最大为0.86%，小于5%为正常。 。	

83	GX-B1310/21-1-26078	2026/3/10	符合标准要求	 <p>2026/2/23</p>
84	GX-B1310/21-1-26079	2026/3/10	符合标准要求	 <p>2026/2/23</p>

85	GX-B1310/21-1-26080	2026/3/10	符合标准要求	 A worker wearing a white hard hat and a red safety suit with reflective stripes is standing in an industrial environment. The worker is holding a clipboard. A yellow timestamp '2026/2/23' is visible in the bottom right corner of the photo.
86	GX-B1310/21-1-26081	2026/3/10	符合标准要求	 A worker wearing a red hard hat and a brown safety suit is working on a large, blue industrial machine. The worker is using a tool on a component of the machine. A yellow timestamp '2026/2/27' is visible in the bottom right corner of the photo.

87	GX-B1310/21-1-26082	2026/3/10	符合标准要求	
88	GX-B1310/21-1-26083	2026/3/10	符合标准要求	

89	GX-B1304/26-1-26006	2026/3/11	综合判定：合格	
90	GX-B1598/24-1-26057	2026/3/10	实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常。 。	

91	GX-B1598/24-1-26058	2026/3/10	实测钢丝绳有效截面积损失百分比最大为2.03%，小于5%为正常。 。	
92	GX-B1598/24-1-26059	2026/3/10	实测钢丝绳有效截面积损失百分比最大为2.17%，小于5%为正常。 。	

93	GX-B1598/24-1-26060	2026/3/10	实测钢丝绳有效截面积损失百分比最大为1.85%，小于5%为正常。 。	 <p>2026/02/25</p>
94	GX-B1598/24-1-26061	2026/3/10	实测钢丝绳有效截面积损失百分比最大为2.34%，小于5%为正常。 。	 <p>2026/02/28</p>

95	GX-B1598/24-1-26062	2026/3/10	实测钢丝绳有效截面积损失百分比最大为2.40%，小于5%为正常。 。	
96	GX-B1310/21-1-26084	2026/3/10	符合标准要求	

97	GX-B1310/21-1-26085	2026/3/10	符合标准要求	
98	GX-B1310/21-1-26086	2026/3/10	符合标准要求	

99	GX-B1310/21-1-26087	2026/3/10	符合标准要求	
100	GX-B1310/21-1-26088	2026/3/10	符合标准要求	

101	GX-B1310/21-1-26089	2026/3/10	符合标准要求	
102	GX-B1310/21-1-26090	2026/3/10	符合标准要求	

103	GX-B1310/21-1-26091	2026/3/10	符合标准要求	
104	GX-B1310/21-1-26092	2026/3/10	符合标准要求	

105	GX-B1322/26-1-26117~26119	2026/3/11	所检项目合格	
106	GX-B1313/26-1-26034~26035	2026/3/11	所检项目合格	

107	GX-B1451/26-1-26110~26112	2026/3/11	所检项目合格	 A man in a dark jacket is standing next to a large white electrical cabinet. The cabinet has a yellow warning sign with a lightning bolt symbol. The date 2026/03/11 is visible in the bottom right corner of the photo.
108	GX-B1322/26-1-26071~26074	2026/3/11	所检项目合格	 A person wearing a white shirt and a red hard hat is kneeling on a red floor, working on a piece of equipment. The date 2026/02/13 is visible in the bottom right corner of the photo.

109	GX-B1329/26-1-26040~26044 GX-B1329/26-1-26045~26065	2026/3/11	所检项目合格	
110	GX-B1313/21-1-26030~26032	2026/3/12	压器3台, 3台电力变压器	

111	GX-B1313/21-1-26033	2026/3/12	所检项目合格。	
112	GX-B1380/26-1-26014	2026/3/12	所检项目合格。	

113	GX-B1382/26-1-26014	2026/3/12	综合判定:合格。	
114	GX-B1451/20-1-26071~26076	2026. 3. 12	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	

115	GX-B1612/23-1-26001	2026/3/13	所检项目合格。	
116	GX-B1303/21-1-26010	2026. 3. 12	综合判定：合格。	

117	GX-B1350/21-1-26007	2026/3/13	本次共检接地装置 2处, 2处所检项目合格 。	
118	GX-B1350/21-1-26008	2026/3/13	本次共检接地装置 2处, 2处所检项目合格 。	

119	GX-B1350/21-1-26009	2026/3/13	本次共检接地装置 2处, 2处所检项目合格 。	
120	GX-B1322/21-1-26075~26079	2026/3/13	本次共检验电力电缆5 条, 5条所检项目合格 。	

121	GX-B1322/21-1-26080~26084	2026/3/13	本次共检验电力电缆5条，5条所检项目合格。 。	
122	GX-B1322/21-1-26129~26133	2026/3/13	本次共检验电力电缆5条，5条所检项目合格。 。	