


序号	报告编号	发布日期	结论	影像资料
17	GX-B1304/26-5-26006	2026/3/6	综合判定:合格。	
18	GX-B1310/21-5-26069	2026. 3. 6	符合标准要求。	

19	GX-B1310/21-5-26070	2026. 3. 6	符合标准要求。	
20	GX-B1310/21-5-26071	2026. 3. 6	符合标准要求。	

21	GX-B1427/21-5-26011	2026. 3. 6	符合标准要求。	
22	GX-B1598/24-5-26030	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.70%，小于5%为正常。	

23	GX-B1598/24-5-26031	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.68%，小于5%为正常。	 A photograph showing two workers in safety gear (hard hats, safety harnesses, and work clothes) standing on a metal platform or scaffolding. They are inspecting a thick steel cable. The background shows industrial structures. A yellow timestamp '2026/3/4' is visible in the bottom right corner of the photo.
24	GX-B1598/24-5-26032	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为2.76%，小于5%为正常。	 A photograph showing two workers in safety gear (hard hats, safety harnesses, and work clothes) standing on a metal platform or scaffolding. They are inspecting a thick steel cable. The background shows industrial structures. A yellow timestamp '2026/3/4' is visible in the bottom right corner of the photo.

25	GX-B1598/24-5-26033	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为3.12%，小于5%为正常。	 A photograph showing two workers in red hard hats and safety harnesses standing in an industrial environment. They appear to be inspecting a piece of machinery or a steel cable. A yellow date stamp '2026/3/4' is visible in the bottom right corner of the image.
26	GX-B1598/24-5-26034	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为3.33%，小于5%为正常。	 A photograph showing two workers in red hard hats and safety harnesses in an industrial setting. One worker is holding a device, possibly a measuring tool. A sign with the text '及时关闭 防止...' is visible in the background. A yellow date stamp '2026/3/4' is visible in the bottom right corner of the image.

27	GX-B1598/24-5-26035	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为3.78%，小于5%为正常。	
28	GX-B1303/26-5-26005	2026/3/6	综合判定:合格。	

29	GX-B1380/26-5-26009	2026. 3. 6	所检项目合格。	
30	GX-B1310/21-5-26075	2026. 3. 6	符合标准要求。	

31	GX-B1310/21-5-26076	2026. 3. 6	符合标准要求。	
32	GX-B1310/21-5-26077	2026. 3. 6	符合标准要求。	

33	GX-B1427/21-5-26012	2026. 3. 6	符合标准要求。	
34	GX-B1380/26-5-26010	2026. 3. 6	所检项目合格。	

35	GX-B1382/26-5-26003	2026. 3. 6	所检项目合格。	
36	GX-B1382/26-5-26004	2026. 3. 6	综合判定:合格。	



37	GX-B1495/25-5-26274~26275	2026/3/10	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	 A photograph showing a worker in a red hard hat and a grey jacket standing on a red mat next to a high-voltage switch cabinet. A laptop and some equipment are on the floor. The date 2026/1/16 is visible in the bottom right corner of the photo.
38	GX-B1350/21-5-26005	2026/3/10	本次共检验接地装置4处，4处接地装置所检项目合格。	 A photograph showing a worker in a red hard hat and dark clothing standing next to a metal structure, likely a grounding device. A laptop and equipment are on the ground. The date 2026/1/26 is visible in the bottom right corner of the photo.

39	GX-B1312/20-5-26070	2026. 3. 12	所检项目合格。	
40	GX-B1598/24-5-26024	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.62%，小于5%为正常。	

41	GX-B1598/24-5-26025	2026/3/9	实测钢丝绳有效截面积损失百分比最大为3.89%，小于5%为正常。	 A photograph showing two workers in red safety gear and hard hats inspecting a steel cable. A yellow measuring tool is visible. A timestamp '2026/02/14' is in the bottom right corner.
42	GX-B1598/24-5-26026	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.93%，小于5%为正常。	 A photograph showing two workers in red safety gear and hard hats inspecting a steel cable. A yellow measuring tool is visible. A timestamp '2026/02/14' is in the bottom right corner.

43	GX-B1598/24-5-26027	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.43%，小于5%为正常。	 <p>2026/02/14</p>
44	GX-B1598/24-5-26028	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.62%，小于5%为正常。	 <p>2026/02/14</p>



45	GX-B1598/24-5-26029	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.39%，小于5%为正常。	 A photograph showing two workers in red safety suits and helmets working in a dark, industrial environment. They are positioned on a wooden platform, and one worker appears to be inspecting or handling a large steel cable. The scene is dimly lit, with some light reflecting off the workers' gear. A yellow timestamp '2026/02/14' is visible in the bottom right corner of the image.
46	GX-B1598/24-5-26036	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.69%，小于5%为正常。	 A photograph showing two workers in red safety suits and helmets working in a dark, industrial environment. They are standing on a wooden platform, and one worker is holding a tool or device, possibly for inspecting a steel cable. The scene is dimly lit, with some light reflecting off the workers' gear. A yellow timestamp '2026/2/14' is visible in the bottom right corner of the image.

47	GX-B1598/24-5-26037	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.71%，小于5%为正常。	
48	GX-B1598/24-5-26038	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.03%，小于5%为正常。	

49	GX-B1598/24-5-26046	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.48%，小于5%为正常。	
50	GX-B1598/24-5-26047	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.14%，小于5%为正常。	

51	GX-B1598/24-5-26048	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.98%，小于5%为正常。	
52	GX-B1598/24-5-26049	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.41%，小于5%为正常。	

53	GX-B1598/24-5-26050	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.02%，小于5%为正常。	 A photograph showing two workers in red safety suits and helmets inspecting a steel cable in a dark, industrial setting. The workers are standing on a wooden platform. A yellow safety barrier is visible on the right. A timestamp '2026/2/14' is visible in the bottom right corner of the image.
54	GX-B1598/24-5-26051	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.11%，小于5%为正常。	 A photograph showing two workers in red safety suits and helmets inspecting a steel cable in a dark, industrial setting. The workers are standing on a wooden platform. A yellow safety barrier is visible on the right. A timestamp '2026/2/14' is visible in the bottom right corner of the image.



55	GX-B1598/24-5-26039	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.12%，小于5%为正常。	
56	GX-B1598/24-5-26040	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.96%，小于5%为正常。	

57	GX-B1598/24-5-26041	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.56%，小于5%为正常。	
58	GX-B1598/24-5-26042	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.29%，小于5%为正常。	

59	GX-B1598/24-5-26043	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.98%，小于5%为正常。	
60	GX-B1598/24-5-26044	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.72%，小于5%为正常。	

61	GX-B1598/24-5-26045	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.22%，小于5%为正常。	 A photograph showing two workers in red safety gear and headlamps inspecting a cable in a dark, confined space, likely a tunnel. A yellow timestamp '2026/02/14' is visible in the bottom right corner of the image.
62	GX-B1321/20-5-26170~26173	2026/3/12	本次共检电力电缆4条，4条电力电缆所检项目合格。	 A photograph showing a worker in a red hard hat and safety vest inspecting electrical equipment, possibly a control panel or switchgear, in a well-lit area. A yellow timestamp '2026/1/16' is visible in the bottom right corner of the image.

63	GX-B1328/25-5-26033	2026/3/12	本次共检绝缘手套20只，20只绝缘手套合格。	
64	GX-B1328/25-5-26034	2026/3/12	本次共检绝缘靴20只，20只绝缘靴合格。	

65	GX-B1598/24-5-26055	2026/3/12	实测钢丝绳有效截面积损失百分比最大为0.68%，小于5%为正常。 。	
66	GX-B1598/24-5-26056	2026/3/12	实测钢丝绳有效截面积损失百分比最大为0.64%，小于5%为正常。 。	

67	GX-B1598/24-5-26057	2026/3/12	实测钢丝绳有效截面积损失百分比最大为0.83%，小于5%为正常。 。	
68	GX-B1598/24-5-26058	2026/3/12	实测钢丝绳有效截面积损失百分比最大为0.70%，小于5%为正常。 。	

69	GX-B1598/24-5-26059	2026/3/12	实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常。 。	
70	GX-B1598/24-5-26060	2026/3/12	实测钢丝绳有效截面积损失百分比最大为1.84%，小于5%为正常。 。	 

71	GX-B1598/24-5-26066	2026/3/12	实测钢丝绳有效截面积损失百分比最大为1.48%，小于5%为正常。 。	
72	GX-B1598/24-5-26067	2026/3/12	实测钢丝绳有效截面积损失百分比最大为2.14%，小于5%为正常。 。	

73	GX-B1598/24-5-26068	2026/3/12	实测钢丝绳有效截面积损失百分比最大为1.98%，小于5%为正常。 。	
74	GX-B1598/24-5-26069	2026/3/12	实测钢丝绳有效截面积损失百分比最大为1.41%，小于5%为正常。 。	

75	GX-B1598/24-5-26070	2026/3/12	实测钢丝绳有效截面积损失百分比最大为2.69%，小于5%为正常。 。	
76	GX-B1598/24-5-26071	2026/3/12	实测钢丝绳有效截面积损失百分比最大为2.71%，小于5%为正常。 。	

77	GX-B1598/24-5-26072	2026/3/12	实测钢丝绳有效截面积损失百分比最大为2.03%，小于5%为正常。 。	
78	GX-B1312/20-5-26001~26005	2026/3/12	本次共检电力变压器5台，5台电力变压器所检项目合格。	

79	GX-B1312/20-5-26006~26010	2026/3/12	本次共检电力变压器5台，5台电力变压器所检项目合格。	
80	GX-B1312/20-5-26011~26014	2026/3/12	本次共检电力变压器4台，4台电力变压器所检项目合格。	

81	GX-B1312/20-5-26015~26021	2026/3/12	本次共检电力变压器7台，7台电力变压器所检项目合格。	
82	GX-B1312/20-5-26022~26024	2026/3/12	本次共检电力变压器3台，3台电力变压器所检项目合格。	



83	GX-B1312/20-5-26025~26026	2026/3/12	本次共检电力变压器2台，2台电力变压器所检项目合格。	
84	GX-B1312/20-5-26027~26033	2026/3/12	本次共检电力变压器7台，7台电力变压器所检项目合格。	

85	GX-B1312/20-5-26034~26039	2026/3/12	本次共检电力变压器6台，6台电力变压器所检项目合格。	
86	GX-B1312/20-5-26040~26046	2026/3/12	本次共检电力变压器7台，7台电力变压器所检项目合格。	

87	GX-B1312/20-5-26047~26048	2026/3/12	本次共检电力变压器2台，2台电力变压器所检项目合格。	
88	GX-B1312/20-5-26067	2026/3/12	所检项目合格。	

89	GX-B1312/20-5-26068~26069	2026/3/12	本次共检电力变压器2台，2台电力变压器所检项目合格。	
90	GX-B1321/20-5-26026~26033	2026/3/12	本次共检电力电缆8条，8条电力电缆所检项目合格。	

91	GX-B1321/20-5-26034~26040	2026/3/12	本次共检电力电缆7条，7条电力电缆所检项目合格。	
92	GX-B1321/20-5-26041~26052	2026/3/12	本次共检电力电缆12条，12条电力电缆所检项目合格。	



93	GX-B1321/20-5-26053~26062	2026/3/12	本次共检电力电缆10条，10条电力电缆所检项目合格。	
94	GX-B1321/20-5-26063~26066	2026/3/12	本次共检电力电缆4条，4条电力电缆所检项目合格。	

95	GX-B1321/20-5-26067~26070	2026/3/12	本次共检电力电缆4条，4条电力电缆所检项目合格。	
96	GX-B1321/20-5-26071~26082	2026/3/12	本次共检电力电缆12条，12条电力电缆所检项目合格。	

97	GX-B1321/20-5-26083~26087	2026/3/12	本次共检电力电缆5条，5条电力电缆所检项目合格。	
98	GX-B1321/20-5-26088~26096	2026/3/12	本次共检电力电缆9条，9条电力电缆所检项目合格。	

99	GX-B1321/20-5-26097~26106	2026/3/12	本次共检电力电缆10条，10条电力电缆所检项目合格。	
100	GX-B1321/20-5-26107~26119	2026/3/12	本次共检电力电缆13条，13条电力电缆所检项目合格。	

101	GX-B1321/20-5-26120~26129	2026/3/12	本次共检电力电缆10条，10条电力电缆所检项目合格。	
102	GX-B1321/20-5-26130~26137	2026/3/12	本次共检电力电缆8条，8条电力电缆所检项目合格。	

103	GX-B1321/20-5-26138~26143	2026/3/12	本次共检电力电缆6条，6条电力电缆所检项目合格。	 
-----	---------------------------	-----------	--------------------------	---