

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|-----------|--------|--|
| 110 | GX-B1310/21-7-26031 | 2026/3/15 | 符合标准要求 |  |
| 111 | GX-B1310/21-7-26032 | 2026/3/15 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-----------|--------|--|
| 112 | GX-B1310/21-7-26033 | 2026/3/15 | 符合标准要求 |  |
| 113 | GX-B1310/21-7-26034 | 2026/3/15 | 符合标准要求 |  |

| | | | | | |
|-----|---------------------|-----------|--------|--|--|
| 114 | GX-B1310/21-7-26035 | 2026/3/15 | 符合标准要求 | |  |
| 115 | GX-B1310/21-7-26036 | 2026/3/15 | 符合标准要求 | |  |

| | | | | |
|-----|---------------------|-----------|--------|---|
| 116 | GX-B1310/21-7-26037 | 2026/3/15 | 符合标准要求 |  <p>2026/2/26</p> |
| 117 | GX-B1310/21-7-26038 | 2026/3/15 | 符合标准要求 |  <p>2026/2/26</p> |

| | | | | | |
|-----|---------------------|-----------|--------|--|---|
| 118 | GX-B1310/21-7-26039 | 2026/3/15 | 符合标准要求 | |  <p>2026/2/26</p> |
| 119 | GX-B1310/21-7-26040 | 2026/3/15 | 符合标准要求 | |  <p>2026/2/26</p> |

| | | | | | | |
|-----|---------------------|-----------|--------|--|---|--|
| 120 | GX-B1310/21-7-26041 | 2026/3/15 | 符合标准要求 | |  A worker wearing a white hard hat, safety glasses, and a red high-visibility safety suit with reflective stripes is operating a large piece of machinery in a dark, rocky tunnel. The worker is holding a device, possibly a detector or measuring instrument. A yellow timestamp '2026/2/26' is visible in the bottom right corner of the image. | |
| 121 | GX-B1310/21-7-26042 | 2026/3/15 | 符合标准要求 | |  A worker wearing a white hard hat and a red high-visibility safety suit is standing behind a metal gate or barrier in a tunnel. The worker is looking towards the camera. A yellow timestamp '2026/2/26' is visible in the bottom right corner of the image. | |

| | | | | | | |
|-----|---------------------|-----------|--------|--|--|--|
| 122 | GX-B1310/21-7-26043 | 2026/3/15 | 符合标准要求 | |  A worker wearing a white hard hat and a red safety suit with reflective stripes is operating a yellow industrial machine. The machine has a green control panel with a 'MVA' label and an upward-pointing arrow. A yellow timestamp '2026/2/26' is visible in the bottom right corner of the image. | |
| 123 | GX-B1310/21-7-26044 | 2026/3/15 | 符合标准要求 | |  A worker wearing a white hard hat and a red safety suit is working on a large, rusty metal wheel. The worker is positioned behind the wheel, and a bright light source is visible, creating a lens flare effect. A yellow timestamp '2026/2/26' is visible in the bottom right corner of the image. | |

| | | | | |
|-----|---------------------------|-----------|------------------------------|--|
| 124 | GX-B1310/21-7-26045 | 2026/3/15 | 符合标准要求 |  <p>2026/2/26</p> |
| 125 | GX-B1495/26-7-26110~26114 | 2026/3/16 | 本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。 |  <p>2026/2/7</p> |

| | | | | | |
|-----|---------------------------|-----------|------------------------------|--|--|
| 126 | GX-B1495/26-7-26115~26119 | 2026/3/16 | 本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。 | |  |
| 127 | GX-B1310/21-7-26047 | 2026/3/15 | 符合标准要求 | |  |

| | | | | |
|-----|---------------------|-----------|---------|--|
| 128 | GX-B1428/21-7-26047 | 2026/3/15 | 无缺陷迹痕显示 |  |
| 129 | GX-B1310/21-7-26048 | 2026/3/15 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-----------|---------|--|
| 130 | GX-B1428/21-7-26048 | 2026/3/15 | 无缺陷迹痕显示 |  |
| 131 | GX-B1310/21-7-26010 | 2026/3/11 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-----------|---------|---|
| 132 | GX-B1428/21-7-26010 | 2026/3/11 | 无缺陷迹痕显示 |  A photograph showing a worker in a dark jacket and pants inspecting a large, red-painted industrial component. The component has a complex, multi-layered structure with many bolts and rivets. The worker is standing on a platform or walkway, looking closely at the component. A yellow timestamp '2026/01/28' is visible in the bottom right corner of the image. |
| 133 | GX-B1310/21-7-26011 | 2026/3/11 | 符合标准要求 |  A photograph showing a worker in a dark jacket and pants inspecting a large, red-painted industrial component. The component has a complex, multi-layered structure with many bolts and rivets. The worker is standing on a platform or walkway, looking closely at the component. A yellow timestamp '2026/01/28' is visible in the bottom right corner of the image. |

| | | | | |
|-----|---------------------|-----------|---------------------------------------|--|
| 134 | GX-B1428/21-7-26011 | 2026/3/11 | 无缺陷迹痕显示 |  |
| 135 | GX-B1598/24-7-26013 | 2026/3/15 | 实测钢丝绳有效截面积损失百分比最大为2.94%，小于5%为正常。 。 |  |

| | | | | |
|-----|---------------------|-----------|---------------------------------------|--|
| 136 | GX-B1598/24-7-26014 | 2026/3/15 | 实测钢丝绳有效截面积损失百分比最大为2.55%，小于5%为正常。 。 |  |
| 137 | GX-B1598/24-7-26015 | 2026/3/15 | 实测钢丝绳有效截面积损失百分比最大为2.18%，小于5%为正常。 。 |  |

| | | | | |
|-----|---------------------|-----------|---------------------------------------|--|
| 138 | GX-B1598/24-7-26016 | 2026/3/15 | 实测钢丝绳有效截面积损失百分比最大为2.20%，小于5%为正常。 。 |  |
| 139 | GX-B1598/24-7-26017 | 2026/3/15 | 实测钢丝绳有效截面积损失百分比最大为1.60%，小于5%为正常。 。 |  |

| | | | | |
|-----|---------------------|-----------|---------------------------------------|--|
| 140 | GX-B1598/24-7-26018 | 2026/3/15 | 实测钢丝绳有效截面积损失百分比最大为1.93%，小于5%为正常。 。 |  |
| 141 | GX-B1598/24-7-26005 | 2026/3/9 | 实测钢丝绳有效截面积损失百分比最大为1.77%，小于5%为正常。 。 |  |

| | | | | |
|-----|---------------------|-----------|----------------------------------|--|
| 142 | GX-B1598/24-7-26006 | 2026/3/9 | 实测钢丝绳有效截面积损失百分比最大为2.62%，小于5%为正常。 |  <p>2026/2/23</p> |
| 143 | GX-B1312/26-7-26114 | 2026/3/24 | 所检项目合格。 |  <p>2026/3/5</p> |

| | | | | |
|-----|---------------------------|-----------|----------------------------|--|
| 144 | GX-B1312/26-7-26115 | 2026/3/24 | 所检项目合格。 |  |
| 145 | GX-B1312/26-7-26116~26117 | 2026/3/24 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 |  |

| | | | | | |
|-----|---------------------------|-----------|----------------------------|--|--|
| 146 | GX-B1312/26-7-26118~26119 | 2026/3/24 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 | |  |
| 147 | GX-B1312/26-7-26120~26125 | 2026/3/24 | 本次共检电力变压器6台，6台电力变压器所检项目合格。 | |  |



| | | | | |
|-----|---------------------------|-----------|----------------------------|--|
| 148 | GX-B1312/26-7-26126~26131 | 2026/3/24 | 本次共检电力变压器6台，6台电力变压器所检项目合格。 |  |
| 149 | GX-B1321/26-7-26121 | 2026/3/24 | 所检项目合格。 |  |



| | | | | | |
|-----|---------------------|-------------|---------|--|--|
| 150 | GX-B1321/26-7-26122 | 2026/3/24 | 所检项目合格。 | |  |
| 151 | GX-B1380/26-7-26007 | 2026. 3. 24 | 所检项目合格。 | |  |

| | | | | | |
|-----|---------------------|-------------|---------|--|--|
| 152 | GX-B1380/26-7-26008 | 2026. 3. 24 | 所检项目合格。 | |  <p>2026/02/23</p> |
| 153 | GX-B1380/26-7-26009 | 2026. 3. 24 | 所检项目合格。 | |  <p>2026/02/24</p> |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 154 | GX-B1380/26-7-26010 | 2026. 3. 24 | 所检项目合格。 |  |
| 155 | GX-B1380/26-7-26011 | 2026. 3. 24 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------------|-------------|--------------------------|--|
| 156 | GX-B1321/26-7-26065-26068 | 2026. 3. 24 | 本次共检电力电缆4条，4条电力电缆所检项目合格。 |  |
| 157 | GX-B1321/26-7-26101-26108 | 2026. 3. 24 | 本次共检电力电缆8条，8条电力电缆所检项目合格。 |  |

| | | | | |
|-----|---------------------------|-------------|----------------------------|--|
| 158 | GX-B1312/26-7-26093~26098 | 2026. 3. 24 | 本次共检电力变压器6台，6台电力变压器所检项目合格。 |  |
| 159 | GX-B1312/26-7-26084~26087 | 2026. 3. 24 | 本次共检电力变压器4台，4台电力变压器所检项目合格。 |  |

| | | | | |
|-----|---------------------------|-------------|----------------------------|--|
| 160 | GX-B1321/26-7-26059~26064 | 2026. 3. 24 | 本次共检电力电缆6条，6条电力电缆所检项目合格。 |  |
| 161 | GX-B1312/26-7-26088~26089 | 2026. 3. 24 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 |  |

| | | | | |
|-----|---------------------------|-------------|----------------------------|--|
| 162 | GX-B1312/26-7-26090~26092 | 2026. 3. 24 | 本次共检电力变压器3台，3台电力变压器所检项目合格。 |  |
| 163 | GX-B1321/26-7-26091~26100 | 2026. 3. 24 | 本次共检电力电缆10条，10条电力电缆所检项目合格。 |  |