

序号	报告编号	发布日期	结论	影像资料
116	GX-B1598/24-P-26001	2026. 3. 13	<p>实测钢丝绳有效截面积损失百分比最大为0.72%，小于5%为正常。</p>	
117	GX-B1598/24-P-26002	2026. 3. 13	<p>实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常。</p>	

118	GX-B1598/24-P-26003	2026. 3. 13	实测钢丝绳有效截面积损失百分比最大为0.78%，小于5%为正常。 。	
119	GX-B1598/24-P-26004	2026. 3. 13	实测钢丝绳有效截面积损失百分比最大为0.80%，小于5%为正常。 。	

120	GX-B1598/24-P-26005	2026. 3. 13	实测钢丝绳有效截面积损失百分比最大为0.47%，小于5%为正常。 。	
121	GX-B1598/24-P-26006	2026. 3. 13	实测钢丝绳有效截面积损失百分比最大为0.50%，小于5%为正常。 。	

122	GX-B1303/21-P-26005	2026. 3. 16	综合判定：合格。	 A worker in an orange safety suit and red helmet is operating a large green industrial machine. The worker is standing on a platform and reaching towards the machine. The machine has a large circular opening. The date '2026 02 26' is visible in the bottom right corner of the photo.
123	GX-B1303/21-P-26006	2026. 3. 16	综合判定：合格。	 A worker in an orange safety suit and red helmet is standing next to a large green industrial machine. The worker is looking at something in their hands. The machine has a large circular opening. The date '2026 02 26' is visible in the bottom right corner of the photo.

124	GX-B1305/21-P-26003	2026. 3. 16	综合判定：合格。	
125	GX-B1321/26-P-26006~26012	2026. 3. 17	本次共检电力电缆 7条，7条电力电缆所 检项目合格。	

126	GX-B1321/26-P-26013~26015	2026. 3. 17	本次共检电力电缆 3条，3条电力电缆所 检项目合格。	 <p>贵州金沙凤凰煤业有限公司 2026.02.11</p>
127	GX-B1323/26-P-26001~26002	2026. 3. 17	本次共检三相交流电 动机2台，2台三相交 流电动机所检项目合 格。	 <p>贵州金沙凤凰煤业有限公司 2026.03.11</p>

128	GX-B1323/26-P-26003~26005	2026. 3. 17	<p>本次共检高压隔爆型变频调速三相异步电动机3台，3台高压隔爆型变频调速三相异步电动机合格。</p>		
129	GX-B1323/26-P-26006~26007	2026. 3. 17	<p>本次共检矿用隔爆型三相永磁同步变频电动机2台，2台矿用隔爆型三相永磁同步变频电动机合格。</p>		

130	GX-B1323/26-P-26008~26009	2026. 3. 17	<p>本次共检高压隔爆型三相异步电动机2台，2台高压隔爆型三相异步电动机合格。</p>	 <p>贵州金沙龙凤煤业有限公司 2026-02-11</p>
131	GX-B1323/26-P-26010~26011	2026. 3. 17	<p>本次共检矿用隔爆型三相永磁同步变频电动机2台，2台矿用隔爆型三相永磁同步变频电动机合格。</p>	 <p>贵州金沙龙凤煤业有限公司 2026-02-11</p>

132	GX-B1312/26-P-26081	2026. 3. 17	所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月12日</p>
133	GX-B1312/26-P-26082	2026. 3. 17	所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月13日</p>

134	GX-B1312/26-P-26019	2026. 3. 18	所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026.2.10</p>
135	GX-B1312/26-P-26020	2026. 3. 18	所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026.2.10</p>

136	GX-B1312/26-P-26021~26023	2026. 3. 18	本次共检电力变压器3台，3台电力变压器所检项目合格。	
137	GX-B1312/26-P-26024~26026	2026. 3. 18	本次共检煤矿用防爆干式变压器3台，3台防爆干式变压器所检项目合格。	

138	GX-B1312/26-P-26027~26028	2026. 3. 18	本次共检电力变压器2台，2台电力变压器所检项目合格。	
139	GX-B1350/21-P-26003	2026. 3. 17	表置5处，5处接地装置所	

140	GX-B1310/21-P-26049	2026. 3. 19	符合标准要求。	 <p>2026 02 26</p>
141	GX-B1310/21-P-26050	2026. 3. 19	符合标准要求。	 <p>2026 02 26</p>

142	GX-B1310/21-P-26051	2026. 3. 19	符合标准要求。	 A worker in an orange safety suit and red helmet is operating machinery on a large industrial structure. The worker is positioned on a platform, and the machinery appears to be part of a large-scale construction or maintenance project. The background shows a large, curved metal structure, possibly a tank or a large pipe. The date '2026 02 26' is visible in the bottom right corner of the image.
143	GX-B1310/21-P-26052	2026. 3. 19	符合标准要求。	 A worker in an orange safety suit and red helmet is standing on a ladder next to a large, rusted metal structure. The worker is holding a clipboard and looking towards the camera. The structure is made of thick, weathered metal plates. The background is a clear blue sky. The date '2026 02 26' is visible in the bottom right corner of the image.

144	GX-B1310/21-P-26053	2026. 3. 19	符合标准要求。	
145	GX-B1310/21-P-26054	2026. 3. 19	符合标准要求。	

146	GX-B1310/21-P-26055	2026. 3. 19	符合标准要求。	
147	GX-B1310/21-P-26056	2026. 3. 19	符合标准要求。	

148	GX-B1310/21-P-26057	2026. 3. 19	符合标准要求。	 <p>2026 02 25</p>
149	GX-B1310/21-P-26058	2026. 3. 19	符合标准要求。	 <p>2026 02 25</p>

150	GX-B1310/21-P-26059	2026. 3. 19	符合标准要求。	 <p>2026 02 25</p>
151	GX-B1310/21-P-26066	2026. 3. 19	符合标准要求。	 <p>2026 02 26</p>

152	GX-B1427/21-P-26009	2026. 3. 19	符合标准要求。	
153	GX-B1427/21-P-26010	2026. 3. 19	符合标准要求。	

154	GX-B1427/21-P-26011	2026. 3. 19	符合标准要求。	 A photograph showing two workers in red safety gear and hard hats. One worker is standing on a ladder, reaching up to inspect or work on the top of a large, dark, cylindrical industrial tank. The other worker is on the ground, also looking up at the tank. The background shows an industrial setting with metal structures and a yellow safety fence. A date stamp '2026 02 26' is visible in the bottom right corner of the photo.
155	GX-B1427/21-P-26012	2026. 3. 19	符合标准要求。	 A photograph showing two workers in orange safety gear and hard hats. One worker is standing on a ladder, reaching up to inspect or work on the top of a large, dark, cylindrical industrial tank. The other worker is on the ground, also looking up at the tank. The background shows an industrial setting with metal structures and a yellow safety fence. A date stamp '2026 02 26' is visible in the bottom right corner of the photo.

156	GX-B1427/21-P-26013	2026. 3. 19	符合标准要求。	
157	GX-B1427/21-P-26014	2026. 3. 19	符合标准要求。	

158	GX-B1427/21-P-26015	2026. 3. 19	符合标准要求。	 <p>2026 02 26</p>
159	GX-B1310/21-P-26060	2026. 3. 18	符合标准要求。	 <p>桐山县天云煤矿有限公司 2026.3.11</p>

160	GX-B1310/21-P-26061	2026. 3. 18	符合标准要求。	 <p>横山县天云煤矿有限公司 2026.3.11</p>
161	GX-B1310/21-P-26062	2026. 3. 18	符合标准要求。	 <p>横山县天云煤矿有限公司 2026.3.11</p>