





序号	报告编号	发布日期	结论	影像资料
194	GX-B1310/21-6-26054	2026. 4. 30	符合标准要求	
195	GX-B1310/21-6-26055	2026. 4. 30	符合标准要求	

196	GX-B1310/21-6-26056	2026. 4. 30	符合标准要求	
197	GX-B1451/26-6-26122~26132	2026. 4. 30	本次共检高压开关柜 11台, 11台高压开关柜 所检项目合格。	 <p>2026 03 28</p>

198	GX-B1451/26-6-26133~26143	2026. 4. 30	本次共检高压开关柜11台, 11台高压开关柜所检项目合格。		
199	GX-B1451/26-6-26144~26152	2026. 4. 30	本次共检高压开关柜9台, 9台高压开关柜所检项目合格。		



200	GX-B1451/26-6-26153~26165	2026. 4. 30	本次共检高压开关柜 13台, 13台高压开关柜 所检项目合格。	 <p>2026 03 31</p>
201	GX-B1451/26-6-26166~26175	2026. 4. 30	本次共检高压开关柜 10台, 10台高压开关柜 所检项目合格。	 <p>2026 04 01</p>

202	GX-B1451/26-6-26176~26192	2026. 4. 30	本次共检高压开关柜 17台, 17台高压开关柜 所检项目合格。		 <p>2026 04 02</p>
203	GX-B1451/26-6-26193~26207	2026. 4. 30	本次共检高压开关柜 15台, 15台高压开关柜 所检项目合格。		 <p>2026 04 03</p>



204	GX-B1451/26-6-26208~26224	2026. 4. 30	本次共检高压开关柜 17台, 17台高压开关柜 所检项目合格。	
205	GX-B1451/26-6-26225~26240	2026. 4. 30	本次共检高压开关柜 16台, 16台高压开关柜 所检项目合格。	

206	GX-B1495/26-6-26174~26181	2026. 4. 30	本次共检互感器8组， 8组互感器所检项目合格。	
207	GX-B1350/21-6-26008	2026. 4. 30	本次共检接地装置 2处，2处接地装置所 检项目合格。	


208	GX-B1307/26-6-26001	2026. 4. 30	综合判定：合格。	 <p>2026 03 13</p>
209	GX-B1307/26-6-26002	2026. 4. 30	综合判定：合格。	 <p>2026 03 14</p>

210	GX-B1307/26-6-26003	2026. 4. 30	综合判定：合格。	
211	GX-B1307/26-6-26004	2026. 4. 30	综合判定：合格。	

212	GX-B1307/26-6-26005	2026. 4. 30	综合判定：合格。	
213	GX-B1307/26-6-26006	2026. 4. 30	综合判定：合格。	

214	GX-B1313/26-6-26138	2026. 4. 20	所检项目合格。	
215	GX-B1598/24-6-26168	2026. 4. 30	实测钢丝绳有效截面积损失百分比最大为0.50%，小于5%为正常	

216	GX-B1598/24-6-26169	2026. 4. 30	实测钢丝绳有效截面积损失百分比最大为0.45%，小于5%为正常。 。	
217	GX-B1598/24-6-26170	2026. 4. 30	实测钢丝绳有效截面积损失百分比最大为0.41%，小于5%为正常。 。	

218	GX-B1598/24-6-26171	2026. 4. 30	实测钢丝绳有效截面积损失百分比最大为0.38%，小于5%为正常。 。	
219	GX-B1598/24-6-26142	2026. 4. 23	实测钢丝绳有效截面积损失百分比最大为2.00%，小于5%为正常。 。	

220	GX-B1598/24-6-26143	2026. 4. 23	实测钢丝绳有效截面积损失百分比最大为2.09%，小于5%为正常。 。	
221	GX-B1598/24-6-26144	2026. 4. 23	实测钢丝绳有效截面积损失百分比最大为2.14%，小于5%为正常。 。	

222	GX-B1598/24-6-26145	2026. 4. 23	实测钢丝绳有效截面积损失百分比最大为2.19%，小于5%为正常。 。	
223	GX-B1598/24-6-26178	2026. 4. 25	实测钢丝绳有效截面积损失百分比最大为1.79%，小于5%为正常。 。	

224	GX-B1548/20-6-26020	2026. 4. 28	所检项目合格。	 <p>2026 04 10</p>
225	GX-B1310/21-6-26045	2026. 4. 30	符合标准要求	 <p>2026 03 09</p>

226	GX-B1310/21-6-26046	2026. 4. 30	符合标准要求	 A worker in a grey uniform and white hard hat is operating a green machine on a roof. The machine is mounted on a metal structure. The worker is leaning over the machine, and the background shows a blue sky and some buildings. A timestamp '2026 03 09' is visible in the bottom right corner of the image.
227	GX-B1310/21-6-26047	2026. 4. 30	符合标准要求	 A worker in a black shirt and white hard hat is operating a machine on a roof. The worker is wearing a red safety harness. The machine is mounted on a metal structure. The background shows a blue sky and some buildings. A timestamp '2026 03 09' is visible in the bottom right corner of the image.

228	GX-B1310/21-6-26048	2026. 4. 30	符合标准要求	
229	GX-B1310/21-6-26049	2026. 4. 30	符合标准要求	

230	GX-B1310/21-6-26050	2026. 4. 30	符合标准要求	 <p>2026 03 10</p>
231	GX-B1310/21-6-26051	2026. 4. 30	符合标准要求	 <p>2026 03 10</p>

232	GX-B1310/21-6-26052	2026. 4. 30	符合标准要求	
233	GX-B1310/21-6-26053	2026. 4. 30	符合标准要求	