


| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|------------|-------------------|--|
| 23 | GX-B1304/21-1-25007 | 2025. 6. 6 | 综合判定：合格 |  |
| 24 | GX-B1328/20-1-25059 | 2025. 6. 6 | 本次共检验电器2支，2支验电器合格 |  |

| | | | | |
|----|---------------------|------------|-----------------------------|--|
| 25 | GX-B1328/20-1-25060 | 2025. 6. 6 | 本次共检便携式短路接地线1套，1套便携式短路接地线合格 |  |
| 26 | GX-B1328/20-1-25061 | 2025. 6. 6 | 本次共检绝缘杆1套，1套绝缘杆合格 |  |

| | | | | |
|----|---------------------------|-------------|--|---|
| 27 | GX-B1451/20-1-25256~25259 | 2025. 6. 10 | 本次共检高压开关柜4台, 4台 高压开关柜所检项目合格 |  A photograph showing two workers in red hard hats and safety gear inspecting a high-voltage switchgear cabinet. One worker is standing and looking at the internal components, while the other is kneeling and holding a clipboard. The date stamp '2025 05 25' is visible in the bottom right corner of the image. |
| 28 | GX-B1598/24-1-25030 | 2025. 6. 10 | 实测钢丝绳有效截面积损失 百分比最大为1.65%, 小于5% 为正常 |  A photograph showing a worker in a red hard hat and safety gear inspecting a steel rope on a wooden platform. The worker is kneeling and using a tool to measure the rope. The date stamp '2025/4/23' is visible in the bottom right corner of the image. |

| | | | | |
|----|---------------------|-------------|---------------------------------|--|
| 29 | GX-B1598/24-1-25031 | 2025. 6. 10 | 实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常 |  |
| 30 | GX-B1598/24-1-25032 | 2025. 6. 10 | 实测钢丝绳有效截面积损失百分比最大为2.51%，小于5%为正常 |  |

| | | | | |
|----|---------------------------|-------------|---------------------------------|--|
| 31 | GX-B1598/24-1-25033 | 2025. 6. 10 | 实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常 |  |
| 32 | GX-B1313/21-1-25118~25123 | 2025. 6. 11 | 本次共检电力变压器6台，6台电力变压器所检项目合格 |  |

| | | | | |
|----|---------------------------|-------------|---------------------------|--|
| 33 | GX-B1312/20-1-25353~25358 | 2025. 6. 11 | 本次共检电力变压器6台，6台电力变压器所检项目合格 |  |
| 34 | GX-B1312/20-1-25359~25360 | 2025. 6. 11 | 本次共检电力变压器2台，2台电力变压器所检项目合格 |  |

| | | | | |
|----|---------------------------|-------------|---------------------------|--|
| 35 | GX-B1312/20-1-25361~25369 | 2025. 6. 11 | 本次共检电力变压器9台，9台电力变压器所检项目合格 |  |
| 36 | GX-B1312/20-1-25370~25378 | 2025. 6. 11 | 本次共检电力变压器9台，9台电力变压器所检项目合格 |  |


| | | | | |
|----|---------------------------|-------------|---------------------------|--|
| 37 | GX-B1312/20-1-25379~25382 | 2025. 6. 11 | 本次共检电力变压器4台，4台电力变压器所检项目合格 |  <p>2025/05/11</p> |
| 38 | GX-B1312/20-1-25383~25384 | 2025. 6. 11 | 本次共检电力变压器2台，2台电力变压器所检项目合格 |  <p>2025/05/13</p> |

| | | | | |
|----|---------------------------|-------------|---------------------------|--|
| 39 | GX-B1312/20-1-25385~25386 | 2025. 6. 11 | 本次共检电力变压器2台，2台电力变压器所检项目合格 |  |
| 40 | GX-B1312/20-1-25387~25388 | 2025. 6. 11 | 本次共检电力变压器2台，2台电力变压器所检项目合格 |  |

| | | | | | | |
|----|---------------------|-------------|---------|--|--|--|
| 41 | GX-B1418/23-1-25001 | 2025. 6. 13 | 综合判定：合格 | |  | |
| 42 | GX-B1418/23-1-25002 | 2025. 6. 13 | 综合判定：合格 | |  | |

| | | | | |
|----|---------------------------|-------------|---------|--|
| 43 | GX-B1418/23-1-25003 | 2025. 6. 13 | 综合判定：合格 |  |
| 44 | GX-B1323/21-1-25335~25337 | 2025. 6. 13 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|-------------|--------|--|
| 45 | GX-B1323/21-1-25338~25340 | 2025. 6. 13 | 所检项目合格 |  |
| 46 | GX-B1323/21-1-25341~25343 | 2025. 6. 13 | 所检项目合格 |  |

| | | | | |
|----|---------------------|-------------|--------|--|
| 47 | GX-B1310/21-1-25128 | 2025. 6. 12 | 符合标准要求 |  <p>2025/05/16</p> |
| 48 | GX-B1310/21-1-25129 | 2025. 6. 12 | 符合标准要求 |  <p>2025/05/16</p> |

| | | | | |
|----|---------------------|-------------|--------|--|
| 49 | GX-B1427/21-1-25130 | 2025. 6. 12 | 符合标准要求 |  |
| 50 | GX-B1310/21-1-25131 | 2025. 6. 12 | 符合标准要求 |  |

| | | | | |
|----|---------------------|-------------|--------|--|
| 51 | GX-B1310/21-1-25132 | 2025. 6. 12 | 符合标准要求 |  |
| 52 | GX-B1310/21-1-25133 | 2025. 6. 12 | 符合标准要求 |  |

| | | | | |
|----|---------------------|-------------|---------|---|
| 53 | GX-B1310/21-1-25134 | 2025. 6. 12 | 符合标准要求 |  <p>A photograph showing two workers in safety gear (hard hats and work clothes) standing next to large, blue industrial machinery. The machinery has 'Ex' markings on it. The date '2025/05/16' is visible in the bottom right corner of the photo.</p> |
| 54 | GX-B1428/21-1-25135 | 2025. 6. 12 | 无缺陷迹痕显示 |  <p>A photograph showing one worker in safety gear standing next to the same large, blue industrial machinery as in the previous photo. The date '2025/05/16' is visible in the bottom right corner of the photo.</p> |

| | | | | |
|----|---------------------|-------------|---------|--|
| 55 | GX-B1310/21-1-25139 | 2025. 6. 12 | 符合标准要求 |  |
| 56 | GX-B1428/21-1-25140 | 2025. 6. 12 | 无缺陷迹痕显示 |  |