





序号	报告编号	发布日期	结论	影像资料
1	GX-B1350/21-7-26025	2026. 6. 1	所检项目合格。	
2	GX-B1308/26-7-26007	2026. 6. 2	综合判定：合格。	

3	GX-B1321/26-7-26457~26458	2026/6/1	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
4	GX-B1321/26-7-26459~26465	2026/6/1	本次共检电力电缆 7条，7条电力电缆所 检项目合格。	

5	GX-B1321/26-7-26466~26467	2026/6/1	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
6	GX-B1321/26-7-26468~26473	2026/6/1	本次共检电力电缆 6条，6条电力电缆所 检项目合格。	

7	GX-B1451/26-7-26130~26144	2026/6/2	本次共检高压开关柜 15台, 15台高压开关柜 所检项目合格。	
8	GX-B1517/26-7-26012	2026/6/1	综合判定: 合格	

9	GX-B1517/26-7-26013	2026/6/1	综合判定：合格	
10	GX-B1517/26-7-26014	2026/6/1	综合判定：合格	

11	GX-B1517/26-7-26015	2026/6/1	综合判定：合格	
12	GX-B1517/26-7-26016	2026/6/1	综合判定：合格	

13	GX-B1517/26-7-26017	2026/6/1	综合判定：合格	
14	GX-B1310/21-7-26067	2026. 6. 1	符合标准要求。	

15	GX-B1310/21-7-26068	2026. 6. 1	符合标准要求。	 A photograph showing a worker in a red jacket and red hard hat working on a large, green, cylindrical mechanical component of a dam structure. The worker is using a tool to inspect or adjust the component. The background shows a concrete dam structure and a cloudy sky. A yellow date stamp '2026/3/15' is visible in the bottom right corner of the photo.
----	---------------------	------------	---------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------