



序号	报告编号	发布日期	结论	影像资料
264	GX-B1323/26-6-26093~26098	2026/6/16	所检项目合格。	
265	GX-B1422/23-6-26003	2026. 6. 15	综合判定：合格。	

266	GX-B1422/23-6-26004	2026. 6. 15	综合判定：合格。	 2026 04 03
267	GX-B1310/21-6-26085 替换 GX-B1310/21-6-25273	2026. 6. 9	符合标准要求	 2025 9 8

268	GX-B1310/21-6-26086 替换 GX-B1310/21-6-25274	2026. 6. 9	符合标准要求	 A worker in an orange safety suit and helmet is working on a metal structure. The date 2025 9 8 is visible in the bottom right corner of the photo.
269	GX-B1310/21-6-26087 替换 GX-B1310/21-6-25275	2026. 6. 9	符合标准要求	 A worker in an orange safety suit and helmet is working on a metal structure. The date 2025 9 8 is visible in the bottom right corner of the photo.

270	GX-B1310/21-6-26088 替换 GX-B1310/21-6-25276	2026. 6. 9	符合标准要求	
271	GX-B1304/26-6-26018	2026. 6. 15	综合判定：合格。	

272	GX-B1598/24-6-26194	2026. 6. 7	实测钢丝绳有效截面积损失百分比最大为4.13%，小于5%为正常。 。	
273	GX-B1598/24-6-26195	2026. 6. 7	实测钢丝绳有效截面积损失百分比最大为4.31%，小于5%为正常。 。	

274	GX-B1598/24-6-26196	2026. 6. 7	实测钢丝绳有效截面积损失百分比最大为3.96%，小于5%为正常。 。		
275	GX-B1598/24-6-26197	2026. 6. 7	实测钢丝绳有效截面积损失百分比最大为4.38%，小于5%为正常。 。		

276	GX-B1598/24-6-26198	2026. 6. 7	实测钢丝绳有效截面积损失百分比最大为1.45%，小于5%为正常。 。		
277	GX-B1598/24-6-26199	2026. 6. 7	实测钢丝绳有效截面积损失百分比最大为1.40%，小于5%为正常。 。		

278	GX-B1534/20-6-26042	2026. 6. 12	所检项目合格。	
279	GX-B1310/21-6-26113	2026. 6. 22	符合标准要求	

280	GX-B1310/21-6-26114	2026. 6. 22	符合标准要求	
281	GX-B1383/26-6-26001	2026. 6. 16	综合判定：不脱钩试验合格。	

282	GX-B1383/26-6-26002	2026. 6. 16	综合判定：不脱钩试验合格。	
283	GX-B1380/26-6-26026	2026. 6. 17	所检项目合格。	

284	GX-B1304/26-6-26017	2026. 6. 17	综合判定：合格。	
285	GX-B1312/26-6-26118~25119	2026. 6. 16	本次共检电力变压器2台, 2台电力变压器所检项目合格。	

286	GX-B1313/26-6-26189	2026. 6. 16	本次共检电力变压器1台，1台电力变压器所检项目合格。	
287	GX-B1305/26-6-26029	2026/6/18	综合判定：合格。	

288	GX-B1305/26-6-26033	2026/6/18	综合判定：合格。	 A worker wearing a blue uniform, a red helmet, and safety harness is operating a large red industrial machine in a tunnel. The machine has a large flywheel. A date stamp '2026 04 17' is visible in the bottom right corner of the image.
289	GX-B1310/21-6-26079	2026/6/17	符合标准要求	 A worker wearing a grey uniform, a red helmet, and safety glasses is operating a large green industrial machine. The machine has a large flywheel. A date stamp '2026 04 15' is visible in the bottom right corner of the image.

290	GX-B1310/21-6-26080	2026/6/17	符合标准要求			
291	GX-B1310/21-6-26081	2026/6/17	符合标准要求			

292	GX-B1310/21-6-26113	2026. 6. 22	符合标准要求	 A worker wearing a blue uniform, red helmet, and safety harness is operating a device in a dark industrial setting. The date stamp '2026 06 20' is visible in the bottom right corner of the image.
293	GX-B1310/21-6-26114	2026. 6. 22	符合标准要求	 A worker wearing a blue uniform, red helmet, and safety harness is operating a device in a bright industrial setting. The date stamp '2026 06 20' is visible in the bottom right corner of the image.

294	GX-B1598/24-6-26206	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为4.71%，小于5%为正常。 。		
295	GX-B1598/24-6-26207	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为4.79%，小于5%为正常。 。		

296	GX-B1598/24-6-26208	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为4.28%，小于5%为正常。 。			
297	GX-B1598/24-6-26209	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为4.42%，小于5%为正常。 。			

298	GX-B1598/24-6-26210	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为4.18%，小于5%为正常。 。		
299	GX-B1598/24-6-26211	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为2.28%，小于5%为正常。 。		

300	GX-B1598/24-6-26212	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为2.31%，小于5%为正常。 。		
301	GX-B1598/24-6-26213	2026. 6. 22	实测钢丝绳有效截面积损失百分比最大为2.34%，小于5%为正常。 。		