

序号	报告编号	发布日期	结论	影像资料
198	GX-B1310/21-2-25188	2025/8/10	符合标准要求。	
199	GX-B1306/23-2400465TH1	2025/8/18	综合判定：合格	

200	GX-B1539/22-2-25028	2025/8/22	除无辅助制动系统， 其余所检项目合格。	
201	GX-B1539/22-2-25029	2025/8/22	除无辅助制动系统， 其余所检项目合格。	

202	GX-B1539/22-2-25030	2025/8/22	除无辅助制动系统， 其余所检项目合格。	 2025/04/21
203	GX-B1539/22-2-25031	2025/8/22	除无辅助制动系统， 其余所检项目合格。	 2025/04/22

204	GX-B1539/22-2-25032	2025/8/22	除无辅助制动系统、 坐姿司机室基本出入口高度小于1300mm， 其余所检项目合格。	
205	GX-B1539/22-2-25033	2025/8/22	除无辅助制动系统、 坐姿司机室基本出入口高度小于1300mm， 其余所检项目合格。	

206	GX-B1539/22-2-25034	2025/8/22	除坐姿司机室基本出入口高度小于1300mm, 无辅助制动系统, 其余所检项目合格。	
207	GX-B1539/22-2-25035	2025/8/22	除坐姿司机室基本出入口高度小于1300mm, 无辅助制动系统, 其余所检项目合格。	

208	GX-B1539/22-2-25036	2025/8/22	除坐姿司机室基本出入口高度小于1300mm, 无辅助制动系统, 其余所检项目合格。	
209	GX-B1539/22-2-25037	2025/8/22	除坐姿司机室基本出入口高度小于1300mm, 无辅助制动系统, 其余所检项目合格。	

210	GX-B1539/22-2-25038	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。	
211	GX-B1539/22-2-25039	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。	

212	GX-B1539/22-2-25040	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。	
213	GX-B1539/22-2-25041	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。	

214	GX-B1539/22-2-25042	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。		 2025/04/29
215	GX-B1539/22-2-25043	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。		 2025/04/29

216	GX-B1539/22-2-25044	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。		
217	GX-B1539/22-2-25045	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。		

218	GX-B1539/22-2-25046	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。	 A photograph showing a yellow LHD loader in a tunnel. Two workers in blue uniforms and red hard hats are standing near the loader. One worker is kneeling and working on something on the ground. The tunnel walls are rocky and there are some cables hanging from the ceiling. A date stamp '2025/04/30' is visible in the bottom right corner of the photo.
219	GX-B1539/22-2-25047	2025/8/22	除坐姿司机室基本出入口高度小于1300mm，无辅助制动系统，其余所检项目合格。	 A photograph showing a yellow LHD loader in a tunnel. Two workers in red uniforms and red hard hats are standing near the loader. The tunnel walls are rocky and there are some cables hanging from the ceiling. A date stamp '2025/04/30' is visible in the bottom right corner of the photo.



220	GX-B1620/24-2-25009	2025. 8. 22	实测流量42. 3m ³ /h、 电机输入功率 19. 9kW，不做判定， 其余所检项目合格。	
221	GX-B1620/24-2-25010	2025. 8. 22	实测流量40. 6m ³ /h、 电机输入功率 20. 5kW，不做判定， 其余所检项目合格。	


222	GX-B1620/24-2-25011	2025. 8. 22	实测流量38.6m ³ /h、 电机输入功率 19.7kW，不做判定， 其余所检项目合格。	
223	GX-B1328/20-2-25092	2025/8/28	本次共检绝缘手套68 只，68只绝缘手套合 格。	

224	GX-B1328/20-2-25093	2025/8/28	本次共检绝缘靴 38只，38只绝缘靴合格。	
225	GX-B1328/20-2-25094	2025/8/28	本次共检绝缘胶垫90 块，90块绝缘胶垫合格。	



226	GX-B1598/24-2-25196	2025. 8. 29	实测钢丝绳有效截面积损失百分比最大为0. 51%，小于5%为正常。 。	
227	GX-B1598/24-2-25197	2025. 8. 29	实测钢丝绳有效截面积损失百分比最大为0. 47%，小于5%为正常。 。	


228	GX-B1598/24-2-25198	2025. 8. 29	实测钢丝绳有效截面积损失百分比最大为0.63%，小于5%为正常。	
229	GX-B1598/24-2-25199	2025. 8. 29	实测钢丝绳有效截面积损失百分比最大为0.59%，小于5%为正常。 。	



230	GX-B1380/20-2-25001	2025. 8. 28	所检项目合格。	
231	GX-B1380/20-2-25002	2025. 8. 28	所检项目合格。	


232	GX-B1382/21-2-25001	2025. 8. 28	建议按照GB 16423 《金属非金属矿山安全规程》第6. 4. 4. 29条规定，每半年对防坠器进行1次静负荷试验。 合格。	
233	GX-B1382/21-2-25002	2025. 8. 28	建议按照GB 16423 《金属非金属矿山安全规程》第6. 4. 4. 29条规定，每半年对防坠器进行1次静负荷试验。 合格。	

234	GX-B1310/21-2-25323	2025. 8. 29	符合标准要求。	 A photograph showing two workers in blue uniforms and red hard hats. One worker is in the foreground, looking towards the camera, while the other is slightly behind him, looking at a large, dark, circular industrial component. The date '2025/08/23' is visible in the bottom right corner of the photo.
235	GX-B1428/21-2-25323	2025. 8. 29	无缺陷迹痕显示。	 A photograph showing two workers in blue uniforms and red hard hats standing next to a large, red industrial machine. One worker is standing and looking at the machine, while the other is slightly behind him. The date '2025/08/23' is visible in the bottom right corner of the photo.



236	GX-B1598/24-2-25183	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为2.13%，小于5%为正常。 。	
237	GX-B1598/24-2-25184	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为2.27%，小于5%为正常。 。	



238	GX-B1598/24-2-25185	2025. 8. 30	实测钢丝绳有效截面 积损失百分比最大为 2. 55%，小于5%为正常 。	
239	GX-B1598/24-2-25186	2025. 8. 30	实测钢丝绳有效截面 积损失百分比最大为 2. 05%，小于5%为正常 。	



240	GX-B1598/24-2-25187	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为2.34%，小于5%为正常。 。	 2025.08.23
241	GX-B1598/24-2-25188	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为2.28%，小于5%为正常。 。	 2025.08.23


242	GX-B1598/24-2-25189	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为0.71%，小于5%为正常。 。	
243	GX-B1598/24-2-25190	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为0.86%，小于5%为正常。 。	

244	GX-B1598/24-2-25191	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为0.64%，小于5%为正常。 。	
245	GX-B1598/24-2-25192	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为2.37%，小于5%为正常。 。	


246	GX-B1598/24-2-25193	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.81%，小于5%为正常。 。	
247	GX-B1598/24-2-25194	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为2.09%，小于5%为正常。 。	

248	GX-B1598/24-2-25195	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为2.20%，小于5%为正常。 。	
249	GX-B1598/24-2-25200	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.04%，小于5%为正常。 。	

250	GX-B1598/24-2-25201	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.22%，小于5%为正常。 。	
251	GX-B1598/24-2-25202	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.53%，小于5%为正常。 。	

252	GX-B1598/24-2-25203	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.46%，小于5%为正常。 。	
253	GX-B1598/24-2-25204	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。 。	

254	GX-B1598/24-2-25205	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.09%，小于5%为正常。 。	
255	GX-B1598/24-2-25206	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.39%，小于5%为正常。 。	

256	GX-B1598/24-2-25207	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.05%，小于5%为正常。 。	
257	GX-B1598/24-2-25208	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.14%，小于5%为正常。 。	

258	GX-B1598/24-2-25209	2025. 8. 30	实测钢丝绳有效截面积损失百分比最大为1.02%，小于5%为正常。 。	
259	GX-B1354/20-2-25003	2025/8/26	合格。	

260	GX-B1354/20-2-25004	2025/8/26	合格。	 2025/8/5
261	GX-B1354/20-2-25005	2025/8/26	合格。	 2025/8/5

262	GX-B1354/20-2-25006	2025/8/26	合格。	
263	GX-B1404/20-2-25016	2025/8/26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

264	GX-B1404/20-2-25017	2025/8/26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
265	GX-B1404/20-2-25018	2025/8/26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

266

GX-B1404/20-2-25019

2025/8/26

所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。

