






序号	报告编号	发布日期	结论	影像资料
1	GX-B1341/24-8-26004	2026. 3. 12	综合判定：合格。	 <p>2026-02-28</p>
2	GX-B1341/24-8-26005	2026. 3. 12	综合判定：合格。	 <p>2026-02-28</p>

3	GX-B1343/21-8-26003	2026. 3. 12	矿井通风阻力：北翼通风系统708. 2Pa，南翼通风系统624. 6Pa。	 
4	GX-B1347/21-8-26003	2026. 3. 12	综合指标92.4%，大于72%，合格	 

5	GX-B1371/21-8-26001	2026. 3. 12	存在问题：1、监测监控设备未定期进行调校。2、无传感器调校记录表。建议：加强传感器日常维护及调校。除上述问题外，所检项目合格。	  
---	---------------------	-------------	---	---