

序号	报告编号	发布日期	结论	影像资料
12	GX-B1328/26-P-26032	2026. 3. 6	本次共检绝缘手套 2只，2只绝缘手套合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月13日</p>
13	GX-B1328/26-P-26033	2026. 3. 6	本次共检绝缘靴2只， 2只绝缘靴合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月13日</p>

14	GX-B1495/26-P-26141~26144	2026. 3. 6	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	
15	GX-B1495/26-P-26145~26150	2026. 3. 6	本次共检高压开关设备6台，6台高压开关设备所检项目合格。	

16	GX-B1495/26-P-26151~26169	2026. 3. 6	本次共检高压开关设备19台，19台高压开关设备所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月11日</p>
17	GX-B1495/26-P-26170~26187	2026. 3. 6	本次共检高压开关设备18台，18台高压开关设备所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月13日</p>

18	GX-B1354/26-P-26001	2026. 3. 6	合格。	
19	GX-B1404/26-P-26001	2026. 3. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T14549-1993 《电能质量 公用电网谐波》要求。	

20	GX-B1404/26-P-26002	2026. 3. 6	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T14549-1993 《电能质量 公用电网谐波》要求。</p>	
21	GX-B1303/21-P-26001	2026. 3. 6	<p>综合判定：合格。</p>	

22	GX-B1303/21-P-26002	2026. 3. 6	综合判定：合格。	
23	GX-B1303/21-P-26003	2026. 3. 6	综合判定：合格。	

24	GX-B1303/21-P-26004	2026. 3. 6	综合判定：合格。	
25	GX-B1380/26-P-26001	2026. 3. 8	所检项目合格。	

26	GX-B1380/26-P-26002	2026. 3. 8	所检项目合格。	
27	GX-B1380/26-P-26003	2026. 3. 8	所检项目合格。	


28	GX-B1380/26-P-26004	2026. 3. 8	所检项目合格。	
29	GX-B1380/26-P-26005	2026. 3. 8	所检项目合格。	

30	GX-B1380/26-P-26006	2026. 3. 9	所检项目合格。	 <p>2026/2/23</p>
31	GX-B1380/26-P-26007	2026. 3. 9	所检项目合格。	 <p>2026/2/23</p>

32	GX-B1380/26-P-26008	2026. 3. 9	所检项目合格。		
33	GX-B1380/26-P-26009	2026. 3. 9	所检项目合格。		

34	GX-B1380/26-P-26010	2026. 3. 9	所检项目合格。			
35	GX-B1380/26-P-26011	2026. 3. 9	所检项目合格。			

36	GX-B1380/26-P-26012	2026. 3. 9	所检项目合格。		 <p>2026/2/25</p>
37	GX-B1382/26-P-26001	2026. 3. 7	综合判定:合格。		 <p>2026/3/1</p>

38	GX-B1382/26-P-26002	2026. 3. 7	综合判定:合格。	 <p>2026/3/1</p>
39	GX-B1382/26-P-26003	2026. 3. 7	综合判定:合格。	 <p>2026/2/23</p>

40	GX-B1382/26-P-26004	2026. 3. 7	综合判定:合格。	 A worker in a grey uniform and red helmet stands on a yellow safety railing in an industrial setting. A date stamp '2026/2/23' is visible in the bottom right corner of the photo.
41	GX-B1382/26-P-26005	2026. 3. 7	综合判定:合格。	 A worker in a grey uniform and red helmet stands on a yellow safety railing in an industrial setting. A date stamp '2026/2/23' is visible in the bottom right corner of the photo.

42	GX-B1382/26-P-26006	2026. 3. 7	综合判定:合格。			
43	GX-B1382/26-P-26007	2026. 3. 7	综合判定:合格。			

44	GX-B1305/21-P-26001	2026. 3. 7	综合判定：合格。	
45	GX-B1305/21-P-26002	2026. 3. 7	综合判定：合格。	

46	GX-B1304/26-P-26001	2026. 3. 6	综合判定:合格。	
47	GX-B1304/26-P-26002	2026. 3. 7	综合判定:合格。	

48	GX-B1598/24-P-26025	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为0.51%，小于5%为正常。	
49	GX-B1598/24-P-26026	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为0.78%，小于5%为正常。	

50	GX-B1598/24-P-26027	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。 。	
51	GX-B1598/24-P-26028	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为0.80%，小于5%为正常。 。	

52	GX-B1598/24-P-26029	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为1.54%，小于5%为正常。 。	
53	GX-B1598/24-P-26030	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为1.44%，小于5%为正常。 。	



54	GX-B1598/24-P-26031	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为1.07%，小于5%为正常。 。	
55	GX-B1598/24-P-26032	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为0.93%，小于5%为正常。 。	

56	GX-B1598/24-P-26033	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为1.02%，小于5%为正常。 。	 <p>2026 02 28</p>
57	GX-B1598/24-P-26034	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为0.91%，小于5%为正常。 。	 <p>2026 02 28</p>

58	GX-B1598/24-P-26035	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为2.80%，小于5%为正常	
59	GX-B1598/24-P-26036	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为2.79%，小于5%为正常。 。	

60	GX-B1598/24-P-26007	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.78%，小于5%为正常。 。	
61	GX-B1598/24-P-26008	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.93%，小于5%为正常。 。	

62	GX-B1598/24-P-26009	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。 。	
63	GX-B1598/24-P-26010	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。 。	

64	GX-B1598/24-P-26011	2026. 3. 6	实测钢丝绳有效截面积损失百分比最大为1.50%，小于5%为正常。 。	
65	GX-B1598/24-P-26012	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为1.45%，小于5%为正常。 。	

66	GX-B1598/24-P-26013	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为4.02%，小于5%为正常。	 A photograph showing a worker in a green jacket, red helmet, and blue gloves working on a steel structure. The worker is holding a tool and appears to be inspecting or working on a component. The background shows a complex network of steel beams and pipes. A timestamp '2026 03 02' is visible in the bottom right corner of the image.
67	GX-B1598/24-P-26014	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为4.02%，小于5%为正常。 。	 A photograph showing a worker in a green jacket, red helmet, and blue gloves working on a steel structure. The worker is holding a tool and appears to be inspecting or working on a component. The background shows a complex network of steel beams and pipes. A timestamp '2026 03 02' is visible in the bottom right corner of the image.

68	GX-B1598/24-P-26015	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为2.98%，小于5%为正常。 。	
69	GX-B1598/24-P-26016	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为3.26%，小于5%为正常。 。	

70	GX-B1598/24-P-26017	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为2.91%，小于5%为正常。 。	 <p>2026 03 01</p>
71	GX-B1598/24-P-26018	2026. 3. 9	实测钢丝绳有效截面积损失百分比最大为3.98%，小于5%为正常。 。	 <p>2026 03 01</p>

72	GX-B1310/21-P- 26022	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月23日</p>
73	GX-B1310/21-P- 26023	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月23日</p>

74	GX-B1310/21-P- 26024	2026. 3. 10	符合标准要求。	 <p>招远市姜家鑫金矿有限公司 2026年2月23日</p>
75	GX-B1310/21-P- 26025	2026. 3. 10	符合标准要求。	 <p>招远市姜家鑫金矿有限公司 2026年2月25日</p>

76	GX-B1310/21-P- 26026	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月25日</p>
77	GX-B1310/21-P- 26027	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月25日</p>

78	GX-B1310/21-P- 26028	2026. 3. 10	符合标准要求。	
79	GX-B1310/21-P- 26029	2026. 3. 10	符合标准要求。	

80	GX-B1310/21-P- 26030	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月24日</p>
81	GX-B1310/21-P- 26031	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月24日</p>

82	GX-B1310/21-P- 26032	2026. 3. 10	符合标准要求。	
83	GX-B1427/21-P-26001	2026. 3. 10	符合标准要求。	

84	GX-B1427/21-P-26002	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月25日</p>
85	GX-B1427/21-P-26003	2026. 3. 10	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月24日</p>

86	GX-B1310/21-P- 26033	2026. 3. 11	符合标准要求。	 <p>招远市姜家密金矿有限公司 2026年2月23日</p>
87	GX-B1310/21-P- 26034	2026. 3. 11	符合标准要求。	 <p>招远市姜家密金矿有限公司 2026年2月23日</p>

88	GX-B1310/21-P- 26035	2026. 3. 11	符合标准要求。	 <p>招远市姜家鑫金矿有限公司 2026年2月23日</p>
89	GX-B1427/21-P- 26004	2026. 3. 11	符合标准要求。	 <p>招远市姜家鑫金矿有限公司 2026年2月23日</p>

90	GX-B1598/24-P-26019	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为1.31%，小于5%为正常。	
91	GX-B1598/24-P-26020	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为1.28%，小于5%为正常。	

92	GX-B1598/24-P-26021	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为1.68%，小于5%为正常。	 A worker in a blue uniform and red helmet is performing maintenance on a steel structure. The worker is standing on a platform and is holding a tool. The background shows a complex steel framework. A timestamp '2026 03 02' is visible in the bottom right corner of the image.
93	GX-B1598/24-P-26022	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常。	 A worker in a grey uniform and red helmet is performing maintenance on a steel structure. The worker is standing on a platform and is holding a tool. The background shows a complex steel framework. A timestamp '2026 03 02' is visible in the bottom right corner of the image.

94	GX-B1598/24-P-26023	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为2.13%，小于5%为正常。	
95	GX-B1598/24-P-26024	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为2.10%，小于5%为正常。	

96	GX-B1310/21-P-26036	2026. 3. 11	符合标准要求。	 <p>2026 02 22</p>
97	GX-B1536/26-P-26001	2026. 3. 11	综合判定:合格。	 <p>2026 02 22</p>

98	GX-B1310/21-P- 26037	2026. 3. 12	符合标准要求。	
99	GX-B1310/21-P- 26038	2026. 3. 12	符合标准要求。	

100	GX-B1310/21-P- 26039	2026. 3. 12	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月23日</p>
101	GX-B1427/21-P- 26005	2026. 3. 12	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月23日</p>

102	GX-B1310/21-P- 26040	2026. 3. 12	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月24日</p>
103	GX-B1310/21-P- 26041	2026. 3. 12	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月24日</p>



104	GX-B1310/21-P- 26042	2026. 3. 12	符合标准要求。	 <p>招远市姜家金矿有限公司 2026年2月24日</p>
105	GX-B1427/21-P- 26006	2026. 3. 12	符合标准要求。	 <p>招远市姜家金矿有限公司 2026年2月24日</p>

106	GX-B1310/21-P- 26043	2026. 3. 12	符合标准要求。	
107	GX-B1310/21-P- 26044	2026. 3. 12	符合标准要求。	

108	GX-B1310/21-P- 26045	2026. 3. 12	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月24日</p>
109	GX-B1427/21-P- 26007	2026. 3. 12	符合标准要求。	 <p>招远市姜家窑金矿有限公司 2026年2月24日</p>

110	GX-B1310/21-P- 26046	2026. 3. 12	符合标准要求。		 <p>招远市姜家窑金矿有限公司 2026年2月25日</p>
111	GX-B1310/21-P- 26047	2026. 3. 12	符合标准要求。		 <p>招远市姜家窑金矿有限公司 2026年2月25日</p>

112	GX-B1310/21-P- 26048	2026. 3. 12	符合标准要求。	 <p>招远市姜家金矿有限公司 2026年2月25日</p>
113	GX-B1427/21-P- 26008	2026. 3. 12	符合标准要求。	 <p>招远市姜家金矿有限公司 2026年2月25日</p>

114	GX-B1323/26-P-26012~26013	2026. 3. 16	所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月10日</p>
115	GX-B1323/26-P-26014~26015	2026. 3. 16	所检项目合格。	 <p>贵州金沙龙凤煤业有限公司 2026年2月10日</p>