





序号	报告编号	发布日期	结论	影像资料
348	GX-B1310/21-2-26150	2026. 3. 28	符合标准要求。	 A photograph showing a worker in a red hard hat and safety harness operating a large industrial machine. The worker is positioned on a platform, and the machine has a large, dark, cylindrical component. A timestamp '2026/03/26' is visible in the bottom right corner of the image.
349	GX-B1310/21-2-26133	2026. 3. 28	符合标准要求。	 A photograph showing two workers in red hard hats standing next to a large industrial machine. The machine has a large, dark, cylindrical component. One worker is in the foreground, and another is slightly behind. A timestamp '2026/03/12' is visible in the bottom right corner of the image.

350	GX-B1310/21-2-26134	2026. 3. 28	符合标准要求。	 A close-up photograph of a worker wearing a red hard hat and safety glasses, working on a blue industrial structure. The worker is holding a device, possibly a tablet or a specialized tool. The date '2026/03/28' is visible in the bottom right corner of the image.
351	GX-B1310/21-2-26135	2026. 3. 28	符合标准要求。	 A photograph showing a worker in a red hard hat kneeling on the ground next to a complex industrial structure with multiple vertical pipes and valves. The worker is wearing a dark jacket and safety harness. The date '2026/03/28' is visible in the bottom right corner of the image.

352	GX-B1309/26-2-26017	2026. 3. 28	所检项目合格。	
353	GX-B1500/26-2-26062	2026. 3. 28	综合判定：合格。	

354	GX-B1500/26-2-26063	2026. 3. 28	综合判定：合格。	
355	GX-B1500/26-2-26064	2026. 3. 28	综合判定：合格。	

356	GX-B1500/26-2-26065	2026. 3. 28	综合判定：合格。	
357	GX-B1500/26-2-26066	2026. 3. 28	综合判定：合格。	

358	GX-B1598/24-2-26134	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为0.96%，小于5%为正常。	
359	GX-B1598/24-2-26135	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为0.85%，小于5%为正常。	

360	GX-B1598/24-2-26136	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常。 。	 A photograph showing a worker in a blue uniform and cap inspecting a steel cable on a metal structure. The date '2026.3.6' is visible in the bottom right corner of the image.
361	GX-B1598/24-2-26137	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为1.49%，小于5%为正常。 。	 A photograph showing two workers in blue uniforms inspecting a steel cable on a metal structure. One worker is wearing a red hard hat. The date '2026.3.6' is visible in the bottom right corner of the image.

362	GX-B1598/24-2-26138	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。 。	 <p>2026.3.6</p>
363	GX-B1451/26-2-26221~26231	2026. 3. 27	本次共检高压开关柜11台，11台高压开关柜所检项目合格。	 <p>2026/03/10</p>

364	GX-B1451/26-2-26232~26235	2026. 3. 27	本次共检高压开关柜4台, 4台高压开关柜所检项目合格。	
365	GX-B1451/26-2-26236~26243	2026. 3. 27	本次共检高压开关柜8台, 8台高压开关柜所检项目合格。	

366	GX-B1303/26-2-26001	2026/3/21	综合判定：合格。	
367	<u>GX-B1310/21-2-26141</u>	2026. 3. 26	符合标准要求。	

368	GX-B1310/21-2-26142	2026. 3. 26	符合标准要求。	
369	GX-B1310/21-2-26143	2026. 3. 26	符合标准要求。	

370	GX-B1310/21-2-26144	2026. 3. 26	符合标准要求。			
371	GX-B1310/21-2-26145	2026. 3. 26	符合标准要求。			

372	GX-B1310/21-2-26146	2026. 3. 26	无缺陷迹痕显示。			
373	GX-B1310/21-2-26147	2026. 3. 26	无缺陷迹痕显示。			

374	GX-B1310/21-2-26148	2026. 3. 26	无缺陷迹痕显示。	
375	<u>GX-B1329/26-2-26022~26038</u>	2026. 3. 30	本次共检氧化锌避雷器17组，17组所检项目合格。	

376	GX-B1329/26-2-26064~26071	2026. 3. 30	本次共检氧化锌避雷器8组，8组所检项目合格。	 <p>2026/02/28</p>
377	GX-B1322/26-2-26220~26223	2026. 3. 30	本次共检验电力电缆4条，4条所检项目合格。	 <p>2026/02/28</p>

378	GX-B1329/26-2-26047~26063	2026. 3. 30	本次共检氧化锌避雷器17组，17组所检项目合格。	 <p>2026/02/27</p>
379	GX-B1350/21-2-26010	2026. 3. 30	本次共检接地装置5处，5处接地装置所检项目合格。	 <p>2026.02.28</p>

380	GX-B1451/26-2-26576~26578	2026. 3. 30	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	 <p>2026/02/27</p>
381	GX-B1451/26-2-26129~26147	2026. 3. 30	本次共检高压开关柜19台，19台高压开关柜所检项目合格。	 <p>2026/02/28</p>


382	GX-B1451/26-2-26148~26169	2026. 3. 30	本次共检高压开关柜22台，22台高压开关柜所检项目合格。		
383	GX-B1329/26-2-26072~26077	2026/3/31	本次共检氧化锌避雷器6组，6组所检项目合格。		

384	GX-B1329/26-2-26078~26083	2026/3/31	本次共检氧化锌避雷器6组，6组所检项目合格。		 <p>03月 08 2026.03.08 星期日 福建省龙岩市连城县新好乡 居巖市(大源村)地质队</p>	
385	GX-B1350/21-2-26018	2026/3/31	本次共检接地装置4处，4处接地装置所检项目合格。		 <p>03月 06 2026.03.06 星期五</p>	

386	GX-B1350/21-2-26019	2026/3/31	本次共检接地装置 4处，4处接地装置所 检项目合格。			
387	GX-B1350/21-2-26020	2026/3/31	本次共检接地装置 4处，4处接地装置所 检项目合格。			

388	GX-B1451/26-2-26507~26524	2026/3/31	本次共检高压开关柜18台，18台高压开关柜所检项目合格。			
389	GX-B1451/26-2-26525~26530	2026/3/31	本次共检高压开关柜6台，6台高压开关柜所检项目合格。			

390	<u>GX-B1309/26-2-26012</u>	2026. 3. 30	所检项目合格。			
391	GX-B1500/26-2-26047	2026. 3. 30	综合判定：合格。			

392	GX-B1500/26-2-26048	2026. 3. 30	综合判定：合格。		
393	GX-B1500/26-2-26049	2026. 3. 30	综合判定：合格。		

394	GX-B1309/26-2-26013	2026. 3. 30	所检项目合格。		 <p>2026/03/05</p>
395	GX-B1500/26-2-26050	2026. 3. 30	综合判定：合格。		 <p>2026/03/05</p>

396	GX-B1500/26-2-26051	2026. 3. 30	综合判定：合格。			
397	GX-B1500/26-2-26052	2026. 3. 30	综合判定：合格。			

398	GX-B1309/26-2-26014	2026. 3. 30	所检项目合格。			
399	GX-B1500/26-2-26053	2026. 3. 30	综合判定：合格。			

400	GX-B1500/26-2-26054	2026. 3. 30	综合判定：合格。			
401	GX-B1500/26-2-26055	2026. 3. 30	综合判定：合格。			

402	GX-B1322/26-2-26280~26283	2026. 3. 31	本次共检验电力电缆4条，4条所检项目合格。	
403	GX-B1329/26-2-26122~26123	2026. 3. 31	本次共检氧化锌避雷器2组，2组所检项目合格。	

404	<u>GX-B1313/26-2-26141~26148</u>	2026. 3. 30	本次共检电力变压器8台，8台所检项目合格。 。	
405	GX-B1313/26-2-26149~26153	2026. 3. 30	本次共检电力变压器5台，5台所检项目合格。 。	

406	GX-B1313/26-2-26154~26158	2026. 3. 30	本次共检电力变压器5台，5台所检项目合格。 。	
407	GX-B1313/26-2-26159~26160	2026. 3. 30	本次共检电力变压器2台，2台所检项目合格。 。	

408	GX-B1313/26-2-26162~26163	2026. 3. 30	本次共检电力变压器2台，2台所检项目合格。	
409	GX-B1313/26-2-26161	2026. 3. 30	所检项目合格。	

410	GX-B1313/26-2-26164~26165	2026. 3. 30	本次共检电力变压器2台，2台所检项目合格。 。	 <p>2026/3/6</p>
411	GX-B1313/26-2-26052	2026. 3. 30	所检项目合格。	 <p>2026/02/25</p>