


序号	报告编号	发布日期	结论	影像资料
106	GX-B1329/26-2-26084~26088	2026. 4. 14	本次共检氧化锌避雷器5组，5组所检项目合格。	
107	GX-B1350/21-2-26027	2026. 4. 14	本次共检接地装置5处，5处接地装置所检项目合格。	

108	<u>GX-B1310/21-2-26130</u>	2026. 4. 10	符合标准要求。	
109	GX-B1310/21-2-26131	2026. 4. 10	符合标准要求。	

110	<u>GX-B1611/23-2-26001</u>	2026. 4. 14	所检项目合格。	
111	GX-B1539/22-2-26004	2026. 4. 15	除上述问题外，其余所检项目合格。	

112	GX-B1539/22-2-26005	2026. 4. 15	除上述问题外，其余所检项目合格。			
113	GX-B1539/22-2-26006	2026. 4. 15	除上述问题外，其余所检项目合格。			

114	GX-B1539/22-2-26007	2026. 4. 15	除上述问题外，其余所检项目合格。	 <p>2026/03/28</p>
115	GX-B1539/22-2-26008	2026. 4. 15	除上述问题外，其余所检项目合格。	 <p>2026/03/28</p>

116	GX-B1451/26-2-26686~26689	2026. 4. 15	本次共检高压交流断路器4台，4台高压交流断路器所检项目合格。	
117	GX-B1451/26-2-26695~26698	2026. 4. 15	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	

118	GX-B1539/22-2-26013	2026. 4. 14	除无辅助制动系统外，其余所检项目合格。	 <p>2026/04/02</p>
119	GX-B1322/26-2-26290~26302	2026. 4. 15	本次共检验电力电缆13条，13条所检项目合格。	 <p>2026/03/13</p>

120	GX-B1451/26-2-26690~26693	2026. 4. 15	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	
121	GX-B1310/21-2-26155	2026. 4. 20	符合标准要求。	

122	GX-B1310/21-2-26156	2026. 4. 20	符合标准要求。		
123	GX-B1322/26-2-26251~26252	2026. 4. 15	本次共检验电力电缆2条，2条所检项目合格。		

124	GX-B1322/26-2-26253~26256	2026. 4. 15	本次共检验电力电缆 4条，4条所检项目合格。	
125	GX-B1322/26-2-26257~26268	2026. 4. 15	本次共检验电力电缆 12条，12条所检项目合格。	

126	GX-B1322/26-2-26269~26274	2026. 4. 15	本次共检验电力电缆6条，6条所检项目合格。	 <p>2026.3.22</p>
127	GX-B1322/26-2-26275~26279	2026. 4. 15	本次共检验电力电缆5条，5条所检项目合格。	 <p>2026.3.24</p>

128	GX-B1451/26-2-26580~26582	2026. 4. 15	本次共检高压开关柜3台，3台高压开关柜所检项目合格。		
129	GX-B1451/26-2-26583~26588	2026. 4. 15	本次共检高压防爆开关6台，6台高压防爆开关所检项目合格。		

130	GX-B1451/26-2-26589~26598	2026. 4. 15	本次共检高压开关柜10台，10台高压开关柜所检项目合格。	
131	GX-B1451/26-2-26599~26603	2026. 4. 15	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	

132	GX-B1451/26-2-26604~26619	2026. 4. 15	本次共检高压开关柜16台，16台高压开关柜所检项目合格。	
133	GX-B1451/26-2-26620~26627	2026. 4. 15	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	

134	GX-B1451/26-2-26628~26634	2026. 4. 15	本次共检高压防爆开关7台，7台高压防爆开关所检项目合格。		 <p>2026.3.22</p>	
135	GX-B1451/26-2-26635~26636	2026. 4. 15	本次共检高压防爆开关2台，2台高压防爆开关所检项目合格。		 <p>2026.3.23</p>	


136	GX-B1451/26-2-26637~26639	2026. 4. 15	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	
137	GX-B1451/26-2-26640	2026. 4. 15	所检项目合格。	

138	GX-B1451/26-2-26668~26681	2026. 4. 17	本次共检高压开关柜14台，14台高压开关柜所检项目合格。			
139	GX-B1451/26-2-26682~26685	2026. 4. 17	本次共检高压开关柜4台，4台高压开关柜所检项目合格。			

140	GX-B1350/21-2-26026	2026. 4. 17	所检项目合格。	
141	GX-B1598/24-2-26143	2026. 4. 15	实测钢丝绳有效截面积损失百分比最大为2.88%，小于5%为正常。	

142	GX-B1598/24-2-26144	2026. 4. 15	实测钢丝绳有效截面积损失百分比最大为0.44%，小于5%为正常。		 <p>2026/04/06</p>
143	GX-B1598/24-2-26145	2026. 4. 15	实测钢丝绳有效截面积损失百分比最大为0.53%，小于5%为正常。		 <p>2026/04/07</p>

144	GX-B1598/24-2-26146	2026. 4. 15	实测钢丝绳有效截面积损失百分比最大为3.39%，小于5%为正常。	 <p>2026/04/08</p>
145	GX-B1598/24-2-26147	2026. 4. 15	实测钢丝绳有效截面积损失百分比最大为0.74%，小于5%为正常。	 <p>2026/04/09</p>

146	GX-B1598/24-2-26148	2026. 4. 15	实测钢丝绳有效截面积损失百分比最大为1.87%，小于5%为正常。 。	 A photograph showing two workers in a tunnel. They are wearing dark work clothes with reflective stripes and red hard hats. One worker is standing on the left, and the other is on the right, reaching up towards a cable or structure. The tunnel has concrete walls and a floor with tracks. A date stamp '2026/04/10' is visible in the bottom right corner of the photo. 2026/04/10
-----	---------------------	-------------	---------------------------------------	---