

序号	报告编号	发布日期	结论	影像资料
12	GX-B1598/24-6-26001	2025/2/11	实测钢丝绳有效截面积损失百分比最大为2.41%，小于5%为正常。 。	
13	GX-B1598/24-6-26002	2025/2/11	实测钢丝绳有效截面积损失百分比最大为2.70%，小于5%为正常。 。	

14	GX-B1598/24-6-26003	2025/2/11	实测钢丝绳有效截面积损失百分比最大为2.60%，小于5%为正常。 。	
15	GX-B1598/24-6-26004	2025/2/11	实测钢丝绳有效截面积损失百分比最大为0.86%，小于5%为正常。 。	

16	GX-B1598/24-6-26005	2025/2/11	实测钢丝绳有效截面积损失百分比最大为0.89%，小于5%为正常。 。		
17	GX-B1598/24-6-26006	2025/2/11	实测钢丝绳有效截面积损失百分比最大为0.90%，小于5%为正常。 。		

18	GX-B1598/24-6-26007	2025/2/11	实测钢丝绳有效截面积损失百分比最大为0.81%，小于5%为正常。 。		 <p>2026 01 29</p>
19	GX-B1598/24-6-26008	2025/2/11	实测钢丝绳有效截面积损失百分比最大为0.90%，小于5%为正常。 。		 <p>2026 01 29</p>



20	GX-B1598/24-6-26009	2025/2/11	实测钢丝绳有效截面积损失百分比最大为0.94%，小于5%为正常。			
21	GX-B1598/24-6-26001	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为2.41%，小于5%为正常。			



22	GX-B1598/24-6-26002	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为2.70%，小于5%为正常。	
23	GX-B1598/24-6-26003	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为2.60%，小于5%为正常。	

24	GX-B1598/24-6-26004	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为0.86%，小于5%为正常。	
25	GX-B1598/24-6-26005	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为0.89%，小于5%为正常。	

26	GX-B1598/24-6-26006	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为0.90%，小于5%为正常。		
27	GX-B1598/24-6-26007	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为0.81%，小于5%为正常。		

28	GX-B1598/24-6-26008	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为0.90%，小于5%为正常。		
29	GX-B1598/24-6-26009	2026年2月11日	实测钢丝绳有效截面积损失百分比最大为0.94%，小于5%为正常。		



30	GX-B1304/26-6-26003	2026年2月27日	综合判定合格	
31	GX-B1305/26-6-26003	2026年2月27日	综合判定合格	

32	GX-B1451/25-6-26020~26032	2026/2/25	本次共检高压开关柜13台, 13台高压开关柜所检项目合格。	
33	GX-B1350/21-6-26001	2026/2/25	本次共检接地装置1处, 1处接地装置所检项目合格。	

34	GX-B1313/21-6-26011~26012	2026/2/25	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A photograph showing a worker in a blue uniform and orange helmet working on a piece of electrical equipment. The worker is kneeling and looking towards the camera. The equipment is a large metal cabinet with various components visible. The date '2026 2 2' is visible in the bottom right corner of the photo.
35	GX-B1451/25-6-26020~26032	2026/2/25	本次共检高压开关柜13台，13台高压开关柜所检项目合格。	#REF!

36	GX-B1350/21-6-26001	2026/2/25	本次共检接地装置1处，1处接地装置所检项目合格。	#REF!
37	GX-B1313/21-6-26011~26012	2026/2/25	本次共检电力变压器2台，2台电力变压器所检项目合格。	#REF!

38	GX-B1304/26-6-26004	2026. 2. 27	综合判定：合格。	 A photograph showing two workers in safety gear (hard hats and jackets) inspecting a large, blue industrial machine. One worker is wearing a jacket with the text '中检公信' (China Inspection and Certification) on the back. The date '2026 02 12' is visible in the bottom right corner of the image.
39	GX-B1304/26-6-26005	2026. 2. 27	综合判定：合格。	 A photograph showing a worker in safety gear (hard hat and blue uniform) inspecting a large, blue industrial machine. The date '2026 02 12' is visible in the bottom right corner of the image.

40	GX-B1305/21-6-26004	2026. 2. 27	综合判定：合格。	
41	GX-B1305/21-6-26005	2026. 2. 27	综合判定：合格。	

42	GX-B1451/25-6-26020~26032	2026/2/25	本次共检高压开关柜13台, 13台高压开关柜所检项目合格。	
43	GX-B1350/21-6-26001	2026/2/25	本次共检接地装置1处, 1处接地装置所检项目合格。	

44	GX-B1313/21-6-26011~26012	2026/2/25	本次共检电力变压器2台，2台电力变压器所检项目合格。	
45	GX-B1322/26-6-26001~26005	2026/2/25	本次共检电力电缆5条，5条电力电缆绝缘电阻测定合格，直流耐压试验无击穿。	

46	GX-B1322/26-6-26006	2026/2/25	本次共检电力电缆1条，1条电力电缆绝缘电阻测定合格，直流耐压试验无击穿。	
47	GX-B1322/26-6-26007	2026/2/25	本次共检电力电缆1条，1条电力电缆绝缘电阻测定合格，直流耐压试验无击穿。	