


序号	报告编号	发布日期	结论	影像资料
22	GX-B1611/23-6-25007	2025年8月12日	所检项目合格。	 A photograph showing two inspectors in white uniforms and red hard hats inspecting a yellow truck. One inspector is pointing at a document while the other looks on. The truck is parked under a covered area. A timestamp '2025 07 29' is visible in the bottom right corner of the image.
23	GX-B1611/23-6-25008	2025年8月12日	所检项目合格。	 A photograph showing two inspectors in white uniforms and red hard hats inspecting a yellow forklift. One inspector is pointing at a document while the other looks on. The forklift is parked under a covered area. A timestamp '2025 07 29' is visible in the bottom right corner of the image.

24	GX-B1611/23-6-25006	2025年8月12日	所检项目合格。	
25	GX-B1328/20-6-25173	2025年8月12日	本次共检绝缘手套460只, 460只绝缘手套合格。	
26	GX-B1598/24-6-25115	2025年8月8日	实测钢丝绳有效截面积损失百分比最大为1.40%, 小于5%为正常。	

27	GX-B1598/24-6-25116	2025年8月8日	<p>实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。</p>	
28	GX-B1598/24-6-25117	2025年8月8日	<p>实测钢丝绳有效截面积损失百分比最大为1.21%，小于5%为正常。</p>	
29	GX-B1598/24-6-25118	2025年8月8日	<p>实测钢丝绳有效截面积损失百分比最大为1.46%，小于5%为正常。</p>	

30	GX-B1598/24-6-25119	2025年8月8日	实测钢丝绳有效截面损失百分比最大为1.79%，小于5%为正常。	
31	GX-B1598/24-6-25120	2025年8月8日	实测钢丝绳有效截面损失百分比最大为1.44%，小于5%为正常。	
32	GX-B1310/21-6-25215	2025年8月13日	符合标准要求	

33	GX-B1310/21-6-25216	2025年8月13日	符合标准要求	
34	GX-B1310/21-6-25217	2025年8月13日	符合标准要求	
35	GX-B1310/21-6-25218	2025年8月13日	符合标准要求	

36	GX-B1310/21-6-25219	2025年8月13日	符合标准要求	
37	GX-B1310/21-6-25220	2025年8月13日	符合标准要求	
38	GX-B1310/21-6-25221	2025年8月13日	符合标准要求	

39	GX-B1539/22-6-25004	2025年8月13日	所检项目合格。	
40	GX-B1539/22-6-25005	2025年8月13日	所检项目合格。	
41	GX-B1539/22-6-25006	2025年8月13日	所检项目合格。	

42	GX-B1539/22-6-25007	2025年8月13日	所检项目合格。	
43	GX-B1539/22-6-25008	2025年8月13日	所检项目合格。	
44	GX-B1539/22-6-25009	2025年8月13日	所检项目合格。	

45	GX-B1539/22-6-25010	2025年8月13日	所检项目合格。	
46	GX-B1539/22-6-25011	2025年8月13日	所检项目合格。	
47	GX-B1539/22-6-25012	2025年8月13日	所检项目合格。	

48	GX-B1539/22-6-25013	2025年8月13日	所检项目合格。	
49	GX-B1539/22-6-25014	2025年8月13日	所检项目合格。	
50	GX-B1539/22-6-25015	2025年8月13日	所检项目合格。	

51	GX-B1539/22-6-25016	2025年8月13日	所检项目合格。	 <p>2025.07.30</p>
52	GX-B1539/22-6-25017	2025年8月13日	所检项目合格。	 <p>2025.07.30</p>
53	GX-B1313/21-6-25310~25311	2025年8月21日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2025.08.16</p>

54	GX-B1313/21-6-25312~25313	2025年8月21日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
55	GX-B1322/21-6-25409~25412	2025年8月21日	本次共检电力电缆4条，4条电力电缆所检项目合格。	
56	GX-B1322/21-6-25413~25416	2025年8月21日	本次共检电力电缆4条，4条电力电缆所检项目合格。	

57	GX-B1350/21-6-25053	2025年8月21日	本次共检测接地装置2处，2处接地装置所检项目合格。	
58	GX-B1350/21-6-25054	2025年8月21日	本次共检测接地装置2处，2处接地装置所检项目合格。	
59	GX-B1428/21-6-25053	2025. 8. 21	无缺陷痕迹显示	

60	GX-B1428/21-6-25054	2025. 8. 21	无缺陷痕迹显示	
61	GX-B1451/20-6-25939~25940	2025. 8. 22	所检项目合格。	
62	GX-B1451/20-6-25941~25948	2025. 8. 22	所检项目合格。	

63	GX-B1309/21-6-25034	2025. 8. 22	所检项目合格。	
64	GX-B1309/21-6-25035	2025. 8. 22	所检项目合格。	
65	GX-B1500/21-6-25145	2025. 8. 22	综合判定：合格。	

66	GX-B1500/21-6-25146	2025. 8. 22	综合判定：合格。	
67	GX-B1500/21-6-25147	2025. 8. 22	综合判定：合格。	
68	GX-B1500/21-6-25148	2025. 8. 22	综合判定：合格。	

69	GX-B1500/21-6-25149	2025. 8. 22	综合判定：合格。	
70	GX-B1500/21-6-25150	2025. 8. 22	综合判定：合格。	
71	GX-B1328/20-6-25174	2025年8月13日	本次共检全橡胶绝缘胶靴 230只，230只全橡胶绝缘胶靴合格。	

72	GX-B1451/20-6-25936~25938	2025年8月13日	本次共检高压开关柜3台,3台高压开关柜所检项目合格。	
73	GX-B1612/23-6-25025	2025年8月15日	所检项目合格	