

序号	报告编号	发布日期	结论	影像资料
1	GX-B1383/21-1-22005	2022/4/2	合格	
2	GX-B1383/21-1-22006	2022/4/2	合格	

3	GX-B1423/20-1-22014	2022/4/8	合格	
4	GX-B1423/20-1-22015	2022/4/8	合格	
5	GX-B1423/20-1-22016	2022/4/8	合格	

6	GX-B1423/20-1-22017	2022/4/8	合格	
7	GX-B1423/20-1-22018	2022/4/8	合格	
8	GX-B1423/20-1-22019	2022/4/8	合格	

9	GX-B1423/20-1-22020	2022/4/8	合格	
10	GX-B1423/20-1-22021	2022/4/8	合格	
11	GX-B1423/20-1-22022	2022/4/8	合格	

12	GX-B1423/20-1-22023	2022/4/8	合格	
13	GX-B1423/20-1-22024	2022/4/8	合格	
14	GX-B1423/20-1-22025	2022/4/8	合格	

15	GX-B1423/20-1-22026	2022/4/8	合格	
16	GX-B1423/20-1-22027	2022/4/8	合格	
17	GX-B1423/20-1-22028	2022/4/8	合格	

18	GX-B1423/20-1-22029	2022/4/8	合格	 A yellow dump truck with the number 801 on its side. Two workers in safety gear stand in front of it. A red date stamp '2022/03/14' is visible in the bottom right corner of the photo.	
19	GX-B1423/20-1-22030	2022/4/8	合格	 A yellow dump truck with the number 802 on its side. Two workers in safety gear stand in front of it. A red date stamp '2022/03/14' is visible in the bottom right corner of the photo.	
20	GX-B1423/20-1-22031	2022/4/8	合格	 A yellow dump truck with the number 803 on its side. Two workers in safety gear stand in front of it. A red date stamp '2022/03/14' is visible in the bottom right corner of the photo.	

21	GX-B1423/20-1-22032	2022/4/8	合格		
22	GX-B1423/20-1-22033	2022/4/8	合格		
23	GX-B1423/20-1-22034	2022/4/8	合格		

24	GX-B1423/20-1-22035	2022/4/8	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. A red date stamp '2022/03/14' is visible in the bottom right corner of the photo.
25	GX-B1423/20-1-22036	2022/4/8	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. A red date stamp '2022/03/14' is visible in the bottom right corner of the photo.
26	GX-B1423/20-1-22037	2022/4/8	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. A red date stamp '2022/03/14' is visible in the bottom right corner of the photo.

27	GX-B1423/20-1-22038	2022/4/8	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear stand in front of the truck. The truck has the number '811' on its side. A red timestamp '2022/03/14' is visible in the bottom right corner of the photo.	
28	GX-B1423/20-1-22039	2022/4/8	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear stand in front of the truck. The truck has the number '812' and the characters '南矿' (Nan Mine) on its side. A red timestamp '2022/03/14' is visible in the bottom right corner of the photo.	
29	GX-B1423/20-1-22040	2022/4/8	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear stand in front of the truck. The truck has the number '813' and the characters '南矿' (Nan Mine) on its side. A red timestamp '2022/03/14' is visible in the bottom right corner of the photo.	

