

序号	报告编号	发布日期	结论	影像资料
208	GX-B1367/20-A-22067	2022/6/23	合格	

序号	报告编号	发布日期	结论	影像资料
209	GX-B1367/20-A-22064	2022/6/23	合格	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1367/20-A-22065	2022/6/23	合格	 <p>The photograph captures two individuals in grey work uniforms performing a technical task. They are positioned at a wooden table where various tools and equipment are laid out. One person is actively using a multimeter on a component. The setting appears to be an indoor workspace with a window in the background. A date stamp '2022/06/06' is overlaid on the bottom right of the image. The back of the person in the foreground has a logo and the text '中检公' (China Inspection Company) visible.</p>

序号	报告编号	发布日期	结论	影像资料
301	GX-B1363/20-A-22262	2022/6/21	合格	

序号	报告编号	发布日期	结论	影像资料
302	GX-B1363/20-A-22257	2022/6/23	合格	

序号	报告编号	发布日期	结论	影像资料
303	GX-B1363/20-A-22256	2022/6/23	合格	

序号	报告编号	发布日期	结论	影像资料
304	GX-B1363/20-A-22255	2022/6/23	合格	

序号	报告编号	发布日期	结论	影像资料
305	GX-B1364/20-A-22469	2022/6/23	合格	

序号	报告编号	发布日期	结论	影像资料
306	GX-B1363/20-A-22218	2022/6/15	合格	

序号	报告编号	发布日期	结论	影像资料
307	GX-B1366/20-A-22065	2022/6/24	合格	

序号	报告编号	发布日期	结论	影像资料
308	GX-B1363/22-A-22264	2022/6/28	合格	 

序号	报告编号	发布日期	结论	影像资料
309	GX-B1363/22-A-22258	2022/6/28	合格	 

序号	报告编号	发布日期	结论	影像资料
310	GX-B1363/22-A-22259	2022/6/28	合格	 

序号	报告编号	发布日期	结论	影像资料
311	GX-B1363/22-A-22267	2022/6/28	合格	 <p>The '影像资料' (Image Material) column contains two photographs. The top photograph shows two individuals, a woman and a man, both wearing light-colored lab coats with a logo on the back. They are standing at a table, looking at a scale or piece of equipment. A clock is visible on the wall behind them. The date '2022/06/23' is printed in the bottom right corner of the photo. The bottom photograph shows the same two individuals in lab coats standing next to a large, industrial-looking piece of equipment with a glass door. A green trash bin is visible to the left. A window is in the background. The date '2022/06/22' is printed in the bottom right corner of the photo.</p>