



序号	报告编号	发布日期	结论	影像资料
220	GX-B1423/20-Y-234775	2023年9月19日	综合判定：合格	
221	GX-B1423/20-Y-234776	2023年9月19日	综合判定：合格	


222	GX-B1423/20-Y-234777	2023年9月19日	综合判定：合格	
223	GX-B1423/20-Y-234778	2023年9月19日	综合判定：合格	

224	GX-B1423/20-Y-234779	2023年9月19日	综合判定：合格	
225	GX-B1423/20-Y-234780	2023年9月19日	综合判定：合格	

226	GX-B1423/20-Y-234781	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people wearing hard hats and work clothes are standing near the front of the truck. The truck has a large dump body and multiple axles.
227	GX-B1423/20-Y-234782	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people wearing hard hats and work clothes are standing near the front of the truck. The truck has a large dump body and multiple axles.

228	GX-B1423/20-Y-234783	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in blue and white uniforms are standing near the front of the truck. The truck has a large dump body and multiple axles.
229	GX-B1423/20-Y-234784	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in blue and white uniforms are standing near the front of the truck. The truck has a large dump body and multiple axles.

230	GX-B1423/20-Y-234785	2023年9月20日	综合判定：合格	 A yellow dump truck is shown from a front-three-quarter view. Two workers in safety gear are standing near the front of the truck. The background is a clear blue sky and a flat, open area.
231	GX-B1423/20-Y-234786	2023年9月20日	综合判定：合格	 A yellow dump truck is shown from a front-three-quarter view, similar to the one in the first row. Two workers in safety gear are standing near the front of the truck. The background is a clear blue sky and a flat, open area.

232	GX-B1423/20-Y-234787	2023年9月20日	综合判定：合格	
233	GX-B1423/20-Y-234788	2023年9月20日	综合判定：合格	

234	GX-B1423/20-Y-234789	2023年9月20日	综合判定：合格	
235	GX-B1423/20-Y-234790	2023年9月20日	综合判定：合格	



236	GX-B1423/20-Y-234791	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.
237	GX-B1423/20-Y-234792	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.

238	GX-B1423/20-Y-234793	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.
239	GX-B1423/20-Y-234794	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.

240	GX-B1423/20-Y-234795	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.
241	GX-B1423/20-Y-234796	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.

242	GX-B1423/20-Y-234797	2023年9月20日	综合判定：合格	
243	GX-B1423/20-Y-234798	2023年9月20日	综合判定：合格	

244	GX-B1423/20-Y-234799	2023年9月20日	综合判定：合格	
245	GX-B1423/20-Y-234800	2023年9月20日	综合判定：合格	

246	GX-B1423/20-Y-234801	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large, curved dump body. The background is a clear blue sky.
247	GX-B1423/20-Y-234802	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large, curved dump body. The background is a clear blue sky.



248	GX-B1423/20-Y-234803	2023年9月20日	综合判定：合格	
249	GX-B1423/20-Y-234804	2023年9月20日	综合判定：合格	





250	GX-B1423/20-Y-234805	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large yellow dump body and a white cab. The background is a clear blue sky.
251	GX-B1423/20-Y-234806	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large yellow dump body and a white cab. The background is a clear blue sky.



252	GX-B1423/20-Y-234807	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in blue and white uniforms are standing near the front of the truck. The truck has a large yellow dump body and is facing left. The background is a clear blue sky.
253	GX-B1423/20-Y-234808	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in blue and white uniforms are standing near the front of the truck. The truck has a large yellow dump body and is facing left. The background is a clear blue sky.

254	GX-B1423/20-Y-234809	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large dump body and multiple axles.
255	GX-B1423/20-Y-234810	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large dump body and multiple axles.



256	GX-B1423/20-Y-234811	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large yellow body and a black cab. The background is a clear blue sky.
257	GX-B1423/20-Y-234812	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large yellow body and a black cab. The background is a clear blue sky.

258	GX-B1423/20-Y-234813	2023年9月20日	综合判定：合格	
259	GX-B1423/20-Y-234814	2023年9月20日	综合判定：合格	



260	GX-B1423/20-Y-234815	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.
261	GX-B1423/20-Y-234816	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles.

262	GX-B1423/20-Y-234817	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large, raised bed. The background is a clear blue sky.
263	GX-B1423/20-Y-234818	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large, raised bed. The background is a clear blue sky.

264	GX-B1423/20-Y-234819	2023年9月20日	综合判定：合格	
265	GX-B1423/20-Y-234820	2023年9月20日	综合判定：合格	

266	GX-B1423/20-Y-234821	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in safety gear are standing near the front of the truck. The truck has a large yellow dump body and a white cab. The background is a clear blue sky.
267	GX-B1423/20-Y-234822	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in safety gear are standing near the front of the truck. The truck has a large yellow dump body and a white cab. The background is a clear blue sky.





268	GX-B1423/20-Y-234823	2023年9月20日	综合判定：合格	
269	GX-B1423/20-Y-234824	2023年9月20日	综合判定：合格	



270	GX-B1423/20-Y-234825	2023年9月20日	综合判定：合格	
271	GX-B1423/20-Y-234826	2023年9月20日	综合判定：合格	



272	GX-B1423/20-Y-234827	2023年9月20日	综合判定：合格	
273	GX-B1423/20-Y-234828	2023年9月20日	综合判定：合格	



274	GX-B1423/20-Y-234829	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety vests are standing near the front of the truck. The truck has a large dump body and is facing left.
275	GX-B1423/20-Y-234830	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety vests are standing near the front of the truck. The truck has a large dump body and is facing left.

276	GX-B1423/20-Y-234831	2023年9月20日	综合判定：合格	
277	GX-B1423/20-Y-234832	2023年9月20日	综合判定：合格	



278	GX-B1423/20-Y-234833	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing next to it. The truck has a large dump body and a cab. The background is a clear blue sky.
279	GX-B1423/20-Y-234834	2023年9月20日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing next to it. The truck has a large dump body and a cab. The background is a clear blue sky.

280	GX-B1423/20-Y-234835	2023年9月19日	综合判定：合格	
281	GX-B1423/20-Y-234836	2023年9月19日	综合判定：合格	



282	GX-B1423/20-Y-234837	2023年9月19日	综合判定：合格	
283	GX-B1423/20-Y-234838	2023年9月19日	综合判定：合格	



284	GX-B1423/20-Y-234839	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large, raised bed. The background shows a clear blue sky and some distant structures.
285	GX-B1423/20-Y-234840	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large, raised bed. The background shows a clear blue sky and some distant structures.

286	GX-B1423/20-Y-234841	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large, raised bed. The background shows a clear blue sky and some distant structures.
287	GX-B1423/20-Y-234842	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large, raised bed. The background shows a clear blue sky and some distant structures.

288	GX-B1423/20-Y-234843	2023年9月19日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two people are standing near the front of the truck. A yellow timestamp '2023/9/28' is visible in the bottom right corner of the image.
289	GX-B1423/20-Y-234844	2023年9月19日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two people are standing near the front of the truck. A yellow timestamp '2023/9/28' is visible in the bottom right corner of the image.

290	GX-B1423/20-Y-234845	2023年9月19日	综合判定：合格	
291	GX-B1423/20-Y-234846	2023年9月19日	综合判定：合格	

292	GX-B1423/20-Y-234847	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/9/29' is visible in the bottom right corner of the photo.
293	GX-B1423/20-Y-234848	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/9/29' is visible in the bottom right corner of the photo.


294	GX-B1423/20-Y-234849	2023年9月19日	综合判定：合格	
295	GX-B1423/20-Y-234850	2023年9月19日	综合判定：合格	



296	GX-B1423/20-Y-234851	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people are standing near the front of the truck. A yellow timestamp '2023/9/19' is visible in the bottom right corner of the image.
297	GX-B1423/20-Y-234852	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people are standing near the front of the truck. A yellow timestamp '2023/9/19' is visible in the bottom right corner of the image.



298	GX-B1423/20-Y-234853	2023年9月19日	综合判定：合格	 A yellow dump truck with the number '221' on its side is parked on a dirt surface. Two people are standing near the front of the truck. The background shows a clear blue sky and some industrial equipment.
299	GX-B1423/20-Y-234854	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The background shows a clear blue sky and some industrial equipment.



300	GX-B1423/20-Y-234855	2023年9月19日	综合判定：合格	 A yellow dump truck with its bed raised, parked on a dirt surface. A person in a high-visibility vest is standing near the front. A yellow timestamp '2023/9/19' is visible in the bottom right corner of the image.
301	GX-B1423/20-Y-234856	2023年9月19日	综合判定：合格	 A yellow dump truck with its bed lowered, parked on a dirt surface. Two people are standing near the front. A yellow timestamp '2023/9/19' is visible in the bottom right corner of the image.

302	GX-B1423/20-Y-234857	2023年9月19日	综合判定：合格	
303	GX-B1423/20-Y-234858	2023年9月19日	综合判定：合格	



304	GX-B1423/20-Y-234859	2023年9月19日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date '2023/9/29' is visible in the bottom right corner of the image.
305	GX-B1423/20-Y-234860	2023年9月19日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date '2023/9/29' is visible in the bottom right corner of the image.

306	GX-B1423/20-Y-234861	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility vests and hard hats are standing near the front of the truck, appearing to be inspecting it. A small yellow timestamp '2023/9/19' is visible in the bottom right corner of the photo.
307	GX-B1423/20-Y-234862	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility vests and hard hats are standing near the front of the truck, appearing to be inspecting it. A small yellow timestamp '2023/9/19' is visible in the bottom right corner of the photo.

308	GX-B1423/20-Y-234863	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing safety gear (hard hats and high-visibility vests) are standing in front of the truck. The truck has a yellow body and a white cab. The background is a clear blue sky.
309	GX-B1423/20-Y-234864	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing safety gear (hard hats and high-visibility vests) are standing in front of the truck. The truck has a yellow body and a white cab. The background is a clear blue sky.



310	GX-B1423/20-Y-234865	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a flat, light-colored surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's bed is slightly raised. A small yellow timestamp '2023/9/19' is visible in the bottom right corner of the image.
311	GX-B1423/20-Y-234866	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a flat, light-colored surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's bed is slightly raised. A small yellow timestamp '2023/9/19' is visible in the bottom right corner of the image.

312	GX-B1423/20-Y-234867	2023年9月19日	综合判定：合格	
313	GX-B1423/20-Y-234868	2023年9月19日	综合判定：合格	


314	GX-B1423/20-Y-234869	2023年9月19日	综合判定：合格	
315	GX-B1423/20-Y-234870	2023年9月19日	综合判定：合格	





316	GX-B1423/20-Y-234871	2023年9月19日	综合判定：合格	
317	GX-B1423/20-Y-234872	2023年9月19日	综合判定：合格	



318	GX-B1423/20-Y-234873	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in safety gear are standing in front of the truck. The truck has a large dump body and multiple axles.
319	GX-B1423/20-Y-234874	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in safety gear are standing in front of the truck. The truck has a large dump body and multiple axles.

320	GX-B1423/20-Y-234875	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in high-visibility vests are standing near the front of the truck. The truck has a large dump body and multiple axles.
321	GX-B1423/20-Y-234876	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in high-visibility vests are standing near the front of the truck. The truck has a large dump body and multiple axles.


322	GX-B1423/20-Y-234877	2023年9月19日	综合判定：合格	
323	GX-B1423/20-Y-234878	2023年9月19日	综合判定：合格	

324	GX-B1423/20-Y-234879	2023年9月19日	综合判定：合格	
325	GX-B1423/20-Y-234880	2023年9月19日	综合判定：合格	

326	GX-B1423/20-Y-234881	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/9/19' is visible in the bottom right corner of the image.
327	GX-B1423/20-Y-234882	2023年9月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/9/21' is visible in the bottom right corner of the image.

328	GX-B1423/20-Y-234883	2023年9月19日	综合判定：合格	
329	GX-B1423/20-Y-234884	2023年9月19日	综合判定：合格	



330	GX-B1423/20-Y-234885	2023年9月19日	综合判定：合格	
331	GX-B1423/20-Y-234886	2023年9月19日	综合判定：合格	



332	GX-B1423/20-Y-234887	2023年9月19日	综合判定：合格	
333	GX-B1423/20-Y-234888	2023年9月19日	综合判定：合格	