




序号	报告编号	发布日期	结论	影像资料
48	GX-B1316/23-6-24001	2024/2/23	所检项目合格。	
49	GX-B1598/21-6-24011	2023/2/23	实测钢丝绳有效截面积损失百分比最大为0.53%，小于5%为正常。	

50	GX-B1598/21-6-24012	2023/2/23	实测钢丝绳有效截面积损失百分比最大为0.82%，小于5%为正常。	 2024 01 03
51	GX-B1598/21-6-24013	2023/2/23	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。	 2024 01 04
52	GX-B1598/21-6-24014	2023/2/23	实测钢丝绳有效截面积损失百分比最大为0.63%，小于5%为正常。	 2024 01 04

53	GX-B1598/21-6-24015	2023/2/23	<p>实测钢丝绳有效截面积损失百分比最大为0.78%，小于5%为正常。</p>	
54	GX-B1598/21-6-24016	2023/2/23	<p>实测钢丝绳有效截面积损失百分比最大为0.68%，小于5%为正常。</p>	
55	GX-B1303/21-6-24003	2023/2/23	综合判定合格	

56	GX-B1303/21-6-24004	2023/2/23	综合判定合格	
57	GX-B1382/21-6-24001	2023/2/23	合格。	
58	GX-B1534/20-6-24002	2024/2/23	所检项目合格	

59	GX-B1534/20-6-24003	2024/2/23	所检项目合格	
60	GX-B1534/20-6-24004	2024/2/23	所检项目合格	
61	GX-B1451/20-6-24021~24035	2024/2/23	所检项目合格	

62	GX-B1548/20-6-24002	2024/2/23	所检项目合格	
63	GX-B1548/20-6-24003	2024/2/23	所检项目合格	
64	GX-B1548/20-6-24004	2024/2/23	所检项目合格	

65	GX-B1548/20-6-24005	2024/2/23	所检项目合格		
66	GX-B1548/20-6-24006	2024/2/23	所检项目合格		
67	GX-B1548/20-6-24007	2024/2/23	所检项目合格		

68	GX-B1548/20-6-24008	2024/2/23	所检项目合格	
69	GX-B1548/20-6-24009	2024/2/23	所检项目合格	
70	GX-B1548/20-6-24010	2024/2/23	所检项目合格	

71	GX-B1598/21-6-24009	2023/2/26	实测钢丝绳有效截面积损失百分比最大为0.49%，小于5%为正常。	
72	GX-B1598/21-6-24010	2023/2/26	实测钢丝绳有效截面积损失百分比最大为0.57%，小于5%为正常。	
73	GX-B1322/21-6-24001~24006	2023/2/26	所检项目合格	

74	GX-B1322/21-6-24007~24012	2024/2/26	所检项目合格	
75	GX-B1310/21-6-24017	2024/2/26	符合标准要求	
76	GX-B1427/21-6-24006	2024/2/26	符合标准要求	