

序号	报告编号	发布日期	结论	影像资料
169	GX-B1603/22-B-240048~240053	2024年4月8日	所检项目合格	
170	GX-B1603/22-B-240054~240057	2024年4月8日	所检项目合格	
171	GX-B1542/21-B-24132~24144	2024年4月7日	所检项目合格	

172	GX-B1528/20-B-24132~24144	2024年4月7日	所检项目合格	 A photograph showing three people in a laboratory setting. One person is wearing a blue face mask. They are gathered around a piece of equipment. A red date stamp '2024.3.16' is visible in the bottom right corner of the image. The text '中檢公位' is partially visible on the left side of the image.
173	GX-B1310/21-5-24060	2024. 3. 19	符合标准要求。	 A photograph of a construction site showing a large, multi-story concrete structure under construction. A worker is visible on a high platform. A yellow date stamp '2024/02/25' is visible in the bottom right corner of the image.
174	GX-B1310/21-5-24061	2024. 3. 19	符合标准要求。	 A photograph of a construction site showing a worker in a red hard hat and safety harness operating equipment. A yellow date stamp '2024/02/25' is visible in the bottom right corner of the image.