


序号	报告编号	发布日期	结论	影像资料
23	GX-B1427/21-3-24086	2024年9月6日	符合标准要求。	
24	GX-B1427/21-3-24087	2024年9月6日	符合标准要求。	

25	GX-B1310/21-3-24269	2024年9月6日	符合标准要求。	
26	GX-B1310/21-3-24270	2024年9月6日	符合标准要求。	

27	GX-B1427/21-3-24085	2024年9月6日	符合标准要求。	 A worker wearing a red helmet and safety harness stands in a confined space, possibly a tunnel or a large pipe. Safety signs are visible on the wall, including one with the text '进入安全警示标志' (Enter Safety Warning Sign). The date '2024.08.13' is visible in the bottom right corner of the photo.
28	GX-B1310/21-3-24268	2024年9月6日	符合标准要求。	 A worker wearing a red helmet and safety harness is working on a piece of equipment, possibly a generator or a pump. The date '2024.08.13' is visible in the bottom right corner of the photo.

29	GX-B1536/20-3-24001	2024年9月14日	综合判定：合格。	 A worker in a red uniform and helmet is operating industrial machinery. The date stamp in the bottom right corner of the photo is 2024.09.13.
30	GX-B1303/21-3-24007	2024年9月13日	综合判定：合格。	 A worker in a red uniform and helmet is standing next to a large industrial machine. The date stamp in the bottom right corner of the photo is 2024.08.14.


31	GX-B1303/21-3-24008	2024年9月13日	综合判定：合格。	
32	GX-B1328/20-3-24156	2024. 9. 12	合格。	

33	GX-B1328/20-3-24157	2024. 9. 12	合格。	
34	GX-B1328/20-3-24146	2024. 9. 5	所检项目合格。	

35	GX-B1328/20-3-24147	2024. 9. 5	合格。	
36	GX-B1328/20-3-24148	2024. 9. 5	合格。	

37	GX-B1328/20-3-24149	2024. 9. 5	合格。	
38	GX-B1418/23-3-24010	2024. 9. 10	综合判定：合格。	

39	GX-B1418/23-3-24011	2024. 9. 10	综合判定：合格。	
40	GX-B1418/23-3-24012	2024. 9. 10	综合判定：合格。	

41	GX-B1418/23-3-24013	2024. 9. 10	综合判定：合格。	 A worker in a red uniform and helmet is using a tool in a tunnel. The date 2024.7.26 is visible in the bottom right corner of the photo.
42	GX-B1418/23-3-24014	2024. 9. 10	综合判定：合格。	 A worker in a red uniform and helmet is inspecting a rock surface. The date 2024.7.26 is visible in the bottom right corner of the photo.

43	GX-B1418/23-3-24015	2024. 9. 10	综合判定：合格。	 A worker in a red uniform and helmet is working in a tunnel. There are blue pipes and a yellow pipe visible. The date 2024.7.26 is printed in yellow at the bottom right of the image.
44	GX-B1418/23-3-24016	2024. 9. 10	综合判定：合格。	 A worker in a red uniform and helmet is kneeling in a tunnel, looking at a green object on the ground. The date 2024.7.26 is printed in yellow at the bottom right of the image.
45	GX-B1328/20-3-24151	2024. 9. 11	合格。	
46	GX-B1328/20-3-24152	2024. 9. 11	合格。	

47	GX-B1328/20-3-24153	2024. 9. 11	合格。	
48	GX-B1328/20-3-24154	2024. 9. 11	合格。	
49	GX-B1328/20-3-24155	2024. 9. 11	合格。	
50	GX-B1304/21-3-24001	2024年9月14日	综合判定：合格。	