

序号	报告编号	发布日期	结论	影像资料
27	GX-B1310/21-Y-24164	2024年9月6日	符合标准要求。	
28	GX-B1310/21-Y-24165	2024年9月6日	符合标准要求。	

29	GX-B1310/21-Y-24166	2024年9月6日	符合标准要求。	
30	GX-B1521/20-Y-24578	2024年9月10日	所检项目合格。	

31	GX-B1521/20-Y-24579	2024年9月10日	所检项目合格。	
32	GX-B1521/20-Y-24580	2024年9月10日	所检项目合格。	

33	GX-B1521/20-Y-24581	2024年9月10日	所检项目合格。	
34	GX-B1521/20-Y-24582	2024年9月10日	所检项目合格。	

35	GX-B1521/20-Y-24583	2024年9月10日	所检项目合格。	
36	GX-B1521/20-Y-24584	2024年9月10日	所检项目合格。	

37	GX-B1521/20-Y-24585	2024年9月10日	所检项目合格。	
38	GX-B1521/20-Y-24586	2024年9月10日	所检项目合格。	

39	GX-B1521/20-Y-24587	2024年9月10日	所检项目合格。	
40	GX-B1521/20-Y-24588	2024年9月10日	所检项目合格。	

41	GX-B1521/20-Y-24589	2024年9月10日	所检项目合格。	 A close-up photograph of a worker wearing a red hard hat and a light-colored jacket, operating the controls inside the cab of a yellow excavator. The cab is open, and the worker is looking down at a control panel. A yellow date stamp '2024/9/1' is visible in the bottom right corner of the image.
42	GX-B1521/20-Y-24590	2024年9月10日	所检项目合格。	 A photograph of a yellow excavator with 'JANY' branding on its arm, operating on a dirt construction site. In the background, there are snow-capped mountains under a cloudy sky. A yellow date stamp '2024/9/1' is visible in the bottom right corner of the image.

43	GX-B1539/22-Y-24306	2024年9月10日	所检项目合格。	
44	GX-B1539/22-Y-24307	2024年9月10日	所检项目合格。	

45	GX-B1557/22-Y-24051	2024年9月10日	所检项目合格。	
46	GX-B1328/20-Y-24069	2024年9月12日	本次共检绝缘胶垫3件，3件绝缘胶垫合格。	

47	GX-B1328/20-Y-24070	2023年4月18日	所检项目合格。	 2023/9/6
48	GX-B1521/20-Y-24591	2024年9月12日	所检项目合格。	 2023/9/8

49	GX-B1521/20-Y-24592	2024年9月12日	所检项目合格。	
50	GX-B1521/20-Y-24593	2024年9月12日	所检项目合格。	

51	GX-B1521/20-Y-24594	2024年9月12日	所检项目合格。	 A photograph showing a male operator wearing a red hard hat and a light blue short-sleeved shirt, sitting in the cab of a piece of heavy machinery. He is looking down at a control panel. A yellow date stamp '2024/9/11' is visible in the bottom left corner of the photo.
52	GX-B1539/22-Y-24308	2024年9月12日	所检项目合格。	 A photograph of a yellow front-end loader with the number '5-C-311' on its side, parked on a dirt surface under a clear blue sky. Two people, one in a white shirt and the other in an orange safety vest, are standing next to the front wheel. A yellow date stamp '2024/9/11' is visible in the bottom right corner of the photo.