

序号	报告编号	发布日期	结论	影像资料
1	GX-B1328/20-3-25111	2025. 5. 7	本次共检绝缘手套2只, 2只绝缘手套合格。	
2	GX-B1328/20-3-25112	2025. 5. 7	本次共检绝缘靴2只, 2只绝缘靴合格。	
3	GX-B1328/20-3-25113	2025. 5. 7	本次共检携带式接地和接地短路装置1套, 1套携带式接地和接地短路装置合格。	
4	GX-B1328/20-3-25114	2025. 5. 7	本次共检绝缘杆1套, 1套绝缘杆合格。	
5	GX-B1328/20-3-25115	2025. 5. 7	本次共检验电器1支, 1支验电器合格。	
6	GX-B1328/20-3-25116	2025. 5. 7	本次共检绝缘手套2只, 2只绝缘手套合格。	
7	GX-B1328/20-3-25117	2025. 5. 7	本次共检绝缘靴2只, 2只绝缘靴合格。	

8	GX-B1328/20-3-25118	2025. 5. 7	本次共检绝缘手套2只，2只绝缘手套合格。	
9	GX-B1328/20-3-25119	2025. 5. 7	本次共检绝缘靴2只，2只绝缘靴合格。	
10	GX-B1328/20-3-25120	2025. 5. 7	本次共检携带式接地和接地短路装置1套，1套携带式接地和接地短路装置合格。	
11	GX-B1328/20-3-25121	2025. 5. 7	本次共检绝缘杆1套，1套绝缘杆合格。	
12	GX-B1328/20-3-25122	2025. 5. 7	本次共检验电器1支，1支验电器合格。	
13	GX-B1328/20-3-25123	2025. 5. 7	本次共检绝缘手套4只，4只绝缘手套合格。	

14	GX-B1328/20-3-25124	2025. 5. 7	本次共检绝缘靴4只，4只绝缘靴合格。	
15	GX-B1328/20-3-25125	2025. 5. 7	本次共检便携式接地和接地短路装置2套，2套便携式接地和接地短路装置合格。	
16	GX-B1328/20-3-25126	2025. 5. 7	本次共检绝缘杆2套，2套绝缘杆合格。	


17	GX-B1328/20-3-25127	2025. 5. 7	本次共检验电器2支，2支 验电器合格。	
18	GX-B1328/20-3-25131	2025. 5. 7	本次共检绝缘手套4只，4 只绝缘手套合格。	
19	GX-B1328/20-3-25132	2025. 5. 7	本次共检绝缘靴4只，4只 绝缘靴合格。	
20	GX-B1328/20-3-25133	2025. 5. 7	本次共检绝缘手套4只，4 只绝缘手套合格。	
21	GX-B1328/20-3-25134	2025. 5. 7	本次共检绝缘靴4只，4只 绝缘靴合格。	

22	GX-B1321/20-3-25191~25202	2025. 5. 7	本次共检电力电缆12条，12条电力电缆所检项目合格。 。	
23	GX-B1321/20-3-25209~25217	2025. 5. 7	本次共检电力电缆9条，9条电力电缆所检项目合格。 。	

24	GX-B1321/20-3-25218~25225	2025. 5. 7	本次共检电力电缆8条，8条电力电缆所检项目合格。 。	 <p>2025.03.14</p>
25	GX-B1321/20-3-25226~25230	2025. 5. 7	本次共检电力电缆5条，5条电力电缆所检项目合格。 。	 <p>2025.03.15</p>

26	GX-B1321/20-3-25231~25236	2025. 5. 7	本次共检电力电缆6条，6条电力电缆所检项目合格。 。	 A worker wearing a red safety helmet and a blue jacket is working on a red electrical cabinet. The worker is holding a tool and looking at the equipment. The date stamp in the bottom right corner of the photo is 2025.03.16.
27	GX-B1321/20-3-25258~25270	2025. 5. 7	本次共检电力电缆13条，13条电力电缆所检项目合格。 。	 A worker wearing a red safety helmet and a blue jacket is working on a red electrical cabinet. The worker is holding a tool and looking at the equipment. The date stamp in the bottom right corner of the photo is 2025.03.20.

28	GX-B1321/20-3-25271~25278	2025. 5. 7	本次共检电力电缆8条，8条电力电缆所检项目合格。	
29	GX-B1328/20-3-25095	2025. 5. 6	本次共检绝缘手套84只，84只绝缘手套合格。	

30	GX-B1328/20-3-25096	2025. 5. 6	本次共检绝缘靴84只，84只 绝缘靴合格。	
31	GX-B1328/20-3-25097	2025. 5. 6	本次共检验电器40支，40支 验电器合格。	

32	GX-B1328/20-3-25098	2025. 5. 6	本次共检携带式接地和接地短路装置40套，40套携带式接地和接地短路装置合格。	
33	GX-B1328/20-3-25099	2025. 5. 6	本次共检绝缘杆10套，10套绝缘杆合格。	

34	GX-B1323/21-3-25050~25052	2025. 5. 6	所检项目合格。	
35	GX-B1323/21-3-25053~25055	2025. 5. 6	所检项目合格。	

36	GX-B1323/21-3-25056~25057	2025. 5. 6	所检项目合格。	
37	GX-B1323/21-3-25058~25061	2025. 5. 6	所检项目合格。	

38	GX-B1323/21-3-25062~25065	2025. 5. 6	所检项目合格。	
39	GX-B1323/21-3-25066~25067	2025. 5. 6	所检项目合格。	

40	GX-B1321/20-3-25703	2025. 5. 6	所检项目合格。	
41	GX-B1312/20-3-25302~25307	2025. 5. 6	本次共检防爆干式变压器6台，6台防爆干式变压器所检项目合格。	

42	GX-B1312/20-3-25308	2025. 5. 6	所检项目合格。	
43	GX-B1312/20-3-25173~25174	2025. 5. 6	本次共检电力变压器2台， 2台电力变压器所检项目合格。	

44	GX-B1312/20-3-25153	2025. 5. 6	所检项目合格。	
45	GX-B1312/20-3-25151~25152	2025. 5. 6	本次共检防爆干式变压器2台，2台防爆干式变压器所检项目合格。	

46	GX-B1312/20-3-25154~25157	2025. 5. 6	本次共检防爆干式变压器4台，4台防爆干式变压器所检项目合格。	
47	GX-B1312/20-3-25160	2025. 5. 6	所检项目合格。	

48	GX-B1312/20-3-25161~25165	2025. 5. 6	本次共检防爆干式变压器5台，5台防爆干式变压器所检项目合格。	
49	GX-B1312/20-3-25166~25167	2025. 5. 6	本次共检电力变压器2台，2台电力变压器所检项目合格。	

50	GX-B1312/20-3-25172	2025. 5. 6	所检项目合格。	
51	GX-B1312/20-3-25168~25171	2025. 5. 6	本次共检电力变压器4台， 4台电力变压器所检项目合格。	

52	GX-B1312/20-3-25158~25159	2025. 5. 6	本次共检防爆干式变压器2台，2台防爆干式变压器所检项目合格。	
53	GX-B1336/22-3-25001~25002	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	

54	GX-B1336/22-3-25003~25004	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	 <p>2025.03.13</p>
55	GX-B1336/22-3-25005~25006	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	 <p>2025.03.15</p>

56	GX-B1336/22-3-25007~25008	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	 <p>2025.03.17</p>
57	GX-B1336/22-3-25009~25010	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	 <p>2025.03.18</p>

58	GX-B1336/22-3-25011~25012	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	 <p>2025.03.20</p>
59	GX-B1336/22-3-25013~25014	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	 <p>2025.03.21</p>

60	GX-B1336/22-3-25015~25016	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	
61	GX-B1336/22-3-25017~25018	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	

62	GX-B1336/22-3-25019	2025. 5. 6	所检项目合格。	
63	GX-B1336/22-3-25020	2025. 5. 6	所检项目合格。	

64	GX-B1336/22-3-25021~25022	2025. 5. 6	本次共检母线2段，2段母线所检项目合格。	
65	GX-B1329/21-3-25067~25076	2025. 5. 6	本次共检氧化锌避雷器10组，10组氧化锌避雷器所检项目合格。	


66	GX-B1329/21-3-25077~25080	2025. 5. 6	本次共检氧化锌避雷器4组，4组氧化锌避雷器所检项目合格。	
67	GX-B1329/21-3-25081~25092	2025. 5. 6	本次共检氧化锌避雷器12组，12组氧化锌避雷器所检项目合格。	

68	GX-B1329/21-3-25093~25104	2025. 5. 6	本次共检氧化锌避雷器12组，12组氧化锌避雷器所检项目合格。	
69	GX-B1495/20-3-25581~25596	2025. 5. 6	本次共检高压开关设备16台，16台高压开关设备所检项目合格。	

70	GX-B1495/20-3-25597~25610	2025. 5. 6	本次共检高压开关设备14台，14台高压开关设备所检项目合格。	 <p>2025.03.19</p>
71	GX-B1495/20-3-25611~25625	2025. 5. 6	本次共检高压开关设备15台，15台高压开关设备所检项目合格。	 <p>2025.03.20</p>

72	GX-B1495/20-3-25626~25637	2025. 5. 6	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	
73	GX-B1495/20-3-25638~25642	2025. 5. 6	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	

74	GX-B1495/20-3-25643~25658	2025. 5. 6	本次共检高压开关设备16台，16台高压开关设备所检项目合格。	
75	GX-B1308/23-3-25011	2025. 5. 6	综合判定：合格。	

76	GX-B1308/23-3-25012	2025. 5. 6	综合判定：合格。	
77	GX-B1495/20-3-25886~25896	2025. 5. 9	本次共检高压开关设备11台，11台高压开关设备所检项目合格。	

78	GX-B1310/21-3-25073	2025. 5. 9	符合标准要求。	
79	GX-B1427/21-3-25017	2025. 5. 9	符合标准要求。	

80	GX-B1310/21-3-25071	2025. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
81	GX-B1428/21-3-25026	2025. 5. 9	无缺陷痕迹显示。	

82	GX-B1310/21-3-25072	2025. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
83	GX-B1428/21-3-25027	2025. 5. 9	无缺陷痕迹显示。	