

序号	报告编号	发布日期	结论	影像资料
173	GX-B1601/22-F-250431~250432	2025.5.27	所检项目合格	
174	GX-B1600/24-F-25001	2025. 5. 27	可不注水煤层	
175	GX-B1600/24-F-25002	2025. 5. 27	可不注水煤层	
176	GX-B1373/21-F-25282~25291	2025.5.27	所检项目合格	

177	GX-B1373/21-F-25292~25298	2025.5.27	所检项目合格	
178	GX-B1540/20-F-251250~251254	2025.5.26	所检项目合格	
179	GX-B1540/20-F-251245~251249	2025.5.26	所检项目合格	

180	GX-B1543/25-F-25118~25122	2025.5.27	所检项目合格	
181	GX-B1528/20-F-25106~25110	2025.5.27	所检项目合格	
182	GX-B1529/20-F-25126~25130	2025.5.27	所检项目合格	

183	GX-B1529/20-F-25121~25125	2025.5.27	所检项目合格	
184	GX-B1528/20-F-25101~25105	2025.5.27	所检项目合格	
185	GX-B1543/25-F-25113~25117	2025.5.27	所检项目合格	

186	GX-B1568/22-F-25230~25248	2025.5.29	用风速表19台，19台所检项目合格。	
187	GX-B1606/23-F-25244~25253	2025.5.28	所检项目合格	
188	GX-B1606/23-F-25254~25256	2025.5.29	所检项目合格	

189	GX-B1602/22-F-25036~25039	2025.5.29	所检项目合格	
190	GX-B1568/22-F-25202~25229	2025.5.29	所检项目合格	
191	GX-B1605/23-F-25244-25253	2025.5.28	本次共检验多参数气体测定器10台，10台所检项目合格。”	

192	GX-B1605/23-F-25254-25256	2025.5.29	本次共检验多参数气体测定器3台，3台所检项目合格。”	
193	GX-B1592/21-F-25110~25118	2025.5.29	所检项目合格	
194	GX-B1372/22-F-250409~250413	2025.5.29	所检项目合格	

195	GX-B1601/22-F-250415	2025.5.29	所检项目合格	
196	GX-B1603/22-F-250131	2025.5.29	所检项目合格	
197	GX-B1372/22-F-250422	2025.5.29	所检项目合格	

198	GX-B1568/22-F-25249~25251	2025.5.29	所检项目合格	 2025.5.23
199	GX-B1568/22-F-25256~25266	2025.5.30	所检项目合格	 2025.5.28
200	GX-B1568/22-F-25273~25274	2025.5.30	所检项目合格	 2025.5.28

201	GX-B1595/22-F-25077~25080	2025.5.30	所检项目合格	
202	GX-B1568/22-F-25275~25281	2025.5.30	所检项目合格	
203	GX-B1568/22-F-25282~25285	2025.5.30	所检项目合格	

204	GX-B1568/22-F-25286~25287	2025.5.30	所检项目合格	 2025.5.28	
205	GX-B1540/20-F-251443~251445	2025.5.30	所检项目合格	 2025.5.22	
206	GX-B1531/25-F-250507	2025.5.30	所检项目合格	 2025.5.28	

207	GX-B1531/25-F-250508	2025.5.30	所检项目合格	
-----	----------------------	-----------	--------	---