

序号	报告编号	发布日期	结论	影像资料
344	GX-B1363/22-A-25285	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
345	GX-B1363/22-A-25286	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1363/22-A-25300	2025/5/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1363/22-A-25302	2025/5/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
348	GX-B1363/22-A-25299	2025/5/27	全厚度拉伸强度为；1085N/mm，全厚度拉断伸长率为32%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
349	GX-B1363/22-A-25305	2025/5/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
350	GX-B1363/22-A-25306	2025/5/27	所检项目合格。	 A photograph showing two men in light blue work shirts inspecting a large, dark-colored industrial furnace or boiler. The furnace has a large door that is open. One man is on the left, looking into the furnace, and the other is on the right, also looking inside. A green trash bin is visible on the left, and a fan is on the right. The date '2025.05.23' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
351	GX-B1508/20-A-25007	2025/5/27	阻燃性能不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
352	GX-B1508/20-A-25008	2025/5/27	阻燃性能不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
353	GX-B1363/22-A-25298	2025/5/28	全厚度拉伸强度为1065N/mm；全厚度拉断伸长率为27%，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
354	GX-B1365/25-A-25057	2025/5/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
355	GX-B1366/25-A-25065	2025/5/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
356	GX-B1369/20-A-25005	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
357	GX-B1364/22-A-25549	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
358	GX-B1364/22-A-25551	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
359	GX-B1364/22-A-25552	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
360	GX-B1364/22-A-25553	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
361	GX-B1364/22-A-25554	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
362	GX-B1364/22-A-25555	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
363	GX-B1364/22-A-25556	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
364	GX-B1363/22-A-25308	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
365	GX-B1363/22-A-25304	2025/5/28	所检项目合格。	 <p>The photograph shows two men in light blue work shirts and dark trousers inspecting a large, dark-colored industrial machine. One man is wearing yellow gloves. The machine has a large, dark, rectangular panel that is open. In the background, there is a window with a view of greenery outside and a large black industrial fan. A green trash bin is visible on the left. The date '2025.05.23' is printed in orange in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
366	GX-B1363/22-A-25303	2025/5/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
367	GX-B1365/25-A-25058	2025/5/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
368	GX-B1366/25-A-25066	2025/5/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
369	GX-B1366/25-A-25067	2025/5/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
370	GX-B1365/25-A-25056	2025/5/29	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
371	GX-B1366/25-A-25063	2025/5/29	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
372	GX-B1366/25-A-25064	2025/5/29	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
373	GX-B1364/22-A-25565	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
374	GX-B1364/22-A-25566	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
375	GX-B1364/22-A-25567	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
376	GX-B1364/22-A-25568	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
377	GX-B1364/22-A-25569	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
378	GX-B1364/22-A-25570	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
379	GX-B1364/22-A-25571	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
380	GX-B1363/22-A-25316	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
381	GX-B1363/22-A-25311	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
382	GX-B1363/22-A-25314	2025/5/30	所检项目合格。	 <p>The photograph shows two men in light blue work shirts inspecting a large, dark-colored industrial furnace or boiler. The furnace has a large, open door on the right side. The room has a window with a view of greenery outside and a large green fan in the foreground. A date stamp '2025.05.29' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
383	GX-B1363/22-A-25309	2025/5/29	所检项目合格。	 A photograph showing two men in light blue work shirts inspecting a large, dark-colored industrial furnace or boiler. The furnace has a large, dark, rectangular opening on its front. One man is on the left, looking into the opening, while the other is on the right, also looking at the furnace. The room has white walls and a window on the right side. A green trash bin is visible on the left. The date '2025.05.27' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
384	GX-B1363/22-A-25310	2025/5/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
385	GX-B1364/22-A-25588	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
386	GX-B1364/22-A-25589	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
387	GX-B1364/22-A-25560	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
388	GX-B1364/22-A-25561	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
389	GX-B1364/22-A-25564	2025/5/30	成束电线电缆燃烧试验不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
390	GX-B1364/22-A-25563	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
391	GX-B1364/22-A-25562	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
392	GX-B1364/22-A-25575	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
393	GX-B1364/22-A-25576	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
394	GX-B1364/22-A-25577	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
395	GX-B1364/22-A-25578	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
396	GX-B1364/22-A-25579	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
397	GX-B1364/22-A-25557	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
398	GX-B1364/22-A-25574	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
399	GX-B1538/22-A-25050	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
400	GX-B1538/22-A-25051	2025/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
401	GX-B1363/22-A-25315	2025/5/30	所检项目合格。	 A photograph showing two men in light blue short-sleeved shirts inspecting a large, dark-colored industrial boiler or furnace. The boiler has a tall, cylindrical chimney stack on top. The men are looking into the open front door of the boiler. The background shows a plain wall and a window with a red frame. A date stamp '2025.05.29' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
402	GX-B1363/22-A-25313	2025/5/30	所检项目合格。	 A photograph showing two technicians in light blue uniforms inspecting a large, dark-colored industrial furnace or boiler. One technician is wearing yellow gloves and is touching the furnace. The furnace has a large, conical top section. In the background, there is a window with a view of trees and a green fan. The date '2025 05 25' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
403	GX-B1363/22-A-25312	2025/5/30	所检项目合格。	