


序号	报告编号	发布日期	结论	影像资料
23	GX-B1304/21-1-25007	2025. 6. 6	综合判定：合格	 <p>2025 04 22</p>
24	GX-B1328/20-1-25059	2025. 6. 6	本次共检验电器2支，2支验电器合格	 <p>2025 06 03</p>


25	GX-B1328/20-1-25060	2025. 6. 6	本次共检便携式短路接地线1套，1套便携式短路接地线合格	 A photograph showing a testing setup in a laboratory. It features a large circular metal ring mounted on a yellow stand, connected to various electrical components and cables. A person is partially visible in the background, and a red timestamp '2025. 6. 6' is visible in the bottom right corner of the image.
26	GX-B1328/20-1-25061	2025. 6. 6	本次共检绝缘杆1套，1套绝缘杆合格	 A photograph showing a testing setup in a laboratory, similar to the one above. It features a large circular metal ring mounted on a yellow stand, connected to various electrical components and cables. A person is partially visible in the background, and a red timestamp '2025. 6. 6' is visible in the bottom right corner of the image.


27	GX-B1451/20-1-25256~25259	2025. 6. 10	压开关柜4台, 4台高压开关柜所	 A photograph showing two workers in red hard hats and safety gear. One worker is standing and looking into an open electrical cabinet, while the other is kneeling and holding a clipboard. The date stamp '2025 05 25' is visible in the bottom right corner of the photo.
28	GX-B1598/24-1-25030	2025. 6. 10	截面积损失百分比最大为1.65%	 A photograph of a worker wearing a red hard hat, safety glasses, and a grey jacket. The worker is kneeling on a wooden plank and working on a metal structure, possibly a railing or part of a machine. The date stamp '2025/4/23' is visible in the bottom right corner of the photo.

29	GX-B1598/24-1-25031	2025. 6. 10	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常	
30	GX-B1598/24-1-25032	2025. 6. 10	实测钢丝绳有效截面积损失百分比最大为2.51%，小于5%为正常	


31	GX-B1598/24-1-25033	2025. 6. 10	实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常	
32	GX-B1313/21-1-25118~25123	2025. 6. 11	本次共检电力变压器6台，6台电力变压器所检项目合格	

33	GX-B1312/20-1-25353~25358	2025. 6. 11	变压器6台，6台电力变压器	
34	GX-B1312/20-1-25359~25360	2025. 6. 11	本次共检电力变压器2台，2台电力变压器所检项目合格	

35	GX-B1312/20-1-25361~25369	2025. 6. 11	本次共检电力变压器9台，9台电力变压器所检项目合格	 <p>2025/05/09</p>
36	GX-B1312/20-1-25370~25378	2025. 6. 11	本次共检电力变压器9台，9台电力变压器所检项目合格	 <p>2025/05/10</p>

37	GX-B1312/20-1-25379~25382	2025. 6. 11	本次共检电力变压器4台，4台电力变压器所检项目合格	 <p>2025/05/11</p>
38	GX-B1312/20-1-25383~25384	2025. 6. 11	本次共检电力变压器2台，2台电力变压器所检项目合格	 <p>2025/05/13</p>

39	GX-B1312/20-1-25385~25386	2025. 6. 11	本次共检电力变压器2台，2台电力变压器所检项目合格	
40	GX-B1312/20-1-25387~25388	2025. 6. 11	本次共检电力变压器2台，2台电力变压器所检项目合格	

41	GX-B1418/23-1-25001	2025. 6. 13	综合判定：合格	 A photograph of a worker in a dark tunnel. The worker is wearing a grey uniform and a headlamp. They are standing next to a bundle of cables and pipes. The tunnel walls are rough and there are more cables and pipes visible in the background. A date stamp '2025 06 11' is visible in the bottom right corner of the photo.
42	GX-B1418/23-1-25002	2025. 6. 13	综合判定：合格	 A photograph of a worker in a dark tunnel. The worker is wearing a grey uniform, a red hard hat, and a headlamp. They are standing next to a bundle of cables and pipes. The tunnel walls are rough and there are more cables and pipes visible in the background. A date stamp '2025 06 11' is visible in the bottom right corner of the photo.

43	GX-B1418/23-1-25003	2025. 6. 13	综合判定：合格	
44	GX-B1323/21-1-25335~25337	2025. 6. 13	所检项目合格	

45	GX-B1323/21-1-25338~25340	2025. 6. 13	所检项目合格	
46	GX-B1323/21-1-25341~25343	2025. 6. 13	所检项目合格	

47	GX-B1310/21-1-25128	2025. 6. 12	符合标准要求	
48	GX-B1310/21-1-25129	2025. 6. 12	符合标准要求	

49	GX-B1427/21-1-25130	2025. 6. 12	符合标准要求	
50	GX-B1310/21-1-25131	2025. 6. 12	符合标准要求	

51	GX-B1310/21-1-25132	2025. 6. 12	符合标准要求	
52	GX-B1310/21-1-25133	2025. 6. 12	符合标准要求	

53	GX-B1310/21-1-25134	2025. 6. 12	符合标准要求	 <p>A photograph showing two workers in safety gear (hard hats and work clothes) standing next to large, blue industrial machinery. The machinery has several circular access points with 'Ex' labels. The date '2025/05/16' is visible in the bottom right corner of the photo.</p>
54	GX-B1428/21-1-25135	2025. 6. 12	无缺陷迹痕显示	 <p>A photograph showing one worker in safety gear (hard hat and work clothes) standing next to the same large, blue industrial machinery as in the first photo. The machinery has 'Ex' labels. The date '2025/05/16' is visible in the bottom right corner of the photo.</p>

55	GX-B1310/21-1-25139	2025. 6. 12	符合标准要求	
56	GX-B1428/21-1-25140	2025. 6. 12	无缺陷迹痕显示	