






序号	报告编号	发布日期	结论	影像资料	
193	GX-B1305/21-6-25013	2025/6/12	综合判定：合格。		 A worker in a blue uniform and red helmet is operating a large industrial machine with a large black cable. The worker is wearing a red helmet and a blue uniform. The machine is large and black, with a large cable running through it. The background shows a tunnel or underground setting with some equipment and signs. The date 2025 05 13 is visible in the bottom right corner of the image.
194	GX-B1611/23-6-25001	2025年6月12日	所检项目合格		 A worker in a blue uniform and red helmet is operating a machine with a steering wheel. The worker is wearing a red helmet and a blue uniform. The machine has a steering wheel and some controls. The background shows an indoor setting with some equipment. The date 2025 05 14 is visible in the bottom right corner of the image.



195	GX-B1328/20-6-25149	2025/6/10	本次共检绝缘手套4只, 4只绝缘手套合格。	
196	GX-B1328/20-6-25150	2025/6/10	本次共检全橡胶绝缘胶靴4只, 4只全橡胶绝缘胶靴合格。	
197	GX-B1305/21-6-25011	2025/6/12	综合判定：合格。	


198	GX-B1305/21-6-25012	2025/6/12	本次共检全橡胶绝缘胶靴4只，4只全橡胶绝缘胶靴合格。 。	
199	GX-B1328/20-6-25117	2025年6月10日	本次共检绝缘手套101只，101只绝缘手套合格。	
200	GX-B1328/20-6-25118	2025年6月10日	本次共检绝缘手套33只，33只绝缘手套合格。	

201	GX-B1328/20-6-25119	2025年6月10日	本次共检验电器16支，16支验电器合格。	
202	GX-B1328/20-6-25120	2025年6月10日	本次共检验携带式接地和接地短路装置3组，3组携带式接地和接地短路装置合格。	
203	GX-B1328/20-6-25121	2025年6月10日	本次共检绝缘手套80只，80只绝缘手套合格。	

204	GX-B1328/20-6-25122	2025年6月10日	本次共检绝缘手套72只，72只绝缘手套合格。	
205	GX-B1328/20-6-25123	2025年6月10日	本次共检绝缘手套36只，36只绝缘手套合格。	
206	GX-B1328/20-6-25124	2025年6月10日	本次共检绝缘手套24只，24只绝缘手套合格。	

207	GX-B1328/20-6-25125	2025年6月10日	本次共检绝缘手套12只，12只绝缘手套合格。	
208	GX-B1328/20-6-25126	2025年6月10日	本次共检全橡胶绝缘胶靴14只，14只全橡胶绝缘胶靴合格。	
209	GX-B1328/20-6-25127	2025年6月10日	本次共检全橡胶绝缘胶靴26只，26只全橡胶绝缘胶靴合格。	

210	GX-B1328/20-6-25128	2025年6月10日	本次共检全橡胶绝缘胶靴2只，2只全橡胶绝缘胶靴合格。 。	
211	GX-B1328/20-6-25129	2025年6月10日	本次共检验电器2支，2支验电器合格。	
212	GX-B1328/20-6-25130	2025年6月10日	本次共检验携带式接地和接地短路装置2组，2组携带式接地和接地短路装置合格。	

213	GX-B1328/20-6-25131	2025年6月10日	本次共检验绝缘杆2组，2组绝缘杆合格。 。	
214	GX-B1423/20-2501897TH1	2025/6/12	综合判定：合格。	
215	GX-B1423/20-2501898TH1	2025/6/12	综合判定：合格。	

216	GX-B1423/20-2501899TH1	2025/6/12	综合判定：合格。		
217	GX-B1423/20-2501900TH1	2025/6/12	综合判定：合格。		
218	GX-B1423/20-2501901TH1	2025/6/12	综合判定：合格。		

219	GX-B1423/20-2501902TH1	2025/6/12	综合判定：合格。	
220	GX-B1423/20-2501904TH1	2025/6/12	综合判定：合格。	
221	GX-B1423/20-2501905TH1	2025/6/12	综合判定：合格。	

222	GX-B1423/20-2501906TH1	2025/6/12	综合判定：合格。		
223	GX-B1423/20-2501908TH1	2025/6/12	综合判定：合格。		
224	GX-B1423/20-2501909TH1	2025/6/12	综合判定：合格。		

225	GX-B1423/20-2501911TH1	2025/6/12	综合判定：合格。		
226	GX-B1423/20-2501912TH1	2025/6/12	综合判定：合格。		
227	GX-B1423/20-2501960TH1	2025/6/12	综合判定：合格。		

228	GX-B1423/20-2501963TH1	2025/6/12	综合判定：合格。	
229	GX-B1423/20-2501979TH1	2025/6/12	综合判定：合格。	
230	GX-B1423/20-2501946TH1	2025/6/12	综合判定：合格。	

231	GX-B1423/20-2502025TH1	2025/6/12	综合判定：合格。			
232	GX-B1423/20-2501977TH1	2025/6/12	综合判定：合格。			
233	GX-B1423/20-2501969TH1	2025/6/12	综合判定：合格。			



234	GX-B1423/20-2501973TH1	2025/6/12	综合判定：合格。	
235	GX-B1423/20-2502024TH1	2025/6/12	综合判定：合格。	
236	GX-B1423/20-2502010TH1	2025/6/12	综合判定：合格。	

237	GX-B1423/20-2502005TH1	2025/6/12	综合判定：合格。		
238	GX-B1423/20-2502003TH1	2025/6/12	综合判定：合格。		
239	GX-B1423/20-2502002TH1	2025/6/12	综合判定：合格。		

240	GX-B1423/20-2501971TH1	2025/6/12	综合判定：合格。	
241	GX-B1423/20-2501961TH1	2025/6/12	综合判定：合格。	
242	GX-B1423/20-2502008TH1	2025/6/12	综合判定：合格。	

243	GX-B1423/20-2501999TH1	2025/6/12	综合判定：合格。		
244	GX-B1423/20-2502007TH1	2025/6/12	综合判定：合格。		
245	GX-B1423/20-2502015TH1	2025/6/12	综合判定：合格。		

246	GX-B1423/20-2502014TH1	2025/6/12	综合判定：合格。		
247	GX-B1423/20-2501945TH1	2025/6/12	综合判定：合格。		
248	GX-B1423/20-2501947TH1	2025/6/12	综合判定：合格。		


249	GX-B1423/20-2501950TH1	2025/6/12	综合判定：合格。	
250	GX-B1423/20-2501952TH1	2025/6/12	综合判定：合格。	
251	GX-B1423/20-2501955TH1	2025/6/12	综合判定：合格。	

252	GX-B1423/20-2501957TH1	2025/6/12	综合判定：合格。	
253	GX-B1423/20-2501958TH1	2025/6/12	综合判定：合格。	
254	GX-B1423/20-2501959TH1	2025/6/12	综合判定：合格。	

255	GX-B1423/20-2501964TH1	2025/6/12	综合判定：合格。	
256	GX-B1423/20-2501965TH1	2025/6/12	综合判定：合格。	
257	GX-B1423/20-2501968TH1	2025/6/12	综合判定：合格。	

258	GX-B1423/20-2502001TH1	2025/6/12	综合判定：合格。	
259	GX-B1423/20-2502054TH1	2025/6/12	综合判定：合格。	
260	GX-B1423/20-2502185TH1	2025/6/12	综合判定：合格。	

261	GX-B1423/20-2502186TH1	2025/6/12	综合判定：合格。	
262	GX-B1423/20-2502332TH1	2025/6/12	综合判定：合格。	
263	GX-B1495/25-6-251119~251124	2025年6月12日	本次共检高压防爆开关6台, 6台高压防爆开关所检项目合格。	

264	GX-B1321/20-6-25597~25600	2025年6月13日	本次共检电力电缆4条，4条电力电缆所检项目合格。	
265	GX-B1323/21-6-25148~25149	2025年6月12日	所检项目合格	
266	GX-B1328/20-6-25153	2025/6/13	本次共检验电器2支，2支验电器合格。	

267	GX-B1309/21-6-25020	2025年6月12日	所检项目合格			
268	GX-B1500/21-6-25094	2025年6月12日	综合判定：合格			
269	GX-B1500/21-6-25095	2025年6月12日	综合判定：合格			

270	GX-B1500/21-6-25096	2025年6月12日	综合判定：合格	
271	GX-B1500/21-6-25097	2025年6月12日	综合判定：合格	
272	GX-B1500/21-6-25098	2025年6月12日	综合判定：合格	

273	GX-B1309/21-6-25019	2025年6月12日	所检项目合格		 A worker in an orange safety suit and helmet is holding a device in a tunnel. The date 2025 05 13 is visible in the bottom right corner of the image.	
274	GX-B1500/21-6-25088	2025年6月12日	综合判定：合格		 A worker in an orange safety suit and helmet is standing next to a blue machine in a tunnel. The date 2025 05 13 is visible in the bottom right corner of the image.	
275	GX-B1500/21-6-25089	2025年6月12日	综合判定：合格		 A worker in an orange safety suit and helmet is standing next to a blue machine in a tunnel. The date 2025 05 13 is visible in the bottom right corner of the image.	

276	GX-B1500/21-6-25090	2025年6月12日	综合判定：合格		
277	GX-B1500/21-6-25091	2025年6月12日	综合判定：合格		
278	GX-B1500/21-6-25092	2025年6月12日	综合判定：合格		

279	GX-B1500/21-6-25093	2025年6月12日	综合判定：合格			
280	GX-B1534/20-6-25024	2025年6月12日	所检项目合格			
281	GX-B1534/20-6-25025	2025年6月12日	所检项目合格			

282	GX-B1534/20-6-25026	2025年6月12日	所检项目合格			
283	GX-B1534/20-6-25027	2025年6月12日	所检项目合格			
284	GX-B1534/20-6-25028	2025年6月12日	所检项目合格			

285	GX-B1534/20-6-25029	2025年6月12日	所检项目合格	
286	GX-B1534/20-6-25030	2025年6月12日	所检项目合格	
287	GX-B1534/20-6-25031	2025年6月12日	所检项目合格	

288	GX-B1534/20-6-25032	2025年6月12日	所检项目合格	
289	GX-B1534/20-6-25033	2025年6月12日	所检项目合格	
290	GX-B1534/20-6-25034	2025年6月12日	所检项目合格	

291	GX-B1598/24-6-25071	2025年6月14日	实测钢丝绳有效截面积损失百分比最大为0.45%，小于5%为正常。	
292	GX-B1598/24-6-25072	2025年6月14日	实测钢丝绳有效截面积损失百分比最大为0.32%，小于5%为正常。	
293	GX-B1598/24-6-25073	2025年6月14日	实测钢丝绳有效截面积损失百分比最大为0.43%，小于5%为正常。	

294	GX-B1598/24-6-25074	2025年6月14日	实测钢丝绳有效截面损失百分比最大为0.37%，小于5%为正常。	
295	GX-B1598/24-6-25075	2025年6月14日	实测钢丝绳有效截面损失百分比最大为1.94%，小于5%为正常。	
296	GX-B1598/24-6-25076	2025年6月14日	实测钢丝绳有效截面损失百分比最大为2.11%，小于5%为正常。	

297	GX-B1321/20-6-25606~25613	2025年6月13日	本次共检电力电缆8条，8条电力电缆所检项目合格。	
298	GX-B1321/20-6-25601~25605	2025年6月13日	本次共检电力电缆5条，5条电力电缆所检项目合格。	
299	GX-B1495/25-6-251138~251153	2025年6月12日	本次共检高压开关柜16台，16台高压开关柜所检项目合格。	

300	GX-B1495/25-6-251194~251208	2025年6月12日	本次共检高压开关设备15台，15台高压开关设备所检项目合格。	
301	GX-B1495/25-6-251209~251219	2025年6月12日	本次共检高压防爆开关11台，11台高压防爆开关所检项目合格。	
302	GX-B1310/21-6-25171	2025年6月16日	符合标准要求	

303	GX-B1310/21-6-25172	2025年6月16日	符合标准要求		
-----	---------------------	------------	--------	---	--