

序号	报告编号	发布日期	结论	影像资料	
27	GX-B1362/23-A-25181	2025/6/3	所检项目合格		
28	GX-B1362/23-A-25182	2025/6/3	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
29	GX-B1362/23-A-25183	2025/6/3	所检项目合格		
30	GX-B1362/23-A-25184	2025/6/3	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
31	GX-B1362/23-A-25185	2025/6/3	所检项目合格	
32	GX-B1362/23-A-25186	2025/6/3	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1362/23-A-25187	2025/6/3	所检项目合格	
34	GX-B1362/23-A-25213	2025/6/3	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
35	GX-B1362/23-A-25214	2025/6/3	合格		
36	GX-B1361/22-A-25604	2025/6/3	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
37	GX-B1361/22-A-25605	2025/6/3	所检项目合格		
38	GX-B1361/22-A-25606	2025/6/3	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
39	GX-B1362/23-A-25223	2025/6/5	合格		 A photograph showing two male workers in light-colored short-sleeved shirts operating a large industrial machine, possibly a lathe or mill, in a workshop. The machine is light-colored with a dark circular opening. The worker on the left is adjusting the machine, while the worker on the right is holding a piece of wood. A yellow date stamp '2025/5/30' is visible in the bottom right corner of the image.
40	GX-B1362/23-A-25224	2025/6/5	合格		 A photograph showing two male workers in light-colored short-sleeved shirts operating a large industrial machine, possibly a lathe or mill, in a workshop. The machine is light-colored with a dark circular opening. The worker on the left is adjusting the machine, while the worker on the right is holding a piece of wood. A yellow date stamp '2025/5/30' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
41	GX-B1362/23-A-25225	2025/6/5	合格		
42	GX-B1361/22-A-25612	2025/6/5	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
43	GX-B1361/22-A-25613	2025/6/5	所检项目合格		 A photograph showing a worker in a light-colored uniform operating a large industrial machine in a factory. The machine is white and yellow. The worker is standing and looking at the machine. The background shows other industrial equipment and a bright light fixture on the ceiling. A yellow date stamp '2025/5/30' is visible in the bottom right corner of the image.
44	GX-B1361/22-A-25614	2025/6/5	所检项目合格		 A photograph showing a worker in a light-colored uniform operating a large industrial machine in a factory. The worker is wearing gloves and is focused on the task. The machine is white and yellow. The background shows other industrial equipment and a bright light fixture on the ceiling. A yellow date stamp '2025/5/30' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
45	GX-B1362/23-A-25215	2025/6/9	所检项目合格		
46	GX-B1362/23-A-25216	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
47	GX-B1362/23-A-25217	2025/6/9	所检项目合格		
48	GX-B1362/23-A-25218	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
49	GX-B1362/23-A-25219	2025/6/9	所检项目合格		
50	GX-B1362/23-A-25220	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
51	GX-B1362/23-A-25221	2025/6/9	所检项目合格		
52	GX-B1362/23-A-25222	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
53	GX-B1361/22-A-25615	2025/6/9	所检项目合格		
54	GX-B1361/22-A-25616	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
55	GX-B1361/22-A-25617	2025/6/9	所检项目合格		
56	GX-B1361/22-A-25618	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
57	GX-B1361/22-A-25619	2025/6/9	所检项目合格		 A photograph showing a male worker in a light-colored short-sleeved shirt and dark pants operating a lathe machine. He is wearing white gloves and is focused on his work. The machine is a large, industrial-grade lathe with a wooden base. In the background, another worker is visible, also working on a machine. The date '2025/6/2' is printed in yellow in the bottom right corner of the image.
58	GX-B1361/22-A-25620	2025/6/9	所检项目合格		 A photograph showing two male workers in a workshop. One worker is operating a machine, possibly a lathe or a similar industrial machine, while the other worker stands next to him, observing or assisting. Both workers are wearing light-colored short-sleeved shirts and dark pants. The machine is a large, industrial-grade machine with a wooden base. The date '2025/6/2' is printed in yellow in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
59	GX-B1361/22-A-25621	2025/6/9	所检项目合格		
60	GX-B1361/22-A-25622	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
61	GX-B1361/22-A-25623	2025/6/9	所检项目合格		
62	GX-B1361/22-A-25624	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
63	GX-B1361/22-A-25625	2025/6/9	所检项目合格		
64	GX-B1361/22-A-25626	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
65	GX-B1361/22-A-25627	2025/6/9	所检项目合格		
66	GX-B1361/22-A-25628	2025/6/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
67	GX-B1361/22-A-25629	2025/6/9	所检项目合格	
68	GX-B1361/22-A-25630	2025/6/10	合格	

序号	报告编号	发布日期	结论	影像资料	
69	GX-B1361/22-A-25631	2025/6/10	合格		
70	GX-B1361/22-A-25632	2025/6/10	合格		

序号	报告编号	发布日期	结论	影像资料	
71	GX-B1361/22-A-25633	2025/6/10	合格		
72	GX-B1361/22-A-25634	2025/6/10	合格		

序号	报告编号	发布日期	结论	影像资料	
73	GX-B1361/22-A-25635	2025/6/10	合格		
74	GX-B1361/22-A-25636	2025/6/10	合格		

序号	报告编号	发布日期	结论	影像资料	
75	GX-B1361/22-A-25637	2025/6/10	不合格		
76	GX-B1361/22-A-25638	2025/6/11	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
77	GX-B1361/22-A-25639	2025/6/11	合格		
78	GX-B1361/22-A-25640	2025/6/11	合格		

序号	报告编号	发布日期	结论	影像资料	
79	GX-B1361/22-A-25641	2025/6/13	所检项目合格		 2025/6/6
80	GX-B1361/22-A-25642	2025/6/13	所检项目合格		 2025/6/6

序号	报告编号	发布日期	结论	影像资料
81	GX-B1361/22-A-25643	2025/6/12	所检项目合格	
82	GX-B1361/22-A-25644	2025/6/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
83	GX-B1361/22-A-25645	2025/6/12	所检项目合格		
84	GX-B1361/22-A-25646	2025/6/12	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
85	GX-B1361/22-A-25647	2025/6/12	所检项目合格		
86	GX-B1361/22-A-25648	2025/6/12	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
87	GX-B1361/22-A-25649	2025/6/12	所检项目合格	