

序号	报告编号	发布日期	结论	影像资料
85	GX-B1509/20-A-25015	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
86	GX-B1509/20-A-25016	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
87	GX-B1509/20-A-25017	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
88	GX-B1509/20-A-25018	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
89	GX-B1363/22-A-25332	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
90	GX-B1363/22-A-25318	2025/6/6	所检项目合格。	 A photograph showing two male technicians in light blue short-sleeved shirts and dark trousers inspecting a large, rusted industrial furnace. The furnace door is open, revealing internal components. One technician is on the left, looking into the furnace, while the other is on the right, also looking inside. A large green industrial fan stands to the right of the furnace. The background shows a window with a view of greenery outside.

序号	报告编号	发布日期	结论	影像资料
91	GX-B1363/22-A-25334	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
92	GX-B1364/22-A-25607	2025/6/9	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
93	GX-B1364/22-A-25608	2025/6/9	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
94	GX-B1364/22-A-25609	2025/6/9	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
95	GX-B1364/22-A-25610	2025/6/9	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
96	GX-B1364/22-A-25611	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
97	GX-B1364/22-A-25612	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
98	GX-B1364/22-A-25613	2025/6/9	所检项目合格。	 A photograph showing two male technicians in white short-sleeved uniforms with a logo on the back, inspecting a large, dark-colored industrial machine. The machine has a digital display and various control buttons. The technician on the right is wearing safety glasses. The background is a simple industrial setting with a white wall and a red door. A timestamp '2025 06 03' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
99	GX-B1364/22-A-25614	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
100	GX-B1367/22-A-25052	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
101	GX-B1367/22-A-25049	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
102	GX-B1367/22-A-25047	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
103	GX-B1367/22-A-25048	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
104	GX-B1363/22-A-25333	2025/6/6	所检项目合格。	 A photograph showing two male technicians in light blue uniforms inspecting a large, rusted industrial furnace. One technician is on the left, looking at a digital display on the furnace's control panel. The other is on the right, wearing gloves and looking into the open furnace door. A large black fan stands to the right of the furnace. The background shows a window with curtains and a white wall. An orange timestamp '2025.06.05' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
105	GX-B1363/22-A-25335	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
106	GX-B1363/22-A-25336	2025/6/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
107	GX-B1363/22-A-25330	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
108	GX-B1363/22-A-25331	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
109	GX-B1363/22-A-25328	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
110	GX-B1363/22-A-25337	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
111	GX-B1363/22-A-25338	2025/6/10	所检项目合格。	 A photograph showing two male technicians in light blue short-sleeved shirts and dark trousers inspecting a large, rusted industrial furnace. The technician on the right has a logo on his shirt that reads '中检公信'. The furnace is a large, boxy metal structure with a vertical pipe on top. To the right of the furnace is a green floor-standing fan. The background shows a window with a view of trees outside. In the bottom right corner of the photo, there is an orange date stamp that reads '2025.06.08'.

序号	报告编号	发布日期	结论	影像资料
112	GX-B1363/22-A-25339	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
113	GX-B1363/22-A-25320	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
114	GX-B1364/22-A-25590	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
115	GX-B1364/22-A-25591	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
116	GX-B1364/22-A-25592	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
117	GX-B1364/22-A-25593	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
118	GX-B1364/22-A-25594	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
119	GX-B1364/22-A-25595	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
120	GX-B1364/22-A-25596	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
121	GX-B1364/22-A-25597	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
122	GX-B1364/22-A-25598	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
123	GX-B1364/22-A-25599	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
124	GX-B1364/22-A-25600	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
125	GX-B1364/22-A-25601	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
126	GX-B1364/22-A-25602	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
127	GX-B1364/22-A-25603	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
128	GX-B1364/22-A-25604	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
129	GX-B1364/22-A-25605	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
130	GX-B1364/22-A-25606	2025/6/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
131	GX-B1363/22-A-25342	2025/6/11	全厚度拉伸强度 为； 1503N/mm ； 全厚度拉断伸长率为； 31%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
132	GX-B1363/22-A-25340	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
133	GX-B1363/22-A-25339	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
134	GX-B1509/20-A-25022	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
135	GX-B1509/20-A-25023	2025/6/11	所检项目合格。	 A photograph showing two male workers in light blue short-sleeved uniforms and glasses. They are standing in a factory or laboratory setting, looking down at a workbench. The workbench has a green frame and a clear plastic cover. There are some yellow papers or documents on the table. In the background, there are white walls and a window with yellow curtains. A timestamp '2025.06.06' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
136	GX-B1364/22-A-25615	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
137	GX-B1364/22-A-25616	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
138	GX-B1364/22-A-25617	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
139	GX-B1364/22-A-25623	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
140	GX-B1364/22-A-25624	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
141	GX-B1538/22-A-25052	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
142	GX-B1538/22-A-25053	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
143	GX-B1538/22-A-25054	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
144	GX-B1538/22-A-25055	2025/6/10	所检项目合格。	 A photograph showing two technicians in white uniforms inspecting a large industrial machine in a workshop. The machine has a dark grey door and a red door. The technicians are standing in front of the machine, looking at it. The workshop has a window on the right side. The date 2025.06.06 is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
145	GX-B1538/22-A-25056	2025/6/10	所检项目合格。	 A photograph showing two male technicians in light grey lab coats working in a laboratory or industrial setting. They are standing in front of a large, dark grey piece of equipment, possibly a furnace or a large container. The technician on the left is wearing safety glasses and is looking down at something. The technician on the right is also looking down. In the background, there is a red door and a window. A timestamp '2025.06.06' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
146	GX-B1538/22-A-25057	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
147	GX-B1538/22-A-25058	2025/6/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
148	GX-B1509/20-A-25019	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
149	GX-B1509/20-A-25020	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
150	GX-B1509/20-A-25021	2025/6/11	所检项目合格。	 A photograph showing two individuals in light blue lab coats working in a laboratory or inspection area. They are positioned in front of a whiteboard and a workbench. The person on the right is wearing glasses and looking down at a device. The person on the left is seen from the back. An orange timestamp '2025.06.06' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
151	GX-B1364/22-A-25618	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
152	GX-B1364/22-A-25619	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
153	GX-B1364/22-A-25620	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
154	GX-B1364/22-A-25621	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
155	GX-B1364/22-A-25622	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
156	GX-B1368/20-A-25002	2025/6/11	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
157	GX-B1364/22-A-25635	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
158	GX-B1364/22-A-25636	2025/6/11	成束燃烧试验不合格； 其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
159	GX-B1538/22-A-25061	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
160	GX-B1538/22-A-25062	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
161	GX-B1538/22-A-25059	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1538/22-A-25060	2025/6/13	所检项目不合格。	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1509/20-A-25024	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1509/20-A-25025	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
165	GX-B1364/22-A-25625	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
166	GX-B1364/22-A-25639	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1363/22-A-25341	2025/6/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
168	GX-B1365/25-A—25062	2025/6/16	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
169	GX-B1365/25-A—25063	2025/6/16	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
170	GX-B1366/25-A—25073	2025/6/16	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
171	GX-B1365/25-A—25074	2025/6/16	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
172	GX-B1365/25-A—25075	2025/6/16	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
173	GX-B1363/22-A—25348	2025/6/13	所检项目合格。	 A photograph showing two men in white uniforms inspecting a large, rusted industrial furnace. One man is on the left, looking into the open furnace door. The other man is on the right, standing with his back to the camera, looking at the furnace. A large black fan is positioned to the right of the furnace. The background shows a window with curtains and a wall. The date '2025.06.12' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
174	GX-B1363/22-A—25345	2025/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
175	GX-B1363/22-A—25346	2025/6/13	所检项目合格。	