

序号	报告编号	发布日期	结论	影像资料
252	GX-B1523/20-2-25001	2025. 6. 16	所检项目合格。	
253	GX-B1534/20-2-25035	2025. 6. 20	所检项目合格。	

254	GX-B1534/20-2-25036	2025. 6. 20	所检项目合格。	
255	GX-B1534/20-2-25037	2025. 6. 20	所检项目合格。	

256	GX-B1534/20-2-25038	2025. 6. 20	所检项目合格。	 A photograph showing two workers wearing red hard hats and light blue shirts standing next to a yellow vehicle, possibly a forklift or a small truck, outdoors. The date stamp '2025/06/20' is visible in the bottom right corner of the image.
257	GX-B1534/20-2-25039	2025. 6. 20	所检项目合格。	 A photograph showing a worker wearing a red hard hat, safety glasses, and a light blue shirt. The worker is standing outdoors, and a yellow vehicle is visible in the background. The date stamp '2025/06/20' is visible in the bottom right corner of the image.

258	GX-B1534/20-2-25040	2025. 6. 20	所检项目合格。	
259	GX-B1534/20-2-25041	2025. 6. 20	所检项目合格。	

260	GX-B1534/20-2-25042	2025. 6. 20	所检项目合格。	
261	GX-B1534/20-2-25043	2025. 6. 20	所检项目合格。	

262	GX-B1574/20-2-25024	2025. 6. 21	所检项目合格。	
263	GX-B1574/20-2-25025	2025. 6. 21	所检项目合格。	

264	GX-B1574/20-2-25026	2025. 6. 21	所检项目合格。	
265	GX-B1574/20-2-25027	2025. 6. 21	所检项目合格。	

266	GX-B1574/20-2-25028	2025. 6. 21	所检项目合格。	 A photograph showing a worker wearing a red hard hat and a light-colored shirt operating a yellow forklift. The forklift is parked on a paved surface, and the worker is seated in the operator's compartment. A date stamp "2025/06/20" is visible in the bottom right corner of the image.
267	GX-B1574/20-2-25029	2025. 6. 21	所检项目合格。	 A photograph showing a worker wearing a red hard hat and a light-colored shirt operating a yellow forklift. The forklift is parked on a paved surface, and the worker is seated in the operator's compartment. A date stamp "2025/05/28" is visible in the bottom right corner of the image.

268	GX-B1574/20-2-25030	2025. 6. 21	所检项目合格。	
269	GX-B1574/20-2-25031	2025. 6. 21	所检项目合格。	

270	GX-B1574/20-2-25032	2025. 6. 21	所检项目合格。	
271	GX-B1574/20-2-25033	2025. 6. 21	所检项目合格。	


272	GX-B1574/20-2-25034	2025. 6. 21	所检项目合格。	
273	GX-B1574/20-2-25035	2025. 6. 21	所检项目合格。	

274	GX-B1574/20-2-25036	2025. 6. 21	所检项目合格。	
275	GX-B1574/20-2-25037	2025. 6. 21	所检项目合格。	

276	GX-B1574/20-2-25038	2025. 6. 21	所检项目合格。	
277	GX-B1574/20-2-25039	2025. 6. 21	所检项目合格。	

278	GX-B1574/20-2-25040	2025. 6. 21	所检项目合格。	
279	GX-B1574/20-2-25041	2025. 6. 21	所检项目合格。	

280	GX-B1451/20-2-25684~25704	2025. 6. 23	本次共检高压开关柜21台，21台所检项目合格。	 2025/05/17	
281	GX-B1611/23-2-25011	2025. 6. 24	所检项目合格。	 2025/05/17	

282	GX-B1611/23-2-25012	2025. 6. 24	所检项目合格。	
283	GX-B1611/23-2-25013	2025. 6. 24	所检项目合格。	

284	GX-B1611/23-2-25014	2025. 6. 24	所检项目合格。	
285	GX-B1611/23-2-25015	2025. 6. 24	所检项目合格。	

286	GX-B1611/23-2-25016	2025. 6. 24	所检项目合格。	
287	GX-B1611/23-2-25017	2025. 6. 24	所检项目合格。	

288	GX-B1611/23-2-25018	2025. 6. 24	所检项目合格。	
289	GX-B1611/23-2-25019	2025. 6. 24	所检项目合格。	

290	GX-B1611/23-2-25020	2025. 6. 24	所检项目合格。	
291	GX-B1310/21-2-25133	2025. 06. 26	符合标准要求。	

292	GX-B1310/21-2-25132	2025. 06. 26	符合标准要求。	
293	GX-B1310/21-2-25131	2025. 06. 26	符合标准要求。	

294	GX-B1322/21-2-25425~25438	2025. 06. 30	本次共检验电力电缆14条，14条电力电缆所检项目合格。	 A photograph showing a worker in a red hard hat and safety gear working on electrical equipment. The worker is wearing a light blue shirt and a red hard hat with a headlamp. The background is dark and industrial. The date 2025/05/17 is visible in the bottom right corner of the image.
-----	---------------------------	--------------	-----------------------------	--