

序号	报告编号	发布日期	结论	影像资料
10	GX-B1495/25-2-25284~25290	2025. 7. 3	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
11	GX-B1495/25-2-25291~25299	2025. 7. 3	本次共检互感器9组，9组互感器所检项目合格。	
12	GX-B1495/25-2-25300~25304	2025. 7. 3	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	

13	GX-B1495/25-2-25305~25309	2025. 7. 3	本次共检互感器5组，5组互感器所检项目合格。			
14	GX-B1495/25-2-25310~25316	2025. 7. 3	本次共检高压开关柜7台，7台高压开关柜所检项目合格。			
15	GX-B1495/25-2-25317~25323	2025. 7. 3	本次共检互感器7组，7组互感器所检项目合格。			

16	GX-B1323/21-2-25046~25048	2025. 7. 4	所检项目合格。	
17	GX-B1495/25-2-25264~25274	2025. 07. 03	本次共检高压开关设备11台，11台所检项目合格。	
18	GX-B1495/25-2-25721~25728	2025. 07. 03	本次共检防爆型高压配电装置8台，8台所检项目合格。	

19	GX-B1312/20-2-25086	45842	所检项目合格		
20	GX-B1312/20-2-25079~25081	45842	所检项目合格		
21	GX-B1312/20-2-25078	45842	所检项目合格		

22	GX-B1547/20-2-25007~25010	2025.07.02	本次共检继电保护装置4台，4台所检项目合格。	
23	GX-B1321/20-2-25207~25210	2025.7.3	本次共检验电力电缆4条，4条所检项目合格。	
24	GX-B1321/20-2-25211~25218	2025.7.3	本次共检验电力电缆8条，8条所检项目合格。	

25	GX-B1404/20-2-25014	2025. 7. 8	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		
26	GX-B1404/20-2-25015	2025. 7. 8	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		
27	GX-B1495/25-2-25275~25283	2025. 7. 9	<p>本次共检防爆型高压配电装置9台，9台所检项目合格。</p>		

28	GX-B1312/20-2-25082~25085	2025. 7. 10	本次共检电力变压器4台，4台所检项目合格。	
29	GX-B1321/20-2-25201~25206	2025. 7. 10	本次共检验电力电缆6条,6条所检项目合格。	
30	GX-B1301/25-2-25015	2025. 07. 11	综合判定:合格。	

31	GX-B1301/25-2-25016	2025.07.11	综合判定:合格。	
32	GX-B1301/25-2-25017	2025.07.11	综合判定:合格。	
33	GX-B1301/25-2-25018	2025.07.11	综合判定:合格。	

34	GX-B1310/21-2-25134	2025.07.11	符合标准要求。		
35	GX-B1427/21-2-25134	2025.07.11	符合标准要求。		
36	GX-B1310/21-2-25135	2025.07.11	符合标准要求。		

37	GX-B1427/21-2-25135	2025.07.11	符合标准要求。	 <p>2025/06/25</p>
38	GX-B1310/21-2-25136	2025.07.11	符合标准要求。	 <p>2025/06/26</p>
39	GX-B1427/21-2-25136	2025.07.11	符合标准要求。	 <p>2025/06/26</p>

40	GX-B1310/21-2-25137	2025. 07. 11	符合标准要求。	
41	GX-B1427/21-2-25137	2025. 07. 11	符合标准要求。	
42	GX-B1310/21-2-25147	2025. 07. 11	符合标准要求。	

43	GX-B1428/21-2-25147	2025.07.11	无缺陷迹痕显示。	 A worker wearing a red helmet and dark clothing is kneeling in a dark environment, using a flashlight to inspect a surface. A date stamp '2025/07/04' is visible in the bottom right corner of the photo.
44	GX-B1310/21-2-25148	2025.07.11	符合标准要求。	 Two workers wearing red hard hats are standing in a well-lit indoor setting. One worker is in the foreground, and another is slightly behind. A date stamp '2025/07/04' is visible in the bottom right corner of the photo.
45	GX-B1428/21-2-25148	2025.07.11	无缺陷迹痕显示。	 A worker wearing a red helmet and dark clothing is kneeling in a dark environment, using a flashlight to inspect a surface. Two red bottles are on the ground next to the worker. A date stamp '2025/07/04' is visible in the bottom right corner of the photo.

46	GX-B1310/21-2-25130	2025.07.11	符合标准要求。		
----	---------------------	------------	---------	--	---