

序号	报告编号	发布日期	结论	影像资料
3	GX-B1417/22-2500836TH1	2025年7月15日	综合判定：合格	

4	GX-B1417/22-2500837TH1	2025年7月15日	综合判定：合格	
5	GX-B1417/22-2500839TH1	2025年7月15日	综合判定：合格	

6	GX-B1417/22-2500840TH1	2025年7月15日	综合判定：合格	
7	GX-B1417/22-2500842TH1	2025年7月15日	综合判定：合格	

8	GX-B1417/22-2500843TH1	2025年7月15日	综合判定：合格	
9	GX-B1417/22-2500845TH1	2025年7月15日	综合判定：合格	

10	GX-B1417/22-2500847TH1	2025年7月15日	综合判定：合格	
11	GX-B1417/22-2500848TH1	2025年7月15日	综合判定：合格	

12	GX-B1417/22-2500849TH1	2025年7月15日	综合判定：合格	
13	GX-B1417/22-2500850TH1	2025年7月15日	综合判定：合格	

14	GX-B1417/22-2500851TH1	2025年7月15日	综合判定：合格	
15	GX-B1417/22-2500852TH1	2025年7月15日	综合判定：合格	

16	GX-B1417/22-2500854TH1	2025年7月15日	综合判定：合格	
17	GX-B1417/22-2500857TH1	2025年7月15日	综合判定：合格	

18	GX-B1417/22-2500858TH1	2025年7月15日	综合判定：合格	
19	GX-B1417/22-2500859TH1	2025年7月15日	综合判定：合格	

20	GX-B1417/22-2500860TH1	2025年7月15日	综合判定：合格	 <p>A photograph showing a white truck parked in front of a blue building. Two workers, one in a white uniform and red helmet, and another in a dark blue uniform and blue helmet, are standing next to the truck. The license plate is visible. A yellow timestamp '2025/5/17' is in the bottom right corner.</p>
21	GX-B1417/22-2500862TH1	2025年7月15日	综合判定：合格	 <p>A photograph showing a yellow forklift parked on a wet surface in front of a blue building. Two workers, one in a white uniform and red helmet, and another in a dark blue uniform and blue helmet, are standing next to the forklift. The building has the Chinese characters '资产提质' (Asset Quality Improvement) written on it. A yellow timestamp '2025/5/17' is in the bottom right corner.</p>

22	GX-B1417/22-2500863TH1	2025年7月15日	综合判定：合格	 <p>A photograph showing two workers in safety gear standing in front of a white truck. The truck has a license plate that reads '常州' (Changzhou). In the background, a large building has red Chinese characters '管理提效 资产' (Management Improves Efficiency, Assets) on its facade. A yellow timestamp '2025/5/17' is visible in the bottom right corner of the photo.</p>
23	GX-B1417/22-2500864TH1	2025年7月15日	综合判定：合格	 <p>A photograph showing two workers in safety gear standing in front of a white truck. The truck has a license plate that reads '常州' (Changzhou) and '科试' (Keshi) on its side. In the background, a building is visible. A yellow timestamp '2025/5/17' is visible in the bottom right corner of the photo.</p>

24	GX-B1417/22-2500872TH1	2025年7月15日	综合判定：合格	
25	GX-B1417/22-2500873TH1	2025年7月15日	综合判定：合格	

26	GX-B1417/22-2500874TH1	2025年7月15日	综合判定：合格	
27	GX-B1417/22-2500875TH1	2025年7月15日	综合判定：合格	

28	GX-B1417/22-2500876TH1	2025年7月15日	综合判定：合格	
29	GX-B1417/22-2500877TH1	2025年7月15日	综合判定：合格	

30	GX-B1417/22-2500878TH1	2025年7月15日	综合判定：合格	
31	GX-B1417/22-2500879TH1	2025年7月15日	综合判定：合格	

32	GX-B1417/22-2500880TH1	2025年7月15日	综合判定：合格	
33	GX-B1417/22-2500881TH1	2025年7月15日	综合判定：合格	

34	GX-B1417/22-2500882TH1	2025年7月15日	综合判定：合格	
35	GX-B1417/22-2500883TH1	2025年7月15日	综合判定：合格	

36	GX-B1417/22-2500884TH1	2025年7月15日	综合判定：合格	
37	GX-B1417/22-2500889TH1	2025年7月15日	综合判定：合格	

38	GX-B1417/22-2500941TH1	2025年7月15日	综合判定：合格	
39	GX-B1417/22-2501005TH1	2025年7月15日	综合判定：合格	

40	GX-B1417/22-2501158TH1	2025年7月15日	综合判定：合格	
----	------------------------	------------	---------	---