

序号	报告编号	发布日期	结论	影像资料
144	GX-B1363/22-A-25385	2025/7/10	所检项目合格。	 A photograph showing two male technicians in light blue work shirts inspecting a large, rusted industrial furnace. The technician on the left is looking into the open furnace door, while the one on the right is looking at a panel on the side. A timestamp '2025.07.03' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
145	GX-B1363/22-A-25387	2025/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
146	GX-B1363/22-A-25388	2025/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
147	GX-B1363/22-A-25389	2025/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
148	GX-B1364/22-A-25741	2025/7/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
149	GX-B1364/22-A-25742	2025/7/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
150	GX-B1538/22-A-25070	2025/7/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
151	GX-B1538/22-A-25071	2025/7/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
152	GX-B1367/22-A-25055	2025/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
153	GX-B1458/22-A-25014	2025/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
154	GX-B1458/22-A-25015	2025/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
155	GX-B1366/20-A-25080	2025/7/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
156	GX-B1364/22-A-25748	2025/7/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
157	GX-B1364/22-A-25749	2025/7/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
158	GX-B1365/25-A-25064	2025/7/11	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
159	GX-B1366/25-A-25078	2025/7/11	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
160	GX-B1364/22-A-25751	2025/7/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
161	GX-B1364/22-A-25752	2025/7/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1365/25-A-25065	2025/7/14	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1366/25-A-25079	2025/7/14	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1538/22-A-25072	2025/7/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
165	GX-B1363/22-A-25391	2025/7/11	所检项目合格。	 A photograph showing two male technicians in white short-sleeved uniforms inspecting a large, dark-colored industrial furnace or boiler. The furnace has a large rectangular door that is open. They are standing in a room with white walls and a large window in the background. A green trash bin is visible on the left. The date '2025.07.09' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
166	GX-B1363/22-A-25394	2025/7/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1364/22-A-25753	2025/7/15	所检项目合格。	 A photograph showing two male technicians in grey work uniforms inspecting a large, dark grey industrial machine. The machine has a control panel with several digital displays and buttons. A tall, white, segmented chimney stack is visible on top of the machine. The scene is indoors, with a window in the background. A date stamp '2025.07.12' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
168	GX-B1364/22-A-25754	2025/7/15	所检项目合格。	

	报告编号	发布日期	结论	影像资料
169	GX-B1364/22-A-25755	2025/7/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
170	GX-B1364/22-A-25756	2025/7/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
171	GX-B1364/22-A-25757	2025/7/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
172	GX-B1364/22-A-25758	2025/7/15	所检项目合格。	 A photograph showing two technicians in grey uniforms operating a large industrial machine. The technician on the left is seen from the back, wearing a uniform with a logo that reads '中检公信'. The technician on the right is facing the machine. The machine has a control panel with several green and red indicator lights. A vertical pipe is visible on top of the machine. The background shows a window with a view of trees outside. A timestamp '2025.07.12' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
173	GX-B1364/22-A-25759	2025/7/15	所检项目合格。	 A photograph showing two male technicians in white lab coats inspecting a large industrial machine. The technician on the right is looking at a control panel with a digital display and several analog gauges. The machine is dark-colored with a red door on the right. A yellow warning triangle is visible on the left side of the machine. The date '2025.07.12' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
174	GX-B1363/22-A-25397	2025/7/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
175	GX-B1363/22-A-25396	2025/7/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
176	GX-B1363/22-A-25395	2025/7/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
177	GX-B1538/22-A-25073	2025/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
178	GX-B1363/22-A-25392	2025/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
179	GX-B1363/22-A-25398	2025/7/17	所检项目合格。	