

序号	报告编号	发布日期	结论	影像资料
133	GX-B1310/21-1-25191	2025. 7. 17	符合标准要求。	
134	GX-B1310/21-1-25192	2025. 7. 17	符合标准要求。	

135	GX-B1310/21-1-25193	2025. 7. 17	符合标准要求。	 <p>2025/06/28</p>
136	GX-B1310/21-1-25194	2025. 7. 17	符合标准要求。	 <p>2025/06/28</p>
137	GX-B1312/20-1-25510	2025. 7. 22	所检项目合格。	 <p>2025/7/3</p>

138	GX-B1313/21-1-25130	2025. 7. 22	所检项目合格。	 <p>2025.6.28</p>
139	GX-B1313/21-1-25131~25133	2025. 7. 22	本次共检电力变压器3台，3台所检项目合格。	 <p>2025.6.28</p>
140	GX-B1313/21-1-25134~25136	2025. 7. 22	本次共检电力变压器3台，3台电力变压器所检项目合格。	 <p>2025.6.26</p>

141	GX-B1313/21-1-25137~25142	2025. 7. 22	本次共检电力变压器6台，6台电力变压器所检项目合格。	
142	GX-B1598/24-1-25062	2025. 7. 22	实测钢丝绳有效截面积损失百分比最大为3.04%，小于5%为正常。	
143	GX-B1598/24-1-25063	2025. 7. 22	实测钢丝绳有效截面积损失百分比最大为3.03%，小于5%为正常。	

144	GX-B1598/24-1-25064	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为2.86%，小于5%为正常。	
145	GX-B1598/24-1-25065	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为2.88%，小于5%为正常。	
146	GX-B1598/24-1-25066	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为3.43%，小于5%为正常。	

147	GX-B1598/24-1-25067	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为3.06%，小于5%为正常。	
148	GX-B1598/24-1-25068	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为3.29%，小于5%为正常。	
149	GX-B1598/24-1-25058	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为1.95%，小于5%为正常。	

150	GX-B1598/24-1-25059	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为2.26%，小于5%为正常。	
151	GX-B1598/24-1-25060	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为2.83%，小于5%为正常。	
152	GX-B1598/24-1-25061	2025. 7. 22	实测钢丝绳有效截面损失百分比最大为2.97%，小于5%为正常。	

153	GX-B1309/21-1-25026	2025. 7. 18	所检项目合格。	
154	GX-B1500/21-1-25096	2025. 7. 18	综合判定：合格。 。	
155	GX-B1500/21-1-25097	2025. 7. 18	综合判定：合格。 。	

156	GX-B1500/21-1-25098	2025. 7. 18	综合判定：合格。 。	
157	GX-B1309/21-1-25032	2025. 7. 18	所检项目合格。	
158	GX-B1500/21-1-25115	2025. 7. 18	综合判定：合格。 。	

159	GX-B1500/21-1-25116	2025. 7. 18	综合判定：合格。 。	
160	GX-B1500/21-1-25117	2025. 7. 18	综合判定：合格。 。	
161	GX-B1309/21-1-25031	2025. 7. 18	所检项目合格。	

162	GX-B1500/21-1-25112	2025. 7. 18	综合判定：合格。 。	
163	GX-B1500/21-1-25113	2025. 7. 18	综合判定：合格。 。	
164	GX-B1500/21-1-25114	2025. 7. 18	综合判定：合格。 。	

165	GX-B1310/21-1-25195	2025. 7. 28	符合标准要求。	
166	GX-B1310/21-1-25196	2025. 7. 28	符合标准要求	
167	GX-B1499/23-1-25008	2025. 7. 28	电耗超限外，其余所	

168	GX-B1499/23-1-25009	2025. 7. 28	电耗超限外，其余所检		
169	GX-B1499/23-1-25010	2025. 7. 28	电耗超限外，其余所检		
170	GX-B1559/22-1-25001	2025. 7. 28	所检项目合格。		

171	GX-B1559/22-1-25002	2025. 7. 28	所检项目合格。	
172	GX-B1310/21-1-25203	2025. 7. 28	符合标准要求	
173	GX-B1428/21-1-25197	2025. 7. 28	无缺陷迹痕显示。	

174	GX-B1428/21-1-25198	2025. 7. 28	无缺陷迹痕显示。		
175	GX-B1428/21-1-25199	2025. 7. 28	无缺陷迹痕显示。		
176	GX-B1428/21-1-25200	2025. 7. 28	无缺陷迹痕显示。		

177	GX-B1428/21-1-25201	2025. 7. 28	无缺陷迹痕显示。		 A photograph showing a close-up of a fan blade. A person wearing a red hard hat and a white shirt is visible in the background, looking towards the camera. A bright yellow light source is positioned near the blade, illuminating it. A yellow timestamp "2025/07/28" is visible in the bottom right corner of the photo.	
178	GX-B1428/21-1-25202	2025. 7. 28	无缺陷迹痕显示。		 A photograph showing a close-up of a fan blade. A person wearing a red hard hat and a white shirt is visible in the background, looking towards the camera. A bright yellow light source is positioned near the blade, illuminating it. A yellow timestamp "2025/07/28" is visible in the bottom right corner of the photo.	