

序号	报告编号	发布日期	结论	影像资料
3	GX-B1310/21-1-25205	2025. 8. 12	符合标准要求	
4	GX-B1310/21-1-25206	2025. 8. 12	符合标准要求	

5	GX-B1310/21-1-25207	2025. 8. 12	符合标准要求	
6	GX-B1427/21-1-25208	2025. 8. 12	符合标准要求	

7	GX-B1428/21-1-25209	2025. 8. 12	无缺陷迹痕显示		
8	GX-B1428/21-1-25210	2025. 8. 12	无缺陷迹痕显示		


9	GX-B1428/21-1-25211	2025. 8. 12	无缺陷迹痕显示	
10	GX-B1428/21-1-25212	2025. 8. 12	无缺陷迹痕显示	

11	GX-B1313/21-1-25143	2025. 8. 12	所检项目合格。	
12	GX-B1611/23-1-25009	2025. 8. 14	所检项目合格。	

13	GX-B1611/23-1-25010	2025. 8. 14	所检项目合格。	
14	GX-B1328/20-1-25080	202. 8. 18	本次共检绝缘手套 16只，16只绝缘手 套合格。	

15	GX-B1328/20-1-25081	202. 8. 18	本次共检绝缘靴16只，16只绝缘靴合格。	
16	GX-B1328/20-1-25082	202. 8. 18	本次共检验电器6支，6支验电器合格。	


17	GX-B1328/20-1-25083	202. 8. 18	本次共检携带型短路接地线3组，3组携带型短路接地线合格。	
18	GX-B1328/20-1-25084	202. 8. 18	本次共检绝缘杆3支，3支绝缘杆合格。	

19	GX-B1451/20-1-25444~25449	2025. 8. 18	本次共检高压开关柜6台，6台高压开关柜所检项目合格。 。	
20	GX-B1428/21-1-25214	2025. 8. 18	无缺陷迹痕显示。	

21	GX-B1428/21-1-25215	2025. 8. 18	无缺陷迹痕显示。	
22	GX-B1322/21-1-25244~25245	2025. 8. 18	本次共检电力电缆 2条，2条电力电缆 所检项目合格。	

23	GX-B1539/22-1-25007	2025. 8. 19	所检项目合格。		
24	GX-B1539/22-1-25008	2025. 8. 19	所检项目合格。		

25	GX-B1539/22-1-25009	2025. 8. 19	所检项目合格。	
26	GX-B1310/21-1-25213	2025. 8. 18	符合标准要求	

27	GX-B1313/21-1-25144~25146	2025. 8. 19	本次共检电力变压器3台，3台电力变压器所检项目合格。 。	
28	GX-B1313/21-1-25147~25151	2025. 8. 19	本次共检电力变压器5台，5台电力变压器所检项目合格。 。	

29	GX-B1612/23-1-25007	2025. 8. 21	所检项目合格。	
30	GX-B1612/23-1-25008	2025. 8. 21	所检项目合格。	

31	GX-B1612/23-1-25009	2025. 8. 21	所检项目合格。	
32	GX-B1313/21-1-25152~25153	2025. 8. 21	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	

33	GX-B1322/21-1-25246~25247	2025. 8. 21	本次共检验电力电缆2条，2条所检项目合格。	
34	GX-B1451/20-1-25450~25451	2028. 8. 21	本次共检高压开关柜2台, 2台高压开关柜所检项目合格。	



35	GX-B1350/21-1-25027	2025. 8. 21	所检项目合格。	
36	GX-B1328/20-1-25086	2025. 8. 25	本次共检绝缘手套 2只，2只绝缘手套 合格。	

37	GX-B1328/20-1-25085	2025. 8. 25	本次共检绝缘靴2只，2只绝缘靴合格。	
38	GX-B1328/20-1-25087	2025. 8. 25	本次共检验电器1支，1支验电器合格。	

39	GX-B1328/20-1-25088	2025. 8. 25	本次共检绝缘杆1套，1套绝缘杆合格。	 2025/8/15
40	GX-B1324/21-1-25050~25051	2025. 8. 25	所检项目合格。	 2025. 08. 16

41	GX-B1324/21-1-25052~25053	2025. 8. 25	所检项目合格。	
42	GX-B1322/21-1-25248~25251	2025. 8. 25	本次共检验电力 电缆4条，4条所检 项目合格。	

43	GX-B1322/21-1-25252~25255	2025. 8. 25	本次共检验电力 电缆4条，4条所检 项目合格。	
44	GX-B1451/20-1-25452~25455	2025. 8. 25	本次共检高压开关 设备4台，4台高压 开关设备所检项目 合格。	 地址：河北省张家口市张北县海流图乡 经度：114.34207264 纬度：41.30849871 拍照时间：2025-08-16 09:08:30

45	GX-B1350/21-1-25028	2025. 8. 25	本次共检接地装置 5处，5处接地装置 所检项目合格。	
46	GX-B1350/21-1-25029	2025. 8. 25	本次共检接地装置 5处，5处接地装置 所检项目合格。	

47	GX-B1451/20-1-25456~25459	2025. 8. 25	本次共检高压开关柜4台, 4台高压开关柜所检项目合格。	 地址: 河北省张家口市张北县海流图乡 经度: 114.34207264 纬度: 41.30849871 拍照时间: 2025-08-16 09:08:30
----	---------------------------	-------------	-----------------------------	--