




序号	报告编号	发布日期	结论	影像资料
36	GX-B1352/21-Y-25054~25068	2025. 6. 16	本次共检矿用防爆低压交流真空馈电开关15台, 15台矿用防爆低压交流真空馈电开关所检项目合格。	
37	GX-B1352/21-Y-25069~25075	2025. 6. 16	本次共检矿用防爆低压交流真空馈电开关7台, 7台矿用防爆低压交流真空馈电开关所检项目合格。	
38	GX-B1352/21-Y-25076~25090	2025. 6. 16	本次共检矿用防爆低压交流真空馈电开关15台, 15台矿用防爆低压交流真空馈电开关所检项目合格。	

39	GX-B1352/21-Y-25091~25110	2025. 6. 16	本次共检矿用防爆低压交流真空馈电开关20台, 20台矿用防爆低压交流真空馈电开关所检项目合格。		
40	GX-B1359/21-Y-25030~25038	2025. 6. 16	本次共检矿用隔爆型照明信号综合保护装置9台, 9台矿用隔爆型照明信号综合保护装置所检项目合格。		
41	GX-B1359/21-Y-25039~25043	2025. 6. 16	本次共检矿用隔爆型照明信号综合保护装置5台, 5台矿用隔爆型照明信号综合保护装置所检项目合格。		


42	GX-B1359/21-Y-25044~25048	2025. 6. 16	本次共检矿用隔爆型照明信号综合保护装置5台,5台矿用隔爆型照明信号综合保护装置所检项目合格。		
43	GX-B1359/21-Y-25049~25056	2025. 6. 16	本次共检矿用隔爆型照明信号综合保护装置8台,8台矿用隔爆型照明信号综合保护装置所检项目合格。		
44	GX-B1310/21-Y-25079	2025. 6. 16	符合标准要求。		

45	GX-B1310/21-Y-25080	2025. 6. 16	符合标准要求。	
46	GX-B1310/21-Y-25081	2025. 6. 16	符合标准要求。	
47	GX-B1310/21-Y-25082	2025. 6. 16	符合标准要求。	

48	GX-B1495/25-Y-25249~25265	2025年6月16日	本次共检防爆型高压配电装置17台，17台防爆型高压配电装置所检项目合格。	
49	GX-B1312/20-Y-25108~25113	2025. 6. 17	本次共检煤矿用防爆干式变压器6台，6台煤矿用防爆干式变压器所检项目合格。	
50	GX-B1312/20-Y-25114~25120	2025. 6. 17	本次共检煤矿用防爆干式变压器7台，7台煤矿用防爆干式变压器所检项目合格。	

51	GX-B1310/21-Y-25071	2025. 6. 14	符合标准要求。		
52	GX-B1310/21-Y-25072	2025. 6. 14	符合标准要求。		
53	GX-B1310/21-Y-25073	2025. 6. 14	符合标准要求。		

54	GX-B1310/21-Y-25074	2025. 6. 14	符合标准要求。		
55	GX-B1428/21-Y-25071	2025. 6. 14	无缺陷迹痕显示。		
56	GX-B1428/21-Y-25072	2025. 6. 14	无缺陷迹痕显示。		

57	GX-B1427/21-Y-25073	2025. 6. 14	符合标准要求。	
58	GX-B1427/21-Y-25074	2025. 6. 14	符合标准要求。	
59	GX-B1323/21-Y-25003~25005	2025. 6. 18	所检项目合格。	


60	GX-B1321/20-Y-25212~25218	2025. 6. 19	本次共检电力电缆7条， 7条电力电缆所检项目合格。		
61	GX-B1321/20-Y-25219~25223	2025. 6. 19	本次共检电力电缆5条， 5条电力电缆所检项目合格。		
62	GX-B1321/20-Y-25224~25226	2025. 6. 19	本次共检电力电缆3条， 3条电力电缆所检项目合格。		

63	GX-B1321/20-Y-25227~25230	2025. 6. 19	本次共检电力电缆4条，4条电力电缆所检项目合格。	
64	GX-B1321/20-Y-25202~25211	2025. 6. 19	本次共检验电力电缆10条，10条电力电缆所检项目合格。	
65	GX-B1495/25-Y-25266~25277	2025年6月19日	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	


66	GX-B1495/25-Y-25278~25287	2025年6月19日	本次共检高压开关设备10台，10台高压开关设备所检项目合格。	
67	GX-B1495/25-Y-25288~25291	2025年6月19日	本次共检防爆型高压配电装置4台，4台防爆型高压配电装置所检项目合格。	
68	GX-B1495/25-Y-25292~25302	2025. 6. 19	本次共检防爆型高压配电装置11台，11台防爆型高压配电装置所检项目合格。 。	



69	GX-B1495/25-Y-25303~25320	2025. 6. 19	本次共检防爆型高压配电装置18台，18台防爆型高压配电装置所检项目合格。 。		
70	GX-B1495/25-Y-25337~25349	2025. 6. 19	本次共检高压开关设备13台，13台高压开关设备所检项目合格。		
71	GX-B1495/20-Y-25350~25368	2025. 6. 19	本次共检高压开关设备19台，19台高压开关设备所检项目合格。		

72	GX-B1495/25-Y-25321~25336	2025. 6. 19	本次共检高压开关设备 16台，16台高压开关设备 所 检项目合格	 A photograph showing two workers in a control room. One worker is standing and looking at a panel, while the other is kneeling and working on a device on the floor. The room is filled with various electrical control panels and equipment. The date 2025.6.19 is visible in the bottom right corner of the image.
73	GX-B1310/21-Y-25083	2025. 6. 20	符合标准要求。	 A photograph of a worker wearing a red helmet and a blue uniform, working on a large electrical component. The worker is holding a tool and appears to be inspecting or adjusting the component. The date 2025.5.24 is visible in the bottom right corner of the image.
74	GX-B1310/21-Y-25084	2025. 6. 20	符合标准要求。	 A photograph of a worker wearing a red helmet and a blue uniform, working on a large electrical component. The worker is holding a tool and appears to be inspecting or adjusting the component. The date 2025.5.24 is visible in the bottom right corner of the image.

75	GX-B1310/21-Y-25085	2025. 6. 20	符合标准要求。	
76	GX-B1310/21-Y-25086	2025. 6. 20	符合标准要求。	
77	GX-B1310/21-Y-25087	2025. 6. 20	符合标准要求。	



78	GX-B1310/21-Y-25088	2025. 6. 20	符合标准要求。	
79	GX-B1328/20-Y-25053	2025. 6. 20	本次共检验电器5支，5支验电器所检项目合格。	
80	GX-B1328/20-Y-25054	2025. 6. 20	本次共检携带式接地和接地短路装置2组，2组携带式接地和接地短路装置所检项目合格。	

81	GX-B1515/22-Y-25005	2025. 6. 20	所检项目合格。	
82	GX-B1312/20-Y-25121~25122	2025年6月24日	本次共检煤矿用防爆干式变压器2台，2台煤矿用防爆干式变压器所检项目合格。	
83	GX-B1312/20-Y-25123~25126	2025年6月24日	本次共检煤矿用防爆干式变压器4台，4台煤矿用防爆干式变压器所检项目合格。	

84	GX-B1312/20-Y-25127~25128	2025年6月24日	本次共检煤矿用防爆干式变压器2台，2台煤矿用防爆干式变压器所检项目合格。	
85	GX-B1312/20-Y-25129~25131	2025年6月24日	本次共检煤矿用防爆干式变压器3台，3台煤矿用防爆干式变压器所检项目合格。	
86	GX-B1310/21-Y-25075	2025. 6. 25	符合标准要求。	


87	GX-B1310/21-Y-25076	2025. 6. 25	符合标准要求。	
88	GX-B1427/21-Y-25076	2025. 6. 25	符合标准要求。	
89	GX-B1310/21-Y-25077	2025. 6. 25	符合标准要求。	

90	GX-B1427/21-Y-25077	2025. 6. 25	符合标准要求。	
91	GX-B1310/21-Y-25078	2025. 6. 25	符合标准要求。	
92	GX-B1427/21-Y-25078	2025. 6. 25	符合标准要求。	

93	GX-B1310/21-Y-25089	2025. 6. 25	符合标准要求。	 2025.05.09
94	GX-B1428/21-Y-25090	2025. 6. 25	无缺陷迹痕显示。	 2025.05.09
95	GX-B1310/21-Y-25091	2025. 6. 25	符合标准要求。	 2025.05.09

96	GX-B1428/21-Y-25092	2025. 6. 25	无缺陷迹痕显示。	 A worker in a blue uniform and red helmet is inspecting a large, blue, curved industrial component. The date 2025.05.09 is visible in the bottom right corner of the image.
97	GX-B1310/21-Y-25093	2025. 6. 25	符合标准要求。	 A worker in a blue uniform and red helmet is inspecting a yellow industrial component. The date 2025.5.26 is visible in the bottom right corner of the image.
98	GX-B1310/21-Y-25094	2025. 6. 25	符合标准要求。	 A worker in a blue uniform and red helmet is inspecting a yellow industrial component. The date 2025.5.26 is visible in the bottom right corner of the image.

99	GX-B1515/22-Y-25006	2025. 6. 25	所检项目合格。		
100	GX-B1515/22-Y-25007	2025. 6. 25	所检项目合格。		
101	GX-B1495/25-Y-25453~25457	2025. 6. 30	本次共检高压交流断路器5台，5台所检项目合格。		

102	GX-B1547/20-Y-25009~25012	2025. 6. 30	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	
103	GX-B1323/21-Y-25006~25008	2025. 6. 30	所检项目合格。	
104	GX-B1323/21-Y-25009~25011	2025. 6. 30	所检项目合格。	

105	GX-B1323/21-Y-25012~25014	2025. 6. 30	所检项目合格。	
106	GX-B1312/20-Y-25132~25133	2025年6月30日	本次共检煤矿用防爆干式变压器2台，2台煤矿用防爆干式变压器所检项目合格。	