


序号	报告编号	发布日期	结论	影像资料
9	GX-B1416/22-P-25004	2025. 8. 26	综合判定：合格	
10	GX-B1620/24-P-25001	2025. 8. 26	实测流量255.9m ³ /h、电机输入功率92.6kW，不做判定，其余所检项目合格。	
11	GX-B1620/24-P-25002	2025. 8. 26	实测流量246.5m ³ /h、电机输入功率89.3kW，不做判定，其余所检项目合格。	

12	GX-B1620/24-P-25003	2025. 8. 26	实测流量266. 4m ³ /h、电机输入功率95. 3kW，不做判定，其余所检项目合格。	
13	GX-B1495/20-P-252070~252089	2025. 8. 26	本次共检防爆型高压配电装置20台，20台防爆型高压配电装置所检项目合格。	
14	GX-B1495/20-P-252096~252097	2025. 8. 26	本次共检防爆型高压配电装置2台，2台防爆型高压配电装置所检项目合格。	

15	GX-B1495/20-P-252095	2025. 8. 26	所检项目合格。	
16	GX-B1495/20-P-252094	2025. 8. 26	所检项目合格。	
17	GX-B1495/20-P-252092~252093	2025. 8. 26	本次共检防爆型高压 配电装置2台，2台防 爆型高压配电装置所 检项目合格。	

18	GX-B1495/20-P-252091	2025. 8. 26	所检项目合格。	
19	GX-B1328/20-P-25109	2025. 8. 26	本次共检绝缘鞋 26只，26只绝缘鞋合格。	
20	GX-B1328/20-P-25110	2025. 8. 26	本次共检绝缘手套70 只，70只绝缘手套合格。	

21	GX-B1328/20-P-25111	2025. 8. 26	本次共检绝缘手套8只，8只绝缘手套合格。	
22	GX-B1328/20-P-25112	2025. 8. 26	本次共检绝缘鞋8只，8只绝缘鞋合格。	
23	GX-B1328/20-P-25113	2025. 8. 26	本次共检携带式接地和接地短路装置1套，1套携带式接地和接地短路装置合格。	

24	GX-B1559/22-P-25069	2025. 8. 27	所检项目合格。	
25	GX-B1559/22-P-25070	2025. 8. 27	所检项目合格。	

26	GX-B1559/22-P-25071	2025. 8. 27	所检项目合格。	
27	GX-B1559/22-P-25072	2025. 8. 27	所检项目合格。	


28	GX-B1559/22-P-25073	2025. 8. 27	所检项目合格。	 <p> 图号: 10-20177 图名: 装载机 地址: 内蒙古自治区赤峰市红山区中街亿安驾校考场附近 时间: 2025-08-27 星期五 单位: 中能亿安驾校 </p>
29	GX-B1559/22-P-25074	2025. 8. 27	所检项目合格。	 <p> 图号: 110-20175 图名: 装载机 地址: 内蒙古自治区赤峰市红山区中街亿安驾校考场附近 时间: 2025-08-27 星期五 单位: 中能亿安驾校 </p>

30	GX-B1559/22-P-25075	2025. 8. 27	所检项目合格。	 <p> 电话: 110.70177 手机: 139.98463 地址: 陕西省榆林市神木市大敬路在翠塔里公寓楼附近 时间: 2025-08-27 星期四 名称: 中国石化发电 </p>
31	GX-B1559/22-P-25076	2025. 8. 28	所检项目合格。	 <p> 电话: 110.39389 手机: 139.22497 地址: 陕西省榆林市神木市大敬路在翠塔里附近 时间: 2025-08-23 星期六 名称: 乌兰色太煤矿 </p>

32	GX-B1559/22-P-25077	2025. 8. 28	所检项目合格。	
33	GX-B1559/22-P-25078	2025. 8. 28	所检项目合格。	
34	GX-B1417/22-2500361TH1	2025. 8. 25	综合判定: 合格。	

35	GX-B1417/22-2500747TH1	2025. 8. 25	综合判定：合格。	
36	GX-B1417/22-2500748TH1	2025. 8. 25	综合判定：合格。	

37	GX-B1417/22-2501630TH1	2025. 8. 25	综合判定：合格。	
38	GX-B1417/22-2500925LH1	2025. 8. 25	综合判定：合格。	
39	GX-B1417/22-2501491TH1	2025. 8. 25	综合判定：合格。	

40	GX-B1417/22-2501494TH1	2025. 8. 25	综合判定：合格。		
41	GX-B1417/22-2501499TH1	2025. 8. 25	综合判定：合格。		
42	GX-B1417/22-2501516TH1	2025. 8. 25	综合判定：合格。		

43	GX-B1417/22-2501631TH1	2025. 8. 25	综合判定：合格。	
44	GX-B1417/22-2500744TH1	2025. 8. 23	综合判定：合格。	
45	GX-B1417/22-2500828TH1	2025. 8. 23	综合判定：合格。	

46	GX-B1417/22-2500826TH1	2025. 8. 23	综合判定：合格。	
47	GX-B1417/22-2500825TH1	2025. 8. 23	综合判定：合格。	
48	GX-B1417/22-2500824TH1	2025. 8. 23	综合判定：合格。	

49	GX-B1417/22-2500823TH1	2025. 8. 23	综合判定：合格。	
50	GX-B1417/22-2500820TH1	2025. 8. 23	综合判定：合格。	
51	GX-B1417/22-2501676TH1	2025. 8. 23	综合判定：合格。	

52	GX-B1417/22-2501680TH1	2025. 8. 23	综合判定：合格。	
53	GX-B1417/22-2500722TH1	2025. 8. 23	综合判定：合格。	
54	GX-B1417/22-2500723TH1	2025. 8. 23	综合判定：合格。	

55	GX-B1417/22-2500725TH1	2025. 8. 23	综合判定：合格。	
56	GX-B1417/22-2500726TH1	2025. 8. 23	综合判定：合格。	
57	GX-B1417/22-2500727TH1	2025. 8. 23	综合判定：合格。	


58	GX-B1417/22-2500728TH1	2025. 8. 23	综合判定：合格。	
59	GX-B1417/22-2500731TH1	2025. 8. 23	综合判定：合格。	
60	GX-B1417/22-2500734TH1	2025. 8. 23	综合判定：合格。	

61	GX-B1417/22-2500735TH1	2025. 8. 23	综合判定：合格。	
62	GX-B1417/22-2500830TH1	2025. 8. 23	综合判定：合格。	
63	GX-B1310/21-P-25041	2025. 8. 29	符合标准要求。	

64	GX-B1428/21-P-25017	2025. 8. 29	无缺陷痕迹显示。	 <p> 经 度: 109992041 纬 度: 39.27770 地 址: 新疆维吾尔自治区阿克苏地区阿克苏市伊金霍洛街伊金霍洛街 阿克苏地区阿克苏市伊金霍洛街附近 时 间: 2025-08-20 星期三 时 刻: 08:40:11 </p>
65	GX-B1310/21-P-25032	2025. 8. 29	符合标准要求。	 <p> 时 间: 2025-08-16 星期四 时 刻: 08:40:11 </p>
66	GX-B1310/21-P-25033	2025. 8. 29	符合标准要求。	 <p> 时 间: 2025-08-16 星期四 时 刻: 08:40:11 </p>

67	GX-B1310/21-P-25034	2025. 8. 29	符合标准要求。		 <p>时 间：2025-08-16 星期六 名 称：隐患排查</p>
68	GX-B1310/21-P-25035	2025. 8. 29	符合标准要求。		 <p>时 间：2025-08-16 星期六 名 称：隐患排查</p>
69	GX-B1310/21-P-25036	2025. 8. 29	符合标准要求。		 <p>时 间：2025-08-16 星期六 名 称：隐患排查</p>

70	GX-B1310/21-P-25037	2025. 8. 29	符合标准要求。			
71	GX-B1310/21-P-25038	2025. 8. 29	符合标准要求。			
72	GX-B1310/21-P-25039	2025. 8. 29	符合标准要求。			

73	GX-B1310/21-P-25040	2025. 8. 29	符合标准要求。		 A photograph showing two workers in full safety gear, including red helmets and high-visibility blue and yellow work clothes, standing in an industrial or construction setting. They appear to be inspecting or working on a piece of equipment. The background shows some structural elements of a building or site. <p>附 图：2025-08-16 星期六 时：14:30:00</p>	
----	---------------------	-------------	---------	--	---	--