


序号	报告编号	发布日期	结论	影像资料
146	GX-B1475/22-F-25395~25396	2025.8.20	所检项目合格	 A technician in a white lab coat is working on a piece of equipment in a laboratory setting. The equipment has various wires and components. The date 2025.8.12 is visible in the bottom right corner of the image.
147	GX-B1374/22-F-250731~250732	2025.8.26	本次共检验一氧化碳传感器2台, 2台所检项目合格。	 Two technicians in white lab coats are working on a piece of equipment in a laboratory setting. The equipment has various wires and components. The date 2025.8.10 is visible in the bottom right corner of the image.
148	GX-B1374/22-F-250753~250755	2025.8.26	所检项目合格	 Two technicians in white lab coats are working on a piece of equipment in a laboratory setting. The equipment has various wires and components. The date 2025/8/16 is visible in the bottom right corner of the image.

149	GX-B1372/22-250606~250609	2025.8.27	所检项目合格	
150	GX-B1606/23-F-25367~25371	2025.8.27	所检项目合格	
151	GX-B1605/23-F-25367~25371	2025.8.27	所检项目合格	

152	GX-B1601/22-F-250764~250775	2025.8.27	所检项目合格	
153	GX-B1592/21-F-25155~25156	2025.8.27	本次共检测传感器 2台，2台所检项目合格。	
154	GX-B1409/22-F-25110	2025.8.27	所检项目合格	

155	GX-B1410/22-F-25590~25607	2025.8.27	本次共检验一氧化碳传感器18台，18台所检项目合格。	
156	GX-B1542/21-F-25407~25410	2025.8.27	本次共检验光干涉式甲烷测定器4台，4台所检项目合格	
157	GX-B1593/21-F-25390~25392	2025.8.27	所检项目合格	

158	GX-B1603/22-F-250300	2025.8.27	所检项目合格	 A photograph showing two individuals in a laboratory or industrial setting. One person, wearing a grey lab coat, is standing and looking at a piece of equipment. The other person, wearing a light blue shirt and jeans, is also looking at the equipment. The equipment is a large, blue and white machine with a control panel. The date 2025.8.19 is visible in the bottom right corner of the image.
159	GX-B1601/22-F-250741~250744	2025.8.27	所检项目合格	 A photograph showing a person in a grey lab coat sitting at a desk in a laboratory. They are working on a computer. In the background, there are various pieces of laboratory equipment, including what looks like a large incubator or bioreactor. The date 2025.8.18 is visible in the bottom right corner of the image.
160	GX-B1540/20-F-252023~252025	2025.8.28	所检项目合格	 A photograph showing two people in a laboratory setting. One person, wearing a grey lab coat, is standing and looking at a piece of equipment. The other person, wearing a light blue shirt and jeans, is also looking at the equipment. The equipment is a large, blue and white machine with a control panel. The date 2025.8.20 is visible in the bottom right corner of the image.


161	GX-B1475/22-F-25398~25399	2025.8.28	所检项目合格	
162	GX-B1374/22-F-250706~250710	2025.8.26	所检项目合格	
163	GX-B1410/22-F-25566~25577	2025.8.26	所检项目合格	

164	GX-B1606/23-F-25306~25313	2025.8.26	所检项目合格	
165	GX-B1606/23-F-25314~25321	2025.8.26	所检项目合格	
166	GX-B1606/23-F-25330~25336	2025.8.26	所检项目合格	

167	GX-B1606/23-F-25322~25329	2025.8.26	所检项目合格	
168	GX-B1606/23-F-25305	2025.8.26	所检项目合格	
169	GX-B1605/23-F-25314~25321	2025.8.26	所检项目合格	

170	GX-B1605/23-F-25322~25329	2025.8.26	所检项目合格	
171	GX-B1605/23-F-25298~25303	2025.8.26	所检项目合格	
172	GX-B1605/23-F-25305	2025.8.26	所检项目合格	


173	GX-B1605/23-F-25330~25336	2025.8.26	所检项目合格	
174	GX-B1605/23-F-25306~25313	2025.8.26	所检项目合格	
175	GX-B1606/23-F-25299~25304	2025.8.28	所检项目合格	

176	GX-B1606/23-F-25372~25375	2025.8.28	所检项目合格	
177	GX-B1605/23-F-25372~25375	2025.8.28	所检项目合格	
178	GX-B1593/21-F-25394	2025.8.28	所检项目合格	

179	GX-B1601/22-F-250728~250734	2025.8.28	所检项目合格	
180	GX-B1412/22-F-25040	2025.8.28	所检项目合格	
181	GX-B1411/22-F-25073	2025.8.28	所检项目合格	

182	GX-B1409/22-F-25106	2025.8.28	所检项目合格	
183	GX-B1568/22-F-25493	2025.8.28	所检项目合格	
184	GX-B1410/22-F-25557~25565	2025.8.26	所检项目合格	

185	GX-B1592/21-F-25152~25153	2025.8.28	所检项目合格	
186	GX-B1601/22-F-250737~250740	2025.8.28	所检项目合格	
187	GX-B1602/22-F-25064~25065	2025.8.29	所检项目合格	

188	GX-B1540/20-F-252026~252035	2025.8.29	所检项目合格	
189	GX-B1540/20-F-252036~252038	2025.8.29	所检项目合格	
190	GX-B1540/20-F-252039~252048	2025.8.29	所检项目合格	

191	GX-B1529/20-F-25242~25244	2025.8.29	所检项目合格	
192	GX-B1529/20-F-25245~2525	2025.8.29	所检项目合格	
193	GX-B1528/20-F-25200~25202	2025.8.29	所检项目合格	

194	GX-B1543/25-F-25153~25155	2025.8.29	所检项目合格	
195	GX-B1543/25-F-25156~25165	2025.8.29	所检项目合格	
196	GX-B1593/21-F-25401~25411	2025.8.29	本次共检验烟雾传感器11台，11台所检项目合格。	

197	GX-B1592/21-F-25157	2025.8.29	所检项目合格。	 2025.8.25
198	GX-B1605/23-F-25382~25385	2025.8.29	本次共检验测定器4台，4台所检项目合格。	 2025.8.27
199	GX-B1528/20-F-25203~25212	2025.8.29	所检项目合格	 2025.8.23