

序号	报告编号	发布日期	结论	影像资料
248	GX-B1364/22-A-25844	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
249	GX-B1364/22-A-25845	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1364/22-A-25846	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
251	GX-B1364/22-A-25847	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
252	GX-B1364/22-A-25848	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
253	GX-B1364/22-A-25849	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
254	GX-B1364/22-A-25850	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
255	GX-B1364/22-A-25851	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
256	GX-B1364/22-A-25852	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
257	GX-B1364/22-A-25853	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
258	GX-B1364/22-A-25854	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
259	GX-B1365/25-A-25073	2025/8/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1366/25-A-25089	2025/8/25	所检项目全部合格。	 The photograph shows two individuals in white lab coats working with industrial equipment. One person is positioned at a control panel featuring a large, circular pressure gauge with a red needle. The other person stands nearby, observing the process. The equipment is green and metallic, with a safety cage visible. A date stamp '2025.08.13' is present in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
261	GX-B1365/25-A-25074	2025/8/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
262	GX-B1366/25-A-25090	2025/8/25	所检项目全部合格。	 A photograph showing two technicians in white lab coats working on a large industrial machine. The technician on the left is adjusting a large circular gauge with a red border. The technician on the right is standing next to a green metal frame. The machine has a large circular gauge with a red border and a needle. The date '2025.08.21' is visible in the bottom right corner of the photo. The lab coat of the technician on the right has a logo and the text '中检公司' (China Inspection Company) on the back.

序号	报告编号	发布日期	结论	影像资料
263	GX-B1507/20-A-25001	2025/8/26	所检项目合格。	 A photograph showing two male technicians in light blue lab coats working at a laboratory bench. The technician on the right is holding a handheld electronic device, possibly a multimeter or data logger, and looking at it. The technician on the left is looking down at some papers or equipment on the bench. On the bench, there is a blue box, a small electronic device, and some papers. In the background, there is a shelf with several red cans of 'Xin Sheng' (鲜生) brand products. A date stamp '2025.08.25' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
264	GX-B1363/22-A-25454	2025/8/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
265	GX-B1613/23-A-25003	2025/8/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
266	GX-B1613/23-A-25004	2025/8/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
267	GX-B1363/22-A-25465	2025/8/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
268	GX-B1363/22-A-25459	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
269	GX-B1363/22-A-25460	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
270	GX-B1363/22-A-25461	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
271	GX-B1363/22-A-25462	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
272	GX-B1363/22-A-25463	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
273	GX-B1363/22-A-25464	2025/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1367/22-A-25060	2025/8/28	所检项目合格。	 A photograph showing two male technicians in light blue lab coats working in a laboratory. They are positioned at a workbench with various pieces of equipment, including a large white machine with a digital display and a blue cabinet. The technician on the right is wearing glasses and is looking down at a device in his hands. The technician on the left is seen from the back. A timestamp '2025.08.22' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
275	GX-B1367/22-A-25061	2025/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1367/22-A-25062	2025/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
277	GX-B1367/22-A-25063	2025/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1365/25-A-25076	2025/8/27	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
279	GX-B1366/25-A-25092	2025/8/27	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1366/25-A-25093	2025/8/27	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1365/25-A-25075	2025/8/27	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1366/25-A-25091	2025/8/27	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1364/22-A-25857	2025/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1365/25-A-25077	2025/8/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1366/25-A-25094	2025/8/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1364/22-A-25856	2025/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
287	GX-B1364/22-A-25863	2025/8/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1364/22-A-25864	2025/8/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1364/22-A-25865	2025/8/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	