



序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-4-25159	2025. 9. 2	符合标准要求	
2	GX-B1310/21-4-25160	2025. 9. 2	符合标准要求	

3	GX-B1310/21-4-25161	2025. 9. 2	符合标准要求	
4	GX-B1310/21-4-25162	2025. 9. 2	符合标准要求	

5	GX-B1310/21-4-25163	2025. 9. 2	符合标准要求	
6	GX-B1310/21-4-25164	2025. 9. 2	符合标准要求	


7	GX-B1310/21-4-25165	2025. 9. 2	符合标准要求	
8	GX-B1310/21-4-25166	2025. 9. 2	符合标准要求	

9	GX-B1427/21-4-25167	2025. 9. 2	无缺陷磁痕显示			
10	GX-B1427/21-4-25168	2025. 9. 2	无缺陷迹痕显示			

11	GX-B1350/21-4-25107	2025. 9. 3	本次共检接地装置 10处，10处所检项 目合格。	
12	GX-B1350/21-4-25108	2025. 9. 3	本次共检接地装置2 处，2处所检项目合 格。	

13	GX-B1350/21-4-25109	2025/9/3	本次共检接地装置2处，2处所检项目合格。		
14	GX-B1309/21-4-25006	2025/9/3	所检项目合格。		

15	GX-B1500/21-4-25019	2025/9/3	综合判定：合格。	
16	GX-B1500/21-4-25020	2025/9/3	综合判定：合格。	

17	GX-B1500/21-4-25021	2025/9/3	综合判定：合格。	
18	GX-B1313/21-4-25115-25119	2025. 9. 3	本次共检电力变 压5台，5台电力变 压器所检项目合格 。	

19	GX-B1313/21-4-25114	2025. 9. 3	所检项目合格	
----	---------------------	------------	--------	---