




序号	报告编号	发布日期	结论	影像资料
1	GX-B1451/20-5-25933~25942	2025/9/2	本次共检高压开关柜10台，10台高压开关柜所检项目合格。	
2	GX-B1321/20-5-25747~25756	2025. 9. 3	本次共检电力电缆10条，10条电力电缆所检项目合格。	

3	GX-B1321/20-5-25757~25762	2025. 9. 3	本次共检电力电缆6条，6条电力电缆所检项目合格。	
4	GX-B1312/20-5-25707~25708	2025. 9. 3	本次共检电力变压器2台，2台电力变压器所检项目合格。	


5	GX-B1312/20-5-25709~25711	2025. 9. 3	本次共检防爆干式变压器3台，3台防爆干式变压器所检项目合格。	
6	GX-B1321/20-5-25735	2025. 9. 3	所检项目合格。	


7	GX-B1495/25-5-251227~251248	2025. 9. 4	本次共检高压开关柜22台，22台高压开关柜所检项目合格。	
8	GX-B1323/21-5-25124	2025. 9. 4	所检项目合格。	

9	GX-B1328/20-5-25174	2025. 9. 4	本次共检绝缘手套2只，2只绝缘手套合格。	
10	GX-B1328/20-5-25175	2025. 9. 4	本次共检绝缘靴2只，2只绝缘靴合格。	

11	GX-B1328/20-5-25176	2025. 9. 4	本次共检验电器 1套，1套验电器合格。 。	
12	GX-B1328/20-5-25177	2025. 9. 4	本次共检携带式接地 和接地短路装置 1套，1套携带式接地 和接地短路装置合格。 。	

13	GX-B1300/23-5-25025	2025. 9. 4	综合判定：合格。	
14	GX-B1495/25-5-251219~251221	2025. 9. 5	本次共检高压开关柜 3台，3台高压开关柜 所检项目合格。	

15	GX-B1310/21-5-25236	2025. 9. 5	符合标准要求。	
16	GX-B1427/21-5-25019	2025. 9. 5	详见检验结果。	

17	GX-B1310/21-5-25225	2025. 9. 5	符合标准要求。	
18	GX-B1310/21-5-25235	2025/9/5	符合标准要求。	

19	GX-B1310/21-5-25237	2025/9/5	符合标准要求。	 A black and white photograph showing a worker wearing a hard hat with the letters 'AB' on it, safety glasses, and a high-visibility vest. The worker is focused on a task, using a tool to work on a large, complex industrial machine. The machine has various pipes, hoses, and mechanical components. A date stamp '2025/8/26' is visible in the bottom right corner of the photo.
20	GX-B1310/21-5-25238	2025/9/5	符合标准要求。	 A black and white photograph showing a close-up of a worker's hands as they work on a large industrial machine. The worker is wearing a high-visibility vest. The machine has various pipes, hoses, and mechanical components. A date stamp '2025/8/26' is visible in the bottom right corner of the photo.

21	GX-B1310/21-5-25239	2025/9/5	符合标准要求。	
22	GX-B1300/23-5-25026	2025. 9. 5	综合判定：合格。	