

序号	报告编号	发布日期	结论	影像资料
15	GX-B1304/21-6-25022	2025年9月8日	综合判定：合格	 A worker wearing a red hard hat and black clothing is operating a large blue industrial machine. The machine has a large cylindrical component and various pipes and valves. The worker is standing next to the machine, and the background shows an industrial setting with metal walls and a ceiling.
16	GX-B1304/21-6-25023	2025年9月8日	综合判定：合格	 A worker wearing a red hard hat and a light blue uniform is operating a blue industrial machine. The machine has a complex structure with many pipes, valves, and a large cylindrical component. The worker is standing next to the machine, and the background shows an industrial setting with metal walls and a ceiling.

17	GX-B1304/21-6-25024	2025年9月8日	综合判定：合格	
18	GX-B1451/20-6-25956~25962	2025年9月8日	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。	

19	GX-B1451/20-6-25949~25955	2025年9月8日	本次共检高压开关柜7台,7台高压开关柜所检项目合格。	
20	GX-B1354-20-6-25009	2025年9月12日	所检项目合格。	

21	GX-B1305/21-6-25017	2025年9月12日	综合判定：合格。		
22	GX-B1309/21-6-25036	2025年9月11日	所检项目合格。		

23	GX-B1309/21-6-25037	2025年9月11日	所检项目合格。	
24	GX-B1309/21-6-25038	2025年9月11日	所检项目合格。	


25	GX-B1500/21-6-25151	2025年9月11日	综合判定：合格。	
26	GX-B1500/21-6-25152	2025年9月11日	综合判定：合格。	

27	GX-B1500/21-6-25153	2025年9月11日	综合判定：合格。	
28	GX-B1500/21-6-25154	2025年9月11日	综合判定：合格。	

29	GX-B1500/21-6-25155	2025年9月11日	综合判定：合格。	 A photograph of a large blue industrial machine, likely a lathe or mill, with the number '1' on its side. A worker in a red hard hat and safety vest is standing next to the machine. The machine is surrounded by a blue and white safety fence. The background shows other industrial equipment and a red sign with Chinese characters.
30	GX-B1500/21-6-25156	2025年9月11日	综合判定：合格。	 A photograph of a large blue industrial machine, similar to the one in the previous image, with the number '2' on its side. A worker in a red hard hat and safety vest is standing next to the machine. The machine is surrounded by a blue and white safety fence. The background shows other industrial equipment and a red sign with Chinese characters.

31	GX-B1500/21-6-25157	2025年9月11日	综合判定：合格。	 A photograph of an industrial worker wearing a red hard hat and safety vest, standing behind a blue and white safety fence. The worker is positioned next to a large blue industrial machine with the number '3' on it. The machine has a yellow warning sign. The floor is green and yellow striped. A timestamp '2025-07-21' is visible in the bottom right corner.
32	GX-B1500/21-6-25158	2025年9月11日	综合判定：合格。	 A photograph of an industrial worker wearing a red hard hat and safety vest, standing behind a blue and white safety fence. The worker is positioned next to a large blue industrial machine with the number '4' on it. The machine has a yellow warning sign. The floor is green and yellow striped. A timestamp '2025-07-21' is visible in the bottom right corner.

33	GX-B1500/21-6-25159	2025年9月11日	综合判定：合格。	
34	GX-B1500/21-6-25160	2025年9月11日	综合判定：合格。	

35	GX-B1500/21-6-25161	2025年9月11日	综合判定：合格。	
36	GX-B1500/21-6-25162	2025年9月11日	综合判定：合格。	

37	GX-B1310/21-6-25254	2025年9月12日	符合标准要求	
38	GX-B1310/21-6-25255	2025年9月12日	符合标准要求	


39	GX-B1310/21-6-25256	2025年9月12日	符合标准要求			
40	GX-B1427/21-6-25068	2025年9月12日	符合标准要求			

41	GX-B1310/21-6-25242	2025年9月11日	符合标准要求	
42	GX-B1310/21-6-25243	2025年9月11日	符合标准要求	

43	GX-B1310/21-6-25244	2025年9月11日	符合标准要求	
44	GX-B1310/21-6-25245	2025年9月11日	符合标准要求	

45	GX-B1310/21-6-25246	2025年9月11日	符合标准要求	
46	GX-B1310/21-6-25247	2025年9月11日	符合标准要求	

47	GX-B1310/21-6-25248	2025年9月11日	符合标准要求	
48	GX-B1310/21-6-25249	2025年9月11日	符合标准要求	

49	GX-B1310/21-6-25250	2025年9月11日	符合标准要求		
50	GX-B1310/21-6-25251	2025年9月11日	符合标准要求		

51	GX-B1310/21-6-25252	2025年9月11日	符合标准要求		
52	GX-B1310/21-6-25253	2025年9月11日	符合标准要求		

53	GX-B1427/21-6-25062	2025年9月11日	符合标准要求。			
54	GX-B1427/21-6-25063	2025年9月11日	符合标准要求。			

55	GX-B1427/21-6-25064	2025年9月11日	符合标准要求。	
56	GX-B1428/21-6-25055	2025年9月10日	无缺陷迹痕显示	

57	GX-B1428/21-6-25056	2025年9月10日	无缺陷迹痕显示	 A photograph showing two workers in orange protective suits and red helmets standing next to a large, circular, reddish-brown tunnel opening. The interior of the tunnel is dark, and a bright light source is visible inside. The date '2025 08 25' is printed in the bottom right corner of the image.
58	GX-B1310/21-6-25223	2025年9月10日	符合标准要求。	 A photograph of a worker wearing a grey uniform, a red helmet, and white gloves, focused on inspecting a large, dark, circular metal component. The worker is holding a small electronic device. The date '2025 07 22' is printed in the bottom right corner of the image.

59	GX-B1310/21-6-25224	2025年9月10日	符合标准要求。	
60	GX-B1310/21-6-25225	2025年9月10日	符合标准要求。	

61	GX-B1310/21-6-25226	2025年9月10日	符合标准要求。	
62	GX-B1310/21-6-25227	2025年9月10日	符合标准要求。	

63	GX-B1310/21-6-25228	2025年9月10日	符合标准要求。	
64	GX-B1310/21-6-25229	2025年9月10日	符合标准要求。	


65	GX-B1310/21-6-25230	2025年9月10日	符合标准要求。	
66	GX-B1310/21-6-25231	2025年9月10日	符合标准要求。	

67	GX-B1310/21-6-25232	2025年9月10日	符合标准要求。	
68	GX-B1313/21-6-25326	2025年9月9日	所检项目合格。	

69	GX-B1321/20-6-25734~25735	2025年9月10日	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
70	GX-B1321/20-6-25736~25737	2025年9月10日	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	

71	GX-B1495/25-6-251424~251436	2025年9月8日	本次共检互感器 13组，13组互感器所检 项目合格。	
72	GX-B1495/25-6-251437~251453	2025年9月8日	本次共检互感器 17组，17组互感器所检 项目合格。	

73	GX-B1495/25-6-251394~251406	2025年9月9日	本次共检高压开关柜 13台, 13台高压开关柜 所检项目合格。	
74	GX-B1495/25-6-251407~251423	2025年9月9日	本次共检高压开关柜 17台, 17台高压开关柜 所检项目合格。	

75	GX-B1322/21-6-25427~25433	2025年9月10日	本次共检电力电缆7条，7条电力电缆所检项目合格。	 2025 08 23
76	GX-B1322/21-6-25434~25439	2028年9月10日	本次共检电力电缆6条，6条电力电缆所检项目合格。	 2025 08 24