




序号	报告编号	发布日期	结论	影像资料
142	GX-B1310/21-2-25343	2025. 9. 22	符合标准要求。	
143	GX-B1310/21-2-25344	2025. 9. 22	符合标准要求。	

144	GX-B1310/21-2-25345	2025. 9. 22	符合标准要求。	
145	GX-B1310/21-2-25346	2025. 9. 22	符合标准要求。	

146	GX-B1310/21-2-25347	2025. 9. 22	符合标准要求。	
147	GX-B1310/21-2-25348	2025. 9. 22	符合标准要求。	

148	GX-B1416/22-2-25011	2025. 9. 23	综合判定：合格。	
149	GX-B1416/22-2-25012	2025. 9. 23	综合判定：合格。	

150	GX-B1328/25-2-25126	2025. 9. 23	本次共检绝缘手套32只，32只绝缘手套合格。	
151	GX-B1328/25-2-25127	2025. 9. 23	本次共检绝缘靴32只，32只绝缘靴合格。	

152	GX-B1328/25-2-25128	2025. 9. 23	本次共检验电器 8支，8支验电器合格。 。	 2025/09/06
153	GX-B1404/20-2-25020	2025/9/23	所检电网谐波电压总 谐波畸变率、各次谐 波电压含有率、谐波 电流符合GB/T 14549- 1993 《电能质量 公用 电网谐波》要求。	 2025/9/1

154	GX-B1404/20-2-25021	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
155	GX-B1404/20-2-25022	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

156	GX-B1404/20-2-25023	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
157	GX-B1404/20-2-25024	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

158	GX-B1404/20-2-25025	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
159	GX-B1404/20-2-25026	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	


160	GX-B1404/20-2-25027	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
161	GX-B1404/20-2-25028	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	


162	GX-B1404/20-2-25029	2025/9/23	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
163	GX-B1354/20-2-25007	2025/9/23	合格。	


164	GX-B1354/20-2-25008	2025/9/23	合格。	
165	GX-B1354/20-2-25009	2025/9/23	合格。	

166	GX-B1354/20-2-25010	2025/9/23	合格。	
167	GX-B1354/20-2-25011	2025/9/23	合格。	

168	GX-B1515/22-2-25013	2025/9/18	所检项目合格	 2025/08/21
169	GX-B1515/22-2-25014	2025/9/18	所检项目合格	 2025/08/21

170	GX-B1515/22-2-25015	2025/9/18	所检项目合格	 A photograph showing two workers in blue safety suits and red hard hats standing in a dark tunnel. They are positioned next to a blue piece of equipment. A date stamp '2025/08/22' is visible in the bottom right corner of the image.
171	GX-B1304/21-2-25016	2025/9/24	综合判定：合格。	 A photograph showing three workers in grey safety suits and red hard hats in an industrial setting. They are standing near a large blue machine. A date stamp '2025/02/23' is visible in the bottom right corner of the image.


172	GX-B1310/21-2-25349	2025. 9. 29	符合标准要求。	
173	GX-B1428/21-2-25349	2025. 9. 29	无缺陷迹痕显示。	

174	GX-B1310/21-2-25350	2025. 9. 29	符合标准要求。	
175	GX-B1428/21-2-25350	2025. 9. 29	无缺陷迹痕显示。	


176	GX-B1310/21-2-25351	2025. 9. 29	符合标准要求。	
177	GX-B1428/21-2-25351	2025. 9. 29	无缺陷迹痕显示。	


178	GX-B1310/21-2-25352	2025. 9. 29	符合标准要求。	
179	GX-B1428/21-2-25352	2025. 9. 29	无缺陷迹痕显示。	

180	GX-B1310/21-2-25356	2025. 9. 30	符合标准要求。	
181	GX-B1427/21-2-25356	2025. 9. 30	符合标准要求。	

182	GX-B1304/21-2-25017	2025/9/29	综合判定：合格。	 2025.9.17
183	GX-B1310/21-2-25355	2025/9/27	符合标准要求。	 2025.9.22

184	GX-B1427/21-2-25355	2025/9/27	符合标准要求。	
185	GX-B1309/21-2-25018	2025/9/30	所检项目合格。	

186	GX-B1309/21-2-25019	2025/9/30	所检项目合格。	
187	GX-B1310/21-2-25357	2025/9/30	符合标准要求。	

188	GX-B1310/21-2-25358	2025/9/30	符合标准要求。	
189	GX-B1310/21-2-25359	2025/9/30	符合标准要求。	