


序号	报告编号	发布日期	结论	影像资料
145	GX-B1502/24-F-25040	2025. 9. 23	Ⅱ类，自燃。	
146	GX-B1502/24-F-25041	2025. 9. 23	Ⅱ类，自燃。	
147	GX-B1502/24-F-25042	2025. 9. 23	Ⅱ类，自燃。	
148	GX-B1502/24-F-25043	2025. 9. 23	Ⅱ类，自燃。	
149	GX-B1501/24-F-25040	2025. 9. 23	煤尘具有爆炸性。	
150	GX-B1501/24-F-25041	2025. 9. 23	煤尘具有爆炸性。	

151	GX-B1501/24-F-25042	2025. 9. 23	煤尘具有爆炸性。	
152	GX-B1501/24-F-25043	2025. 9. 23	煤尘具有爆炸性。	
153	GX-B1602/22-F-25069	2025.9.24	所检项目合格	
154	GX-B1568/22-F-25534~25540	2025.9.24	所检项目合格	

155	GX-B1568/22-F-25541~25548	2025.9.24	所检项目合格	
156	GX-B1601/22-F-250829~250832	2025.9.23	所检项目合格	

157	GX-B1593/21-F-25426~25427	2025.9.23	所检项目合格	
158	GX-B1568/22-F-25563~25565	2025.9.24	所检项目合格	


159	GX-B1606/23-F-25406-25410	2025.9.25	所检项目合格	
160	GX-B1605/23-F-25403~25407	2025.9.25	所检项目合格	


161	GX-B1410/22-F-25633~25635	2025.9.25	所检项目合格	
162	GX-B1528/20-F-25305~25324	2025.9.25	所检项目合格	

163	GX-B1540/20-F-252366~252385	2025.9.25	所检项目合格	
164	GX-B1544/21-F-25070~25075	2025.9.25	所检项目合格	


165	GX-B1544/21-F-25076~25078	2025.9.25	所检项目合格	
166	GX-B1606/23-F-25386~25391	2025.9.25	所检项目合格	

167	GX-B1606/23-F-25392~25394	2025.9.25	所检项目合格	
168	GX-B1605/23-F-25386~25391	2025.9.25	所检项目合格	

169	GX-B1374/22-F-250813~250832	2025.9.25	所检项目合格	
170	GX-B1592/21-F-25159~25160	2025.9.25	所检项目合格	

171	GX-B1528/20-F-25325~25333	2025.9.25	所检项目合格	
172	GX-B1542/21-F-25486~25489	2025.9.25	所检项目合格	

173	GX-B1543/25-F-25172	2025.9.25	所检项目合格	
174	GX-B1529/20-F-25355~25371	2025.9.25	所检项目合格	

175	GX-B1542/21-F-25427~25436	2025.9.25	所检项目合格	
176	GX-B1603/22-F-250309	2025.9.25	所检项目合格	

177	GX-B1540/21-F-252329	2025.9.25	所检项目合格	
178	GX-B1602/22-F-25068	2025.9.25	所检项目合格	

179	GX-B1540/20-F-252320~252328	2025.9.25	所检项目合格	
180	GX-B1374/25-F-250812	2025.9.25	所检项目合格	

181	GX-B1601/22-F-250825~250828	2025.9.24	所检项目合格	
182	GX-B1568/22-F-25572	2025.9.26	所检项目合格	

183	GX-B1568/22-F-25567~25571	2025.9.26	所检项目合格	
184	GX-B1374/22-F-250842	2025.9.26	所检项目合格	

185	GX-B1410/22-F-25626~25632	2025.9.26	所检项目合格	
186	GX-B1606/23-F-25395~25405	2025.9.26	所检项目合格	

187	GX-B1605/23-F-25392~25402	2025.9.26	所检项目合格	
188	GX-B1410/22-F-25636~25638	2025.9.26	所检项目合格	

189	GX-B1568/22-F-25566	2025.9.26	所检项目合格		
190	GX-B1601/22-F-250839~250842	2025.9.26	所检项目合格		

191	GX-B1528/20-F-25335~25336	2025.9.28	本次共检测定器2台， 2台所检项目合格。	
192	GX-B1550/22-F-25080~25081	2025.9.28	本次共检测定器2台， 2台所检项目合格。	

193	GX-B1475/22-F-25420	2025.9.28	所检项目合格。	
194	GX-B1374/22-F-250862~250864	2025.9.28	本次共检验一氧化碳传感器3台，3台所检项目合格	

195	GX-B1374/22-F-250871~250875	2025.9.28	所检项目合格	
196	GX-B1465/22-F-25134~25136	2025.9.28	所检项目合格	

197	GX-B1475/22-F-25421~25425	2025.9.28	所检项目合格	
198	GX-B1374/22-F-250803~250811	2025.9.26	所检项目合格	

199	GX-B1374/22-F-250789~250797	2025.9.28	所检项目合格	
200	GX-B1529/20-F-25274~25283	2025.9.28	所检项目合格	

201	GX-B1374/22-F-25527~25532	2025.9.28	所检项目合格	 A photograph showing a male worker in a light blue short-sleeved shirt and dark pants sitting at a control console, operating a large industrial machine. The machine has a blue protective cover. In the background, another worker is visible near another machine. The date '2025年09月01日' is printed in the bottom right corner of the image.
202	GX-B1601/22-F-250790~250794	2025.9.28	所检项目合格	 A photograph showing a male worker in a light blue short-sleeved shirt and dark pants sitting at a control console, operating a large industrial machine. The machine has a blue protective cover. In the background, another worker is visible near another machine. The date '2025年09月01日' is printed in the bottom right corner of the image.


203	GX-B1373/21-F-25478~25481	2025.9.28	所检项目合格	
204	GX-B1603/22-F-250314~250315	2025.9.28	所检项目合格	

205	GX-B1601/25-F-250819~250824	2025.9.28	所检项目合格	 2025.9.16
206	GX-B1475/22-F-25409~25415	2025.9.28	所检项目合格	 2025.9.10

207	GX-B1475/22-F-25416	2025.9.28	所检项目合格	
208	GX-B1373/21-F-25473~25477	2025.9.28	所检项目合格	

209	GX-B1465/22-F-25137~25138	2025.9.29	本次共检验矿用电化学式氧气传感器2台，2台所检项目合格	
210	GX-B1374/22-F-250876~250880	2025.9.29	本次共检验一氧化碳传感器5台，5台所检项目合格	

211	GX-B1475/22-F-25426~25432	2025.9.29	本次共检验非色散红外甲烷传感器7台，7台所检项目合格	
212	GX-B1540/20-F-252206~252230	2025.9.29	本次共检验报警仪25台，25台所检项目合格。	

213	GX-B1372/22-F-250831~250834	2025.9.29	本次共检验煤矿用低浓度载体催化式甲烷传感器4台，4台所检项目合格	
214	GX-B1475/22-F-25420	2025.9.29	所检项目合格。	

215	GX-B1373/21-F-25496~25499	2025.9.29	本次共检验温度传感器4台，4台所检项目合格	
216	GX-B1374/22-F-250862~250864	2025.9.29	本次共检验一氧化碳传感器3台，3台所检项目合格	

217	GX-B1372/22-F-25805~25810	2025.9.29	所检项目合格	 2025/9/21
218	GX-B1373/21-F-25488~25490	2025.9.29	所检项目合格	 2025/9/21

219	GX-B1374/22-F-250865~250870		所检项目合格	
220	GX-B1601/22-F-250834~250838	2025.9.28	所检项目合格	

221	GX-B1568/22-F-25574~25576	2025.9.28	所检项目合格	
222	GX-B1568/22-F-25573	2025.9.28	所检项目合格	

223	GX-B1540/20-F-252306~252311	2025.9.28	所检项目合格	
224	GX-B1568/22-F-25566	2025.9.29	所检项目合格	

225	GX-B1601/22-F-250839~250842	2025.9.29	所检项目合格	 A person in a grey lab coat is sitting at a desk in a laboratory, working on a computer. Another person is visible in the background. The date 2025.09.22 is overlaid on the bottom right of the image.
226	GX-B1603/22-F-250325~250331	2025.9.29	所检项目合格	 Two people are operating a large industrial machine with a digital display. One person is pointing at the screen while the other stands behind. The date 2025.9.25 is overlaid on the bottom right of the image.

227	GX-B1603/22-F-250322~250324	2025.9.29	所检项目合格	
228	GX-B1593/21-F-25437	2025.9.28	所检项目合格	

229	GX-B1568/22-F-25577~25582	2025.9.30	本次共检验矿用风速表6台，6台所检项目合格。	 A woman in a white lab coat is seated at a desk in a laboratory, working on a computer. The desk has a monitor displaying a graph. In the background, there are large blue industrial machines. A date stamp '2025.9.23' is visible in the bottom right corner of the photo.
230	GX-B1409/22-F-25112	2025.9.29	所检项目合格	 Two men in lab coats are standing at a desk in a laboratory. One man is wearing a light blue lab coat and the other is wearing a grey lab coat with '中检公值' (Zhongjian Gongzhi) on the back. They are working with a computer and some equipment on the desk. A date stamp '2025.9.23' is visible in the bottom right corner of the photo.

231	GX-B1601/22-F-250865~250868	2025.9.29	所检项目合格	
232	GX-B1372/22-F-250722~250727	2025.9.29	所检项目合格	

233	GX-B1372/22-F-250728~250737	2025.9.29	所检项目合格	 2025.9.6
234	GX-B1373/21-F-25462~25472	2025.9.29	所检项目合格	 2025.8.31

235	GX-B1466/22-F-25091~25092	2025.9.29	所检项目合格	
236	GX-B1372/22-F-250717~250721	2025.9.29	所检项目合格	

237	GX-B1374/22-F-250871~250875	2025.9.28	所检项目合格	
238	GX-B1465/22-F-25134~25136	2025.9.30	所检项目合格	

239	GX-B1475/22-F-25421~25425	2025.9.29	所检项目合格	
-----	---------------------------	-----------	--------	---