


序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-5-25202	2025. 10. 9	本次共检绝缘手套10只，10只绝缘手套合格。	
2	GX-B1428/21-5-25203	2025. 10. 9	本次共检绝缘靴10只，10只绝缘靴合格。	

3	GX-B1323/21-5-25138~25140	2025/10/10	所检项目合格。	 2025/9/21
4	GX-B1321/20-5-25808~25813	2025/10/10	本次共检电力电缆6条，6条电力电缆所检项目合格。	 2025/9/19

5	GX-B1321/20-5-25814~25818	2025/10/10	本次共检电力电缆 5条，5条电力电缆所 检项目合格。	 A black and white photograph showing a worker in a dark environment, likely a tunnel or underground facility, inspecting a series of power cables. The worker is wearing a hard hat and reflective safety gear. The cables are bundled together and run along a wall. A timestamp '2025/9/21' is visible in the bottom right corner of the image.
6	GX-B1312/20-5-25741~25742	2025. 10. 11	所检项目合格	 A black and white photograph showing a worker in a light-colored uniform and a hard hat with a headlamp, inspecting a large, circular industrial component, possibly a valve or a large pipe. The worker is standing next to the component. A timestamp '2025. 9. 19' is visible in the bottom right corner of the image.

7	GX-B1312/20-5-25743~25746	2025. 10. 11	所检项目合格	
8	GX-B1312/20-5-25747~25754	2025. 10. 11	所检项目合格	

9	GX-B1312/20-5-25755~25756	2025. 10. 11	所检项目合格	
10	GX-B1323/21-5-25141~25143	2025. 10. 11	所检项目合格	

11	GX-B1321/20-5-25829~25837	2025. 10. 13	所检项目合格	
12	GX-B1321/20-5-25838~25852	2025. 10. 13	所检项目合格	